

FINAL DRAFT
PRELIMINARY ASSESSMENT
SERVOMETER CORPORATION
CEDAR GROVE, NEW JERSEY

# FIELD INVESTIGATION TEAM ACTIVITIES AT UNCONTROLLED HAZARDOUS SUBSTANCES FACILITIES — ZONE I

NUS CORPORATION SUPERFUND DIVISION

# FINAL DRAFT PRELIMINARY ASSESSMENT SERVOMETER CORPORATION CEDAR GROVE, NEW JERSEY

#### PREPARED UNDER

## TECHNICAL DIRECTIVE DOCUMENT NO. 02-8904-65 CONTRACT NO. 68-01-7346

**FOR THE** 

ENVIRONMENTAL SERVICES DIVISION
U.S. ENVIRONMENTAL PROTECTION AGENCY

**JUNE 23, 1989** 

NUS CORPORATION SUPERFUND DIVISION

SUBMITTED BY:

JOANN L. WAGNER PROJECT MANAGER

PHILIP J. SOLINSKI

SITE MANAGER

**REVIEWED/APPROVED BY:** 

RONALD M. NAMAN

FIT OFFICE MANAGER

#### POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

#### PART I: SITE INFORMATION

1.	Site Name/Alias	Servometer Corpo	oration			
	Street 501 Little	Falls Road				
	City Cedar Grov	/e		State <u>New Jers</u>	sey	Zip <u>07009</u>
2.	County Essex			County Code _13	3	Cong. Dist. 11
3	EPA ID No. NJD	0002138543				
4.	Latitude 40° 52	.' 10" <u>N</u> .	!	Longitude <u>074°</u>	13′ 26" V	<i>I</i>
	USGS Quad. Or	ange, New Jersey				
5.	Owner <u>Servon</u>	neter Corporation		Tel. No. <u>(201)</u> 7	85-4630	_
	Street 501 Littl	e Falls Road				
	City Cedar Grov	ve		State <u>New Jersey</u>	<u>/</u>	Zip <u>07009</u>
6.	Operator <u>Serve</u>	ometer Corporation		Tel. No. <u>(201)</u> 78	35-4630	_
	Street 501 Littl	e Falls Road				
	City Cedar Gro	ve		State <u>New Jerse</u>	ey	Zip <u>07009</u>
7.	Type of Owners	ship				
		☐ Federal	☐ State			
	☐ County	☐ Municipal	Unkno	own	☐ Other	
8.	Owner/Operato	or Notification on Fi	le			
	<b>⊠ RCRA 3001</b>	Date <u>8/14</u>	i/80	CERCLA 103c	Date	!
	☐ None	☐ Unkno	wn			
9.	Permit Informa	tion				
	Permit	Permit No.	Date Issued	Expiration	n Date	Comments
	RCRA Part A	NJD002138543	10/81			TSD Status ter- minated 12/88
	NJPDES	NJ0027847	10/9/84	11/30/89		Modified in 1987 to include monitoring for discharges to groundwater

	Site Status								
	★ Active		□Inactive	☐ Unknow		wn			
11.	Year	s of Opera	ition	1974	to	Present		_	
12.	abov	e- or belo e unit nur	w-gro nbers	ound tanks or c as needed to id	ontainers	, land treatm	ient, etc.) o	nent, piles, stained so on site. Initiate as mar	
	(a) Waste Management Areas								
	Wast	e Unit No		Waste Unit Type Facility			Facility Na	Name for Unit	
	<ul> <li>6,000-Gallon Above</li> <li>Waste Tank</li> <li>Solvent Vapor Degr</li> </ul>			)-Gallon Under	Gallon Aboveground Storage Tank Caustic V		Waste Storage Tank		
				)-Gallon Above			Caustic \	c Waste Storage Tank	
				e Tank			Batch Treatment Tank		_
				nt Vapor Degreaser		1,1,1-Trichloroethane Unit		_	
				ewater Treatm	Treatment Facility		Wastewater Treatment Facility		_
				<u>Dru</u>		Drum St	n Storage Area		
	(b)	Other A	reas o	f Concern					
	Identify any miscellaneous spills, dumping, etc. on site; describe the materials and identify their locations on site.								
		tify any n			dumping,	etc. on site;	describe th	ne materials and identi	ify
	their	tify any n locations	on sit	e.				ne materials and identi	
	their Ther	tify any n locations e are no k	on sit	e.	ills on site				
	their Ther	tify any n locations e are no k	on sit	e. or reported sp	ills on site				
13.	Ther	tify any n locations e are no k	on sit	e. or reported sp aste treatment	ills on site				
13.	Ther be po	tify any n locations e are no k umped to	on sit	e. or reported sp aste treatment	ills on site area.				- uld

For each of the waste units identified in Part I, complete the following six item
---

Waste Unit 1 - 6,000-Gallon Underground Storage Tank Caustic Waste Storage Tank

1. Identify the RCRA status and permit history, if applicable, and the age of the waste unit.

Servometer Corporation has been a RCRA facility since 1980. The company was originally identified as a hazardous waste treatment, storage, or disposal (TSD) facility, but in December 1988 its TSD status was terminated. Since 1984, Servometer has been permitted to discharge to surface water under the New Jersey Pollutant Discharge Elimination System (NJPDES). In 1987 that permit was modified to include monitoring for any past and/or potential discharges to groundwater. The carbon steel underground storage tank was utilized from the fall of 1974 to the spring of 1987. The tank was removed, and soil sampling was performed on December 7, 1988.

2. Describe the location of the waste unit and identify clearly on the site map.

The tank was located on the north side of the building to the rear of the building.

3. Identify the size or quantity of the waste unit (e.g., area or volume of a landfill or surface impoundment, number and capacity of drums or tanks). Specify the quantity of hazardous substances in the waste unit.

The tank had a maximum capacity of 6,000 gallons.

4. Identify the physical state(s) of the waste type(s) as disposed of in the waste unit. The physical state(s) should be categorized as follows: solid, powder or fines, sludge, slurry, liquid, or gas.

The physical state of the waste was liquid.

5. Identify specific hazardous substance(s) known or suspected to be present in the waste unit.

Caustic waste from dissolution of aluminum from nickel parts was stored in the tank.

6. Describe the containment of the waste unit as it relates to contaminant migration via groundwater, surface water, and air.

The underground tank rested on a concrete slab. Upon the tank's removal, soil sampling was performed. All of the samples showed no contamination. Only one sample showed a high pH.

For each of the waste units identified in Part I	, complete the following six items
--	------------------------------------

Waste Unit 2 - 6,000-Gallon Aboveground Storage Tank Caustic Waste Storage Tank

1. Identify the RCRA status and permit history, if applicable, and the age of the waste unit.

Servometer Corporation has been a RCRA facility since 1980. The company was originally identified as a hazardous waste teatment, storage, or disposal (TSD) facility, but in December 1988 its TSD status was terminated. Since 1984, Servometer has been permitted to discharge to surface water under the NJPDES. In 1987 that permit was modified to include monitoring for any past and/or potential discharges to groundwater. The fiberglass aboveground storage tank has been in operation since spring 1987.

2. Describe the location of the waste unit and identify clearly on the site map.

The tank is located on the south side of the building to the rear.

3. Identify the size or quantity of the waste unit (e.g., area or volume of a landfill or surface impoundment, number and capacity of drums or tanks). Specify the quantity of hazardous substances in the waste unit.

The tank has a maximum capacity of 6,000 gallons.

4. Identify the physical state(s) of the waste type(s) as disposed of in the waste unit. The physical state(s) should be categorized as follows: solid, powder or fines, sludge, slurry, liquid, or gas.

The physical state of the waste is liquid.

5. Identify specific hazardous substance(s) known or suspected to be present in the waste unit.

Caustic waste from dissolution of aluminum from nickel parts is known to be stored in the tank for less than 90 days.

6. Describe the containment of the waste unit as it relates to contaminant migration via groundwater, surface water, and air.

The waste is in a closed container surrounded by a secondary containment system. The New Jersey Department of Environmental Protection (NJDEP) requirements for the secondary containment system include a capacity of 6,00° gallons, and an 8-inch-thick reinforced concrete pad with a permeability rating not greater than 10° cm/sec.

Ref. Nos. 14, 22, 23, 24, 27, 28

Ref. Nos. 14, 21, 22, 23, 24, 27, 28

For ea	ich of th	ne waste u	ınits identified in Part	I, complete the foll	owing six items.	
Waste	e Unit	_3	Waste Tank	Batch Trea	atment Tank	
1.	Identif	y the RCR	A status and permit h	istory, if applicable,	, and the age of the w	aste unit.
	Servon	neter has l	peen a RCRA facility si	nce 1980. The comp	oany began its operati	ons in 1974.
2.	Descril	be the loca	ation of the waste uni	t and identify clear	ly on the site map.	
			nent storage tank is lo rner of the building.	cated near the wast	tewater treatment fac	ility, which is in
3.	impou	ndment, i			ea or volume of a lar . Specify the quantit	
	The ca	pacity of t	the waste tank is 330 g	gallons.		
4.	physic				lisposed of in the wallid, powder or fines,	
	The ph	nysical stat	e of the waste is liquid	d.		
5.	Identif	fy specific	hazardous substance	(s) known or suspec	cted to be present in t	he waste unit.
	miscel		oills and leakage from		olved aluminum an ment. These spills cou	•
6.			ontainment of the warface water, and air.	aste unit as it rela	ates to contaminant	: migration via
			s within the building. nent tank in the waste		floor drains and are t ea.	:hen pumped to

PART II: WASTE SOURCE INFORMATION	PART II:	WASTE	SOURCE	INFORM	ATION
-----------------------------------	----------	-------	--------	--------	-------

Was	te Unit4_	- Solvent Vapor Degreaser	1,1,1-Trichloroethane Unit
1.	-	•	f applicable, and the age of the waste unit.  been a RCRA facility since 1980.
2.	Describe the lo	ocation of the waste unit and id	entify clearly on the site map.
	The unit is loca	ated within the cleaning room i	n the middle of the building.
3.	impoundment		nit (e.g., area or volume of a landfill or surface ns or tanks). Specify the quantity of hazardous
	The unit holds	275 gallons of solvent.	
4.		e(s) should be categorized as f	type(s) as disposed of in the waste unit. The ollows: solid, powder or fines, sludge, slurry
	The physical s	tates of the wastes are liquid an	d sludge.
5.	Identify speci	fic hazardous substance(s) knov	vn or suspected to be present in the waste unit.
	The solvent 1,	1,1-trichloroethane and associa	ted still bottoms are known to be present.
6.		containment of the waste un surface water, and air.	it as it relates to contaminant migration via
			olvent is recycled in a closed loop within the unit n 90 days of generation. Migration is unlikely.
D -1	No. 44.24	22, 27, 20	
Ref.	Nos. 14, 21,	22, 27, 28	

Waste Unit 5 - Wastewater Treatment Facility Wastewater Treatment Facility

Identify the RCRA status and permit history, if applicable, and the age of the waste unit.

Servometer began operations in 1974 and has been a RCRA facility since 1980. The company was originally identified as a hazardous waste treatment, storage, or disposal (TSD) facility, but in December 1988 its TSD status was terminated. Since 1984, Servometer has been permitted to discharge to surface water under the NJPDES.

2. Describe the location of the waste unit and identify clearly on the site map.

The treatment facility is located in the southeast corner of the building.

3. Identify the size or quantity of the waste unit (e.g., area or volume of a landfill or surface impoundment, number and capacity of drums or tanks). Specify the quantity of hazardous substances in the waste unit.

The waste treatment facility treats 12,000 gallons per day and releases the effluent under state permit to the Peckman River. A tank for the storage of sludge resulting from the waste treatment process has a capacity of approximately 1,500 gallons.

4. Identify the physical state(s) of the waste type(s) as disposed of in the waste unit. The physical state(s) should be categorized as follows: solid, powder or fines, sludge, slurry, liquid, or gas.

The physical states of the wastes are liquid and sludge.

5. Identify specific hazardous substance(s) known or suspected to be present in the waste unit.

Process waters from the nickel rinse, cyanide rinse, chrome rinse, sodium hydroxide rinse, and floor spillage are known to be treated. The sludge resulting from the waste treatment process is removed from the site within 90 days of its generation.

6. Describe the containment of the waste unit as it relates to contaminant migration via groundwater, surface water, and air.

All liquid wastes are treated before release into the Peckman River.

Ref. Nos.	14 21	, 22, 23,	27 28	<u> </u>
1101.1103.	17,21	,, _,,	2,,20	/

For e	ach of the waste	uni	ts identified in Part I, complet	e the following six items.
Wast	e Unit <u>6</u> -	<u>.</u>	Drum Storage Area	Drum Storage Area
1.			status and permit history, if a operations in 1974 and has be	pplicable, and the age of the waste unit. een a RCRA facility since 1980.
2.	Describe the lo	cat	on of the waste unit and iden	tify clearly on the site map.
			map included in the facility's along the south wall in the pl	1980 hazardous waste permit application, the ating department.
3.		, nu	mber and capacity of drums	(e.g., area or volume of a landfill or surface or tanks). Specify the quantity of hazardous
	There are nine	55-	gallon drums shown on the 19	80 site map.
4.				pe(s) as disposed of in the waste unit. The ows: solid, powder or fines, sludge, slurry,
	The physical sta	ate	of the wastes are liquid.	
5.	Identify specifi	ic h	azardous substance(s) known	or suspected to be present in the waste unit.
			1980 submittal, the solvent 1, id stripper waste was stored in	1,1-trichloroethane and waste oil are stored in a the four other drums.
6.			tainment of the waste unit face water, and air.	as it relates to contaminant migration via
	The drums are	loc	ated within the building; then	refore, migration is unlikely.
Ref.	Nos. <u>14, 22, 2</u>	8		

#### PART III: HAZARD ASSESSMENT

#### **GROUNDWATER ROUTE**

1. Describe the likelihood of a release of contaminant(s) to the groundwater as follows: observed, alleged, potential, or none. Identify the contaminant(s) detected or suspected, and provide a rationale for attributing the contaminant(s) to the facility.

There is no potential for a release of contaminants to groundwater because the underground tank was removed. The soil around the tank was tested and found to be uncontaminated. The aboveground storage tank, approved by the NJDEP, has no potential for a release to groundwater, because of its containment system. All other waste units are within the building. All waste is either treated and discharged to surface water or is shipped off site for proper disposal.

Ref. Nos. 14, 21, 25, 26, 29

 Describe the aquifer of concern; include information such as depth, thickness, geologic composition, permeability, overlying strata, confining layers, interconnections, discontinuities, depth to water table, groundwater flow direction.

Rocks of the Brunswick Formation are the main source of groundwater in Essex County. The formation consists predominantly of interbedded brown, reddish-brown, and gray shale, sandy shale, sandstone, and some conglomerate. Between the First and Second Watchung Mountains, the formation is predominantly sandstone. The valley in between the mountains is underlain by stratified drift. The depth of this drift is between 30 and 50 feet; underneath this drift, bedrock is found. The primary pore spaces in consolidated rocks of the Brunswick Formation are so small that an insignificant quantity of water, if any, moves through them under natural hydraulic gradients. However, a joint and fracture system that has developed provides secondary porosity, and it is largely in and through these openings that storage and movement of groundwater take place. The groundwater movement in the Brunswick Formation is to the north-northeast, along the strike of the formation; the Peckman River flows in the same direction. Depth to the water table is between 10 and 20 feet below the surface.

Ref. Nos. 1, 2, 3, 4

3. Is a designated sole source aguifer within 3 miles of the site?

The Brunswick Shale and Sandstone Aquifer is designated as a sole source aquifer in the Ridgewood area of northern New Jersey. However, this area does not fall within the 3-mile radius of the site.

Ref. Nos. 5, 6

4. What is the depth from the lowest point of waste disposal/storage to the highest seasonal level of the saturated zone of the aquifer of concern?

The elevation of the facility is approximately 177 feet. The depth of the underground tank is unknown, but is assumed to be 6 feet below the ground surface. The elevation of the nearby river is approximately 172 feet. Therefore, the depth from the lowest point of waste storage to the highest seasonal level of the saturated zone is assumed to be 0 feet.

Ref. Nos. 3, 4, 7, 13, 21

5. What is the permeability value of the least permeable continuous intervening stratum between the ground surface and the aquifer of concern?

The stratified drift between the ground surface and the water table consists mostly of stratified sand and gravel. The approximate range of hydraulic conductivity is from 10<sup>-5</sup> to 10<sup>-3</sup> cm/sec.

Ref. Nos. 2, 7

6. What is the net annual precipitation for the area?

Approximately 16 inches.

Ref. No. 7

7. Identify uses of groundwater within 3 miles of the site (i.e., private drinking source, municipal source, commercial, industrial, irrigation, unusable).

Groundwater is used for drinking water during peak demands in Montclair and is also used for drinking water by Essex County Hospital Center. Two country clubs within 3 miles of the site use groundwater for recreational and irrigation purposes. The Upper Montclair Country Club also uses groundwater for drinking purposes.

Ref. Nos. 6, 8, 9, 10, 11, 30, 31

8. What is the distance to and depth of the nearest well that is currently used for drinking or irrigation purposes?

Distance 1.7 miles Depth Depth 300 ft

Ref. Nos. 8, 12, 13

9. Identify the population served by the aquifer of concern within a 3-mile radius of the site.

Approximately 42,000.

Ref. Nos. 9, 11

#### SURFACE WATER ROUTE

10. Describe the likelihood of a release of contaminant(s) to surface water as follows: observed, alleged, potential, or none. Identify the contaminant(s) detected or suspected, and provide a rationale for attributing the contaminants to the facility.

The Servometer Corporation is currently permitted to discharge effluent from its wastewater treatment system into the Peckman River under New Jersey Pollutant Discharge Elimination System (NJPDES) permit No. NJ0027847. The system treats various spent process solutions containing dissolved metals (aluminum, nickel, and copper), acids, alkalies, and cyanides.

Ref. No. 14

11. Identify and locate the nearest downslope surface water. If possible, include a description of possible surface drainage patterns from the site.

The Peckman River is located approximately 30 feet from the site boundary to the west. A drainage path extends from the rear of the building for a distance of approximately 210 feet to the river.

Ref. Nos. 4, 14, 27

12. What is the facility slope in percent? (Facility slope is measured from the highest point of deposited hazardous waste to the most downhill point of the waste area or to where contamination is detected.)

The facility slope as defined cannot be calculated, as there were no known wastes deposited on site.

Ref. No. 4

13. What is the slope of the intervening terrain in percent? (Intervening terrain slope is measured from the most downhill point of the waste area to the probable point of entry to surface water.)

The intervening terrain slope is estimated to be less than 3 percent.

Ref. Nos. 4, 13

14. What is the 1-year 24-hour rainfall?

Approximately 2.7 inches.

Ref. No. 7

15. What is the distance to the nearest downslope surface water? Measure the distance along a course that runoff can be expected to follow.

Approximately 210 feet.

Ref. Nos. 4, 27

16. Identify uses of surface waters within 3 miles downstream of the site (i.e., drinking, irrigation, recreation, commercial, industrial, not used).

Surface water downstream is used for hydroelectric power generation and possibly some recreational fishing.

Ref. No. 15

17. Describe any wetlands, greater than 5 acres in area, within 2 miles downstream of the site. Include whether it is a freshwater or coastal wetland.

There are no wetlands downstream of the site.

Ref. Nos. 13, 15, 16

18. Describe any critical habitats of federally listed endangered species within 2 miles of the site along the migration path.

There are no critical habitats of federally listed endangered species within 2 miles of the site.

Ref. Nos. 16, 17

19. What is the distance to the nearest sensitive environment along or contiguous to the migration path (if any exist within 2 miles)?

There are no sensitive environments within 2 miles of the site.

Ref. Nos. 13, 16, 17

20. Identify the population served or acres of food crops irrigated by surface water intakes within 3 miles downstream of the site and the distance to the intake(s).

There are no surface water intakes 3 miles downstream of the site.

Ref. Nos. 13, 15, 18

21. What is the state water quality classification of the water body of concern?

The Peckman River is classified as FW2-nontrout.

Ref. No. 19

22. Describe any apparent biota contamination that is attributable to the site.

There is no apparent biota contamination that is attributable to the site.

Ref. Nos. 4, 14

#### AIR ROUTE

23. Describe the likelihood of a release of contaminant(s) to the air as follows: observed, alleged, potential, none. Identify the contaminant(s) detected or suspected, and provide a rationale for attributing the contaminant(s) to the facility.

The potential for a release of contaminants to the air exists because chlorine and cyanide are used in one of the processes on site. This process results in the production of hydrogen cyanide and/or cyanogen chloride gases under improper pH conditions.

Ref. No. 14

24. What is the population within a 4-mile radius of the site?

Approximately 206,400 people.

Ref. No. 20

#### FIRE AND EXPLOSION

25. Describe the potential for a fire or explosion to occur with respect to the hazardous substance(s) known or suspected to be present on site. Identify the hazardous substance(s) and the method of storage or containment associated with each.

There is a potential for fire or explosion on site. If some of the chemicals used or wastes generated on site were mixed with each other, there is a potential for a violent reaction.

Ref. Nos. 7, 14

26. What is the population within a 2-mile radius of the hazardous substance(s) at the facility?

Approximately 37,400 people.

Ref. No. 20

#### **DIRECT CONTACT/ON-SITE EXPOSURE**

27. Describe the potential for direct contact with hazardous substance(s) stored in any of the waste units on site or deposited in on-site soils. Identify the hazardous substance(s) and the accessibility of the waste unit.

Workers on site may be exposed to hazardous substances due to the nature of the processes involved. The waste tank may be accessible to the public, as there is no fence to keep people away. The potential for contact by the public with hazardous substances inside the building is minimal because of a security system.

Ref. Nos. 4, 14

28. How many residents live on a property whose boundaries encompass any part of an area contaminated by the site?

There are no known areas of contaminaton attributable to the site and no residential properties immediately adjacent to the site.

Ref. No. 4

29. What is the population within a 1-mile radius of the site?

Approximately 10,200 people.

Ref. No. 20

#### PART IV: SITE SUMMARY AND RECOMMENDATIONS

Servometer Corporation, located in Cedar Grove, Essex County, New Jersey, is an active facility which began its operations in 1974. The company is privately owned and is located in a mixed residential and industrial area. The 8-acre site is in close proximity to the Peckman River.

The Servometer Corporation manufactures miniature metal bellows, bellows assemblies, couplings, and contacts for the aerospace and control valve industries. The manufacturing operation involves the electrodeposition (electroforming) of copper and nickel onto aluminum mandrels. Once the desired thickness is obtained, the aluminum mandrels are dissolved using a caustic solution.

Servometer operates a wastewater treatment system on site which treats various spent process solutions containing dissolved metals, acids, alkalies, and cyanides. The system also treats rinse waters that flow continuously while the plant is operating. These rinse waters represent a more voluminous but less concentrated source of wastes as compared to the process solutions. The effluent from the treatment system is discharged to the Peckman River under New Jersey Pollutant Discharge Elimination System (NJPDES) permit No. NJ0027847.

The Servometer Corporation was classified as a hazardous waste treatment, storage, or disposal (TSD) facility, EPA I.D. No. NJD002138543, from 1980 to December 1988. Currently, the company is listed only as a generator. Hazardous wastes generated by the facility include caustic waste, waste acid, still bottoms from a solvent (1,1,1-trichloroethane) recovery unit, wastewater treatment sludge, and waste metal working oils. All hazardous wastes are removed from the site within 90 days of generation.

From 1974 to spring 1987, the caustic waste was stored in a 6,000-gallon underground storage tank. Four wells were installed in early 1988 to monitor for any past and/or potential discharges to groundwater. The tank was removed in December 1988. Four soil samples collected from the area of the tank showed no contamination. Only one soil sample had an elevated pH. Since spring 1987, Servometer has been using a 6,000-gallon aboveground tank for the storage of caustic waste.


Servometer Corporation has complied with all New Jersey Department of Environmental Protection (NJDEP) requests. There have been no reported spills or violations. As a result of an October 1988 NJDEP inspection, the company was given an acceptable rating. Therefore, a recommendation of **NO FURTHER REMEDIAL ACTION PLANNED (NFRAP)** is being made.

ATTACHMENT 1

## SERVOMETER CORPORATION CEDAR GROVE, NEW JERSEY

#### CONTENTS


Figure 1: Site Location Map Figure 2: Site Map Exhibit A: Photograph Log



SITE LOCATION MAP
SERVOMETER CORPORATION,
CEDAR GROVE, N.J.

SCALE : 1"= 2000"





SERVOMETER CORPORATION, CEDAR GROVE, N.J.

(NOT TO SCALE)



02-8904-65-PA Rev. No. 0

#### EXHIBIT A

#### PHOTOGRAPH LOG

SERVOMETER CORPORATION CEDAR GROVE, NEW JERSEY

OFF-SITE RECONNAISSANCE: MAY 9, 1989

#### SERVOMETER CORPORATION CEDAR GROVE, NEW JERSEY MAY 9, 1989

#### PHOTOGRAPH INDEX

Photo Number	<u>Description</u>	Time
1P-3	Photo looking southeast at site.	1430
1P-4	Photo looking east at drainage pathway.	1431
1P-5	Photo looking south at Peckman River.	1438
	All photographs by P. Solinski.	



02-8904-65-PA Rev. No. 0

### SERVOMETER CORPORATION CEDAR GROVE, NEW JERSEY




1P-3 May 9. 1989 Photo looking southeast at site. 1430



-4 May 9, 1989 Photo looking east at drainage pathway.

02-8904-65-PA Rev. No. 0

SERVOMETER CORPORATION CEDAR GROVE, NEW JERSEY



1P-5 May 9, 1989 Photo looking south at Peckman River.

ATTACHMENT 2

#### REFERENCES

- 1. New Jersey Department of Conservation and Economic Development, Geologic Map of New Jersey, Atlas Sheet No. 40, 1950.
- Nichols, William D. Ground-Water Resources of Essex County, New Jersey. Special Report No. 28. State of New Jersey Department of Conservation and Economic Development, Division of Water Policy and Supply, 1968.
- 3. Carswell, L.D. and Rooney, J.G. Summary of Geology and Ground-Water Resources of Passaic County, New Jersey. U.S. Geological Survey, Water-Resource Investigations 76-75, June 1976.
- 4. Preliminary Assessment Off-Site Reconnaissance Information Reporting Form, Servometer Corporation, TDD No. 02-8904-65, NUS Corp. Region 2 FIT. May 9, 1989.
- 5. Federal Register, Vol. 49, No. 16, Tuesday, January 24, 1984, p. 2944.
- 6. Telecon Note: Conversation between W. Kowalski, Township of Cedar Grove Engineering Office, and P. Solinski, NUS Corporation, May 10, 1989.
- 7. Uncontrolled hazardous waste site ranking system, A user's manual, 40 CFR, Part 300, Appendix A, 1986.
- 8. N.J. Department of Environmental Protection, Division of Water Resources, Bureau of Water Allocation, Water Withdrawal Points and NJGS Case Index Sites within 5.0 miles of Latitude 404858 and Longitude 741127, June 25, 1988.
- 9. Project Note: From Stanley B. Shulfer, NUS Corporation, regarding Town of Montclair Water Wells. July 6, 1988.
- 10. Telecon Note: Conversation between Kevin Ryan, Montclair Water Bureau, and Stanley B Shulfer, NUS Corporation, June 30, 1988.
- 11. Telecon Note: Conversation between Henry Bogdanski, Essex County Hospital Center, and Stanley B. Shulfer, NUS Corporation, July 13, 1988.
- 12. Michna, Vlado. Staff Report, In the matter of Town of Montclair, Application No. 5245 to renew permit to divert water from three wells in the Town of Montclair, Essex County, N.J. Department of Environmental Protection, Water Allocation Office.
- 13. Three-Mile Vicinity Map, based on U.S. Department of Interior, Geological Survey Topographic Maps, 7.5 minute series, "Orange Quadrangle, N.J.", "Pompton Plains Quadrangle, N.J.", "Paterson Quadrangle, N.J." (all 1955, revised 1981), "Caldwell Quadrangle, N.J.", 1954, revised 1981.
- 14. Lancy Laboratories Division, Lancy International, Inc. Emergency Plan and Preparedness, Prevention and Contingency Plan for Servometer Corporation, May 1984.
- 15. Telecon Note: Conversation between Mr Deblock, West Paterson Water Pollution Control, and P. Solinski, NUS Corporation, May 10, 1989


#### REFERENCES (CONT'D)

- 16. U.S. Department of Interior, U.S. Fish and Wildlife Service, Atlantic Coast Ecological Inventory, Newark, N.J. N.Y. PA, 1980.
- 17. New York State Department of Environmental Conservation, Significant Habitat Overlay, Newark Quadrangle, March 1981, revised April 1987.
- 18. State of New Jersey, Department of Environmental Protection, Water Supply Overlay Sheet No. 26, August 1975.
- 19. New Jersey Department of Environmental Protection (NJDEP), Surface Water Quality Standards, N.J.A.C. 7:9-4 and N.J.A.C. 7:9-4.1 et. seq., May 1985.
- 20. General Software Corporation, Graphical Exposure Modeling System (GEMS). Landover, Maryland, 1986.
- 21. Letter from Robert Berg, Chief, Bureau of Ground Water Quality Management, NJDEP, to Peter Holowachuk, Servometer Corporation, August 20, 1987. Re: Response to Comments and Issuance of Final NJPDES Permit.
- 22. U.S. EPA, Notification of Hazardous Waste Activity, EPA Form 8700-12 (6-80), Servometer Corporation, EPA I.D. Number NJD002138543, August 12, 1980.
- 23. Letter from Ernest J. Kuhlwein, Chief, Bureau of Hazardous Waste Engineering, NJDEP, to Peter J. Holowachuk, Servometer Corporation, December 9, 1988.
- 24. Letter from Frank Coolick, Acting Assistant Director, Hazardous Waste Regulation Element, NJDEP, to Peter Holowachuk, Servometer Corporation, March 26, 1987.
- 25. NJDEP, Division of Waste Management, Inspection Report on Servometer Corporation, October 31, 1988.
- 26. Quazza and Associates, Inc., Closure Observation of Servometer Corporation Underground Storage Tank, August 5, 1988.
- 27. U.S. EPA, General Information, EPA Form 3510-1(6-80), Servometer Corporation, EPA I.D. Number NJD002138543, October 31, 1980.
- 28. U.S. EPA, Hazardous Waste Permit Application, EPA Form 3510-3 (6-80), Servometer Corporation, EPA I.D. Number NJD002138543, October 27, 1980.
- 29. Letter from Stefan D. Sidlak, Section Chief, Metro Bureau of Regional Enforcement, NJDEP, to Peter Holowachuk, Servometer Corporation, November 18, 1988.
- 30. Telecon Note: Conversation between Greenskeeper, Glen Ridge Country Club, and S. Shulfer, NUS Corporation, June 30, 1988
- 31. Telecon Note: Conversation between R. Dickerson, Upper Montclair Country Club, and S. Shulfer, NUS Corporation, July 20, 1988.

#### REFERENCE NO. 1

#### STATE OF NEW JERSEY DEPARTMENT OF CONVERVATION AND ECONOMIC DEVELOPMENT

#### ATLAS SHEET No. 40



COASON'S INL

# GEOLOGIC MAP

OF

# NEW JERSEY

Compiled from published folios and from manuscript data in possession of the Survey, the latter chiefly the field work of

W. S. BAYLEY, (Pre-Cambr in)

H. B. KÜMMEL, (Paleozoic, "riassic, Quaternary)

R. D. SALISBURY, (Quatern cry)

G. N. KNAPP, (Cretaceous, 7 rtiary, Quaternary)

BY

# J. VOLNEY LEWIS AND HENRY B. KÜMMEL 1910-1; 12

REVISED BY H. B. KI MMEL, 1931 AND MEREDITH E. J. HNSON, 1950


SCALE: 1:250,000 (approximately 4 miles to an inch)



Section A-A.-Diugman's Ferry to Hoboken. Scales: Horizontal,  $\frac{1}{250000}$ ; Vertical,  $\frac{1}{100000}$ ; Vertical exaggeration 2%.

Hard cherty limestone and limy shale (New Scotland) overlying light-gray limestone (Cocymans) and separated southward by a thin sandy bed (Stormwille), (Northwestern area).

Bangor



#### REFERENCE NO. 2

### GROUND-WATER RESOURCES OF ESSEX COUNTY, NEW JERSEY

 $\mathbf{B}\mathbf{y}$ 

WILLIAM D. NICHOLS

Hydrologist, U. S. Geological Survey

SPECIAL REPORT NO. 28

1968

Prepared by the U. S. Geological Survey
in Cooperation with the
State of New Jersey

#### By WILLIAM D. NICHOLS

#### **ABSTRACT**

Ground water in Essex County occurs in joints and fractures in consolidated rocks and in the voids of unconsolidated statified drift deposits. Wells in sandstone and shale of the Brunswick Formation of Triassic age yield from 35 to 820 gpm; the most productive water-bearing zones are commonly between depths of 300 to 400 feet. Drawdown due to pumping is greatest in the direction of strike of the formation (about N 30' E in Essex County) and least in the direction perpendicular to strike. Wells in the Watchung basalt, which is intercalated with rocks of the Brunswick Formation commonly yield small to moderate supplies but may occasionally yield up to 400 gpm. Large yields, ranging from 410 to 1,593 gpm, are common from wells tapping the stratified drift deposits in the western part of the county.

Quality of ground water is acceptable for most uses throughout the county. However, heavy pumpage in the Newark area has lowered water levels to more than 100 feet below sea level. The low water levels have reversed the natural gradient and induced the flow of salt water into the bedrock aquifer, seriously impairing ground-water quality there. Recent analyses of ground-water samples from Newark indicate that the chloride concentration in the aquifer has increased since the preliminary study of the problem by Herpers and Barksdale in 1951.

Highly productive stratified drift deposits are found primarily in that part of the county west of Second Watchung Mountain. They occur as valley-fill material in stream valleys cut into the underlying bedrock before the last glaciation. These deposits in Essex County are part of an extensive valley-fill aquifer system underlying the eastern Morris-western Essex County area. Water levels in these deposits in western Millburn Township have declined 36 feet since 1950, probably as a result of below normal rainfall for most of the period 1953 to 1966 together with constantly increasing pumpage throughout the area.

Withdrawals of ground water from all aquifers in Essex County for public supply averaged about 26 mgd (million gallons per day) in 1966. Pumpage for public supply from aquifers in unconsolidated sediments averaged 20.9 mgd, about 81 percent of the total from all aquifers.

Most of the productive aquifers in Essex County are currently being developed. Although the optimum potential of the stratified drift aquifers

in western Essex County and the Brunswick Formation in the northeastern part of the county probably has not been realized, development of these resources must be undertaken with care if anticipated increase in water needs of the county are to be met.

#### INTRODUCTION

#### PURPOSE AND SCOPE

This study was made as part of a statewide program of investigation of the ground-water resources of New Jersey, authorized by the New Jersey Water Supply Act of 1958 and its companion, Water Bond Act. The purpose and scope of these studies are to assemble the available data on geologic and hydrologic factors relating to the occurrence, movement, availability, and chemical quality of ground water in New Jersey; to evaluate and interpret the data; and to make the results of the investigation available to the public. This report represents the results of the ground-water investigation of Essex County made by the U. S. Geological Survey in cooperation with the New Jersey State Department of Conservation and Economic Development, Division of Water Policy and Supply. The work was under the general supervision of Allen Sinnott, formerly District Geologist.

#### LOCATION AND EXTENT OF AREA

Essex County is located in northeastern New Jersey between longitudes 74°05′W and 74°25′W, and latitudes 40°40′N and 40°55′N. It is bounded on the north by Passaic County; on the east by Bergen County, Hudson County, and Newark Bay; on the south by Union County and on the west by Morris County (fig. 1). The county is 127.44 square miles in area. Newark is the county seat. Other major communities include Orange, East Orange, South Orange, West Orange, Irvington, Belleville, Nutley, Montclair, and Bloomfield.

#### PREVIOUS INVESTIGATIONS

The geology of Essex County is described in detail by Darton and others (1908) in the Passaic folio. Salisbury (1894) discussed the surficial geology of the county as part of a regional investigation. Rogers and others (1951) described the engineering characteristics of the soils and glacial deposits in the county. Ground-water conditions in the extreme southwestern part of the county were described by Thompson (1932). Herpers and Barksdale (1951) discussed ground-water conditions in the Newark area.

#### ACKNOWLEDGMENTS

The author wishes to thank the numerous well drillers, State, municipal, and industrial officials and private individuals who supplied data on which this report is based. Acknowledgment is made for the records and logs of wells that were furnished from the files of the New Jersey Bureau of Geology and Topography. The cooperation of those who permitted use of their wells for water-level observation, collection of water samples, and pumping tests is gratefully acknowledged. Most of the well inventory for this report was made by the late O. J. Coskery of the U. S. Geological Survey.




Figure 1.—Map of New Jersey showing the location of Essex County.

#### **GEOGRAPHY**

#### TOPOGRAPHY

Essex County is situated entirely on the Triassic lowlands of the Piedmont Province, one of six physiographic provinces included in the Appalachian Highland physiographic division. The province consists primarily of lowland and gently rolling hills above which rise the ridges of the Watchung Mountains. Altitudes in Essex County range from sea level in the southeastern part of the county to 650 feet along the ridges of the Watchung Mountains. The escarpment of the First Watchung Mountain, trending from northeast to southwest across the middle part of the county, rises 400 feet above the gently rolling plain to the east; the breadth of the First and Second Watchung Mountains varies from 1 to 2 miles. The major streams draining Essex county are the Passaic, Rahway, and Elizabeth Rivers.

#### CLIMATE

The climate of Essex County, like that of much of New Jersey, is mainly continental because of the predominance of winds from the continental interior. The prevailing wind is from the northwest from October to April and from the southwest for the remaining months. As a consequence, winter weather is controlled by cold continental air masses and summer by tropical air masses. Precipitation in the county averages more than 48 inches annually, and is commonly well distributed throughout the year. Part of the precipitation is received from storms which cross the Great Lakes region and pass down the St. Lawrence Valley. However, the heaviest general rains are produced by coastal storms of tropical origin. The centers of these storms usually pass some distance offshore, with rainfall heaviest and winds strongest near their center (U. S. Department of Agriculture, page 1010, 1941). The average January temperature for the eastern part of the county is 39°F and that of the western part of the county about 28°F. Average temperatures in July range from about 74°F in the eastern part of the county to about 72°F in the western part of the county.

#### POPULATION AND ECONOMY

Compared with the other counties in New Jersey, Essex County ranks only nineteenth in area, but ranks first in population as of the 1960 census. The population increased from 905 949 in 1950 to 923,545 in 1960—an increase of 1.9 percent; less than in any preceding 10 year period since 1900, except for 1930-40.

000	359,053
	512,886
920	
930	
940	
	905,949
	923,545

Nearly 90 percent of the county's population is located in the 71.5 square miles (55.6 percent of total area) east of the Watchung Mountains.

The economy of Essex County is primarily industrial. The principal manufactured products include food products, electrical goods and machinery, chemicals, machinery (excluding electrical machinery), fabricated metal products, and apparel. In 1960, only about 5 percent of the total land area of the county was utilized as farmland.

#### GEOLOGY

#### INTRODUCTION

The Brunswick Formation and Watchung Basalt of the Newark Group of Late Triassic age underlie all of Essex County. The Brunswick Formation is dominantly shale and sandstone, but also includes minor amounts of conglomerate. The Watchung Basalt consists of three extensive sequences of lava flows intercalated with the shale and sandstone of the Brunswick Formation. The generalized bedrock geologic map (fig. 2) shows the areal extent of the rocks of Triassic age underlying Essex County. Overlying the rocks of the Newark Group are unconsolidated clay, sand, and gravel deposited during the Pleistocene and Recent Epochs. Pleistocene deposits are the most widespread and are found throughout the county. Deposits of Recent age are confined to the present-day stream valleys. Figure 3 shows the general distribution of the unconsolidated Pleistocene deposits.

Parts of Fairfield and Millburn Townships and Newark are underlain by valleys cut (fig. 3) in bedrock by streams that drained the area before the last glaciation. The valley were subsequently filled in and buried by glacial debris and have little present-day surface expression.

# DISTRIBUTION AND LITHOLOGY OF ROCK UNITS Consolidated Rocks

Rocks of the Brunswick Formation, the uppermost unit of the Newark Group, underlie most of Essex County. The formation consists dominantly of interbedded brown, reddish-brown, and gray shale, sandy shale, sandstone, and some conglomerate. Three sheets of gray to black basalt are intercalated with sandstone and shale beds of the Brunswick Formation. The total thickness of the Brunswick Formation is not known, but probably exceeds 6,000 feet (Kümmel 1940, p. 102).

In the southern part of the county east of the Watchung Mountains, the Brunswick Formation is predominantly a soft red shale. These rocks become coarser grained toward the north. In the northern part of the county the rocks are mostly sandstone and some interbedded shale; conglomerate is found in the extreme northern part of the county. This change from soft, easily weathered, shale to more resistant sandstone is reflected in the change of topography from the rather flat low-lying plain with few hills in southern Newark to hills of low relief in the northern part of the county.

Between First and Second Watchung Mountains, the Brunswick Formation is dominantly sandstone. West of Second Watchung Mountain, the formation is covered with thick deposits of unconsolidated sediments

of glacial origin and few outcrops can be found. As indicated from records of wells drilled in this area, the rocks are mainly shale and some interbedded sandstone.

Two prominent ridges, First and Second Watchung Mountains, extend from northeast to southwest across the county (fig. 2). These are the two lowest sequences of basalt flows of the Watchung Basalt. The third, uppermost, sequence of flows is represented by Ricker Hill in Livingston Township. These basalt sheets were formed by lava which was extruded at three different times during the accumulation of the sedimentary rocks of the formation. Each of these sheets is made up of several lava flows. Scoriaceous zones occur at the top of many of the individual flows. In some places, thin beds of shale occur between successive flows. The lower part of the Watchung Basalt, which comprises First Watchung Mountain, is from 600 to 650 feet thick; the Watchung Basalt in Second Watchung Mountain varies from 750 to 900 feet in thickness; the uppermost Watchung Basalt ranges from 225 to 350 feet in thickness (Darton and others, 1908, p. 10).

First and Second Watchung Mountains are parallel, and in places have double-crested ridges reflecting the presence of interbedded sedimentary rocks; the ridges generally rise between 300 and 400 feet above the adjacent country. The trend of the ridges reflect the general strike of the sedimentary rocks of the Brunswick Formation. The beds dip about 10 degrees toward the northwest.

# Pleistocene and Recent Deposits

Unconsolidated sediments deposited by glaciers or by glacial meltwater during the Pleistocene Epoch cover most areas of Essex County. These deposits can be divided roughly into several types. Unstratified drift called till or ground moraine is a heterogeneous mixture of clay, silt, sand, gravel, cobbles, and boulders which was deposited by the ice. Unstratified drift that has accumulated in a ridgelike deposit along the margin of a glacier is called an end moraine. Stratified drift is deposited by glacial meltwater in streams (glaciofluvial deposits) and lakes (glaciolacustrine deposits). Glaciofluvial deposits are generally stratified sand, and sand and gravel, and glaciolacustrine deposits are usually bedded or laminated silt and clay. Figure 3 is a map showing the generalized distribution of the Pleistocene deposits in Essex County.

Streams and rivers draining the Essex County area before the last glaciation cut deep valleys into the Triassic rocks (fig. 3). These valleys were subsequently buried by glacial debris, and the thickness of the glacial deposits is largely controlled by the underlying bedrock topography. The

altitude of the floor of the buried bedrock valley under the Newark area is as much as 280 feet below sea level (fig. 4), and the glacial drift is as much as 300 feet thick. In the southwestern corner of Essex County in Millburn Township, the altitude of the valley floor is 17 feet above sea level and the drift averages 150 feet in thickness. In the northwestern part of the county in Fairfield Township, the floor of the valley is as much as 35 feet below sea level and the drift has a maximum thickness of about 200 feet. In the areas between the valleys, where the bedrock surface is high, the drift ranges from 0 to 70 feet thick.

East of the Watchung Mountains and west of the buried valley under the Newark area, the glacial deposits consist dominantly of till. The valley under the Newark area, however, is filled largely with stratified drift and interbedded lenses of till. In the central and southern part of Newark the main valley (fig. 4) is filled with as much as 200 feet of lacustrine clay and sandy clay, which is overlain by 50 to 100 feet of other stratified or unstratified glacial drift. In the northern part of Newark, where the valley (fig. 4) parallels the Passaic River, the valley contains several deposits of sand and gravel interbedded with clay and till. The sand and gravel ranges from 1 to 19 feet in thickness and is encountered mostly at depths of less than 50 feet and depths of more than 220 feet below land surface.

The present-day valley between First and Second Watchung Mountains is underlain by approximately 100 feet of stratified drift in both Cedar Grove in the north and Millburn Township in the south. These deposits consist mostly of stratified sand and gravel. Their maximum thickness appears to occur under that part of the valley west of the Rahway and Peckman Rivers; east of the rivers, the bedrock surface is shallow (30 to 50 feet below the valley floor), and the unconsolidated deposits are thin. There are not enough data to define the thickness and character of the subsurface glacial deposits in the valley in Verona and most of West Orange.

West of Second Watchung Mountain, the stratigraphy of the glacial deposits is moderately complex, especially in the buried valleys. The drift in the main buried valley in Livingston and Millburn Townships (fig. 3) has a maximum thickness of about 170 feet and consists of interbedded sand, sand and gravel, clay and till. Thicknesses of sand and gravel outwash range from 20 to 80 feet. Farther north, in north-western Fairfield, the main buried valley (fig. 3) is filled with as much as 200 feet of drift consisting almost exclusively of 140 to 170 feet of laminated silt and clay underlain by 10 to 30 feet of till. Deposits of fine- to medium-grained sand ranging in thickness from 0 to 20 feet occur on the surface

28 32/60/6

The tributary buried valleys in Fairfield Township (fig. 3) contain from 30 to 50 feet of silty sand, sand, and gravel overlain by clay and till near the confluence with the main buried valley. Where the bedrock surface is high, between buried valleys, the glacial deposits consist dominantly of till. However, some stratified sand and gravel are found in the subsurface in eastern Roseland and Essex Fells which do not occur as valley-fill deposits.

Unconsolidated sediments of Recent age are confined to areas adjacent to present-day streams. These deposits consist of clay, silt, and fine sand with gravel. (Rogers and others, 1957, p. 7).

#### **GROUND-WATER HYDROLOGY**

#### INTRODUCTION

Ground water is derived from that part of precipitation that does not run off the surface of the land to streams or return to the atmosphere through evaporation and transpiration. Factors which determine the amount of water that infiltrates to the ground-water reservoir include (1) the porosity and permeability of the surficial material, (2) the slope of the land, (3) the amount and kind of natural and artificial cover, and (4) the intensity and amount of precipitation.

The permeability of a rock, or its ability to transmit water, depends on its porosity, that is, on the number and size of the interstices and on the extent to which the interstices are interconnected. The porosity of a rock, in turn, depends largely on: "the shape and arrangement of its constituent particles, the degree of assortment of its particles, the cementation and compacting to which it has been subjected since its deposition, the removal of mineral matter through solution by percolating waters, and the fracturing of the rock, resulting in joints and other openings" (Meinzer, 1923, p. 3). Porosity is expressed quantitatively as the ratio between the volume of void to the total volume of the rock, that is, as the percentage of the total volume of rock occupied by interstices.

On the basis of the type of openings in which ground water may occur, the geologic formations in Essex County may be divided into two groups: (1) consolidated rocks of Triassic age, and (2) unconsolidated sediments of Pleistocene age.

The primary pore spaces in consolidated rocks of the Brunswick Formation in Essex County are commonly so small that an insignificant quantity of water, if any, moves through them under the natural hydraulic gradients or those established by pumping. However, a joint and fracture system that has developed in the consolidated rocks provides secondary porosity and it is largely in and through these openings that the storage and movement of ground water takes place. In addition, vesicles and scoriaceous zones in the basalt add to the porosity in these rocks. Limited interconnected void space occurs in sandstone beds where cementing material is lacking. The volume of all of these openings constitute only a very small percentage of the total volume of the Brunswick Formation and, consequently, their capacity to store and transmit water is limited.

In unconsolidated sediments, water occurs in the pore spaces between the constituent grains. The capacity of unconsolidated sand and gravel deposits to store and transmit water is commonly much greater than that of the consolidated rocks. The reason for this is that the ratio of the volume of void to the total volume of unconsolidated sediment is considerably greater than the ratio of the volume of fracture openings to the total volume of rock. The interstitial openings in clays and silts are so small, however, that they restrict the movement of water, even though the percentage of void space may be great.

# WATER-BEARING PROPERTIES OF MAJOR GEOLOGIC UNITS

#### Consolidated Rocks

Rocks of the Brunswick Formation are the main source of ground water in Essex County. The shales and sandstones are generally capable of sustaining moderate to large yields to wells. The Watchung basalt commonly is capable of yielding only small to moderate quantities of water.

Water in these rocks occurs under both unconfined and confined conditions. Unconfined ground water occurs mainly in the upland areas where overlying unconsolidated deposits are thin or absent. Confined and semiconfined ground water conditions exist in lowland areas in Newark, parts of Fairfield, and along the Passaic River where clay beds in the unconsolidated Quaternary deposits mantle the underlying rocks. Wherever such confinement occurs, water beneath the relatively impermeable confining layers is commonly under artesian pressure. In many areas, such as parts of Fairfield and in the northern part of the county, water in wells tapping the confined aquifers will rise above the top of the aquifer and sometimes near or above land surface. In areas subjected to heavy pumping, such as the Newark area and western Millburn Township, the artesian pressure may be considerably reduced. Parts of the confined aquifer may even become dewatered as has happened in part of Newark, in which case the water remaining in the aquifer is no longer confined.

Confined ground water is also encountered in the shales and sandstone directly beneath the basalt flows in the western part of the county downdip from the outcrop area. Confined or semiconfined ground-water conditions may occur in some areas because of differences in permeability within the rock layers resulting from variations in fracturing or weathering or a combination of both.

Some of the various systems of joints and fractures in the consolidated rocks intersect so that water can move vertically as well as horizontally and zones of high secondary porosity are then interconnected. Most wells tapping these rocks draw water from more than one water-bearing zone. However, these zones in the Brunswick Formation have not yet been accurately defined. They are certainly within the first 600 feet below land surface, and for most practical purposes are probably within the first 400 feet. The best producing wells in the Brunswick Formation in

Essex County are for the most part between 300 and 400 feet deep. Nevertheless, the lack of any precise known boundaries makes it difficult to determine the optimum depth to which a well should be drilled in any given location. Also it is impossible to predict the yield of a proposed well except in very general terms based on the average yield of other wells in the area.

Two pumping tests, both at the same locality, were conducted by the U. S. Geological Survey in January 1949 on wells tapping the Brunswick Formation in Essex County. The wells (owned by P. Ballantine and Sons, Newark), shown on figure 5, were selected to provide the best possible spread of observation wells in as many directions as possible. As the results of the tests have been reported by Herpers and Barksdale (1951, p. 28-31) they will be only summarized here.

In the first test, the centrally located well I-1 was pumped and water levels were observed in the seven surrounding wells indicated on figure 5. Well II-9 was pumped during the second test and the same wells were used to observe water levels. In both tests, observation wells lying along the strike of the Brunswick Formation with respect to the pumping well showed the greatest drawdown. When well I-1 was pumped, there was a prompt and distinct decline of the water level in observation well II-8. When well II-9 was pumped, the water level in observation well II-10 responded promptly and distinctly. No significant response was seen in observation wells aligned in directions other than along the strike during either test.

In these tests, as well as in several others conducted, it is invariably noted that aquifers in the sedimentary rocks of Triassic age of northern New Jersey are anisotropic, that is, they do not transmit water equally in all directions (Vecchioli, 1967). The greatest drawdowns are observed in those wells aligned along the strike of the sedimentary layers with respect to the pumping well. The least amount of drawdown is observed in observation wells that are located transverse to the strike. These observations have been interpreted to indicate that water moves more readily along joints and fractures which strike parallel to the strike of the bedding than along joints and fractures which strike in other directions. It is useful, when planning future well locations, to know the direction in which wells will interfere most with each other and with existing wells. In general, wells should be spaced far apart along the direction of strike (approximately N 30° E for most of Essex County) because it is in this direction that the greatest interference occurs. They may be placed closer together perpendicular to the strike since interference is lece in al. , 1"




Figure 5.—Location of wells at plants of P. Ballantine and Sons, Newark, N. J., used during pumping tests in January 1949 (after Herpers and Barksdale, 1951, fig. 3, p. 30).

# Well Yield and Specific Capacity

Yields of 35 large diameter public-supply, industrial, and commercial wells tapping the Brunswick Formation range from 35 to 820 gpm (gallons per minute) (Table 2) and average 364 gpm. The distribution of the yields is as follows:

Yields	No. of wells
0-150	4
151-300	12
301-500	12
>500	7

Depths of the same wells in the Brunswick Formation range from 115 to 856 feet; the average depth is 381 feet. Specific capacities of the 35 wells range from 0.21 to 70.00 gpm per foot of drawdown and average 11.07 gpm per foot of drawdown.

Wells tapping the Watchung Basalt commonly produce small to moderate quantities of water. Yields of 26 wells range from 7 to 400 gpm (Table 2) and average 116 gpm. The distribution of the yields is as follows:

Yields	No. of wells
0-100	15
100-199	5
200-300	5
>300	1

Specific capacities of wells in the basalt range from 0.05 to 5.66 gpm per foot of drawdown and average 1.74 gpm per foot of drawdown. Several moderate to high yielding public supply and industrial wells have been developed in the Essex Fells-West Caldwell-Fairfield area. These higher yields may be the result of increased fracturing of the basalt which has been slightly folded in this area.

Figures 6, 7, and 8 are specific capacity cumulative frequency distribution graphs for wells in the Brunswick Formation in Essex County. In figure 6, specific capacities are grouped on the basis of well depth. Wells drilled between 300 and 399 feet deep appear to have consistently higher specific capacities than wells of other depths (fig. 6). This relationship suggests that the best water-bearing zones in the Brunswick Formation will be

Figure 6.—Cumulative frequency distribution of specific capacities of wells penetrating the Brunswick Formation grouped according to depth.

encountered between depths of 300 and 400 feet and that significantly greater quantities of water generally will not be obtained by drilling below 400 feet. The specific capacities of wells grouped according to geographic area are shown in figure 7. These areas divide Essex County into three strips which are approximately parallel to the strike of the Brunswick Formation. The eastern strip is further divided into a northern part covering Belleville, Bloomfield, Glen Ridge, and Nutley, and a southern part covering East Orange, Irvington, and Newark. From this graph it readily can be seen that wells in Maplewood, Montclair, Orange, South Orange, and West Orange, have generally higher specific capacities than wells in other parts of Essex County. The wells in these communities are located in the area immediately east of First Watchung Mountain. In figure 8, specific capacities are related to well diameter. As should be expected, larger diameter wells have higher specific capacities.

# Quality of Water

Except for hardness-forming constituents and local salt-water contamination, water from the Triassic rocks commonly does not contain objectional concentrations of any chemical constituents throughout most of the county (Table 3). The hardness of water ranges from 104 ppm (parts per million) to 273 ppm. In the Newark area, salt-water contamination has seriously impaired the quality of ground water and chloride concentration are as high as 1,900 ppm.

Ground water has high chloride concentrations in areas of relatively heavy pumpage in eastern Newark adjacent to Newark Bay and the Passaic River. By 1900, water levels in these areas, notably in the southeastern section, were considerably below sea level (fig. 9). The major pattern of ground-water development had changed slightly by 1960. More significant however is the extent to which water levels had been lowered below sea level and the incerase in the size of the area affected by 1960 (fig. 10). Heavy ground-water withdrawals have lowered the general water level in these areas (fig. 10), reversing the natural gradient between the ground- and surface-water bodies, and have induced a flow of salt water from the river and bay into the underlying water-bearing formations A water sample collected in 1879 from a well owned by the Celluloid Works, located in this part of Newark, contained only 6.2 ppm chloride. In 1948, water with 1,900 ppm chloride was collected from a well in the same area owned by P. Ballantine and Sons. A probable contributing factor in salt-water intrusion is the dredging of ship canals in Newark Bay and the Passaic River. In deepening these canals, semipervious Recent and Pleistocene sediments were removed which had acted as an imperfect barrier to the infiltration of solt with




Figure 7.—Cumulative frequency distribution of specific capacities of wells penetrating the Brunswick Formation grouped according to geographic area.

Figure 8.—Cumulative frequency distribution of specific capacities of wells penetrating the Brunswick Formation grouped according to well diameter.




Figure 9.—Generalized piezometric contours for the Brunswick Formation in the Newark area based on water levels in wells drilled between 1890 and 1900.

Figure 10.—Generalized piezometric contours for the Brunswick Formation in the Newark area based on water levels in wells

Salt-water contamination of the Brunswick Formation in the Newark area has been investigated by Herpers and Barksdale (1951). Their study was based on analyses of water samples collected in 1942 by the city of Newark. More recent analyses suggest there has been additional encroachment of saline water since 1942 throughout the problem area. In 1942, water from the Wilbur Driver Company's well No. 2 along the Passaic River in northern Newark contained 72 ppm chloride. In 1961, water from this same well contained 330 ppm chloride. Water from a well drilled by Mutual Benefit Life Insurance Company, 520 Broad Street, in 1965 contained 1,145 ppm chloride. Samples collected from other wells in this area contained less than 500 ppm chloride in 1942.

# Pleistocene Deposits

Unconsolidated sediments of Pleistocene age mantle the bedrock throughout much of Essex County (fig. 3). They consist of clay, silt, sand, gravel, and boulders and can be divided into two general categories—stratified drift and unstratified drift. Only sand and gravel aquifers in stratified drift deposits contain sufficient quantities of water to warrant discussion of their water-bearing properties.

Water in the stratified drift occurs under both unconfined (water table) and confined (artesian) conditions. Unconfined ground water occurs where sand and gravel deposits are not covered by clay, silt, or glacial till and are exposed at the surface. The distribution of these deposits is shown on figure 3. For the most part however, these sand and gravel deposits do not yield large quantities of water as they are commonly less than 20 feet thick and are not areally extensive. The unconfined aquifers are recharged directly from precipitation on the outcrop area. Confined and semiconfined ground water occurs where sand and gravel deposits have been covered by lake clay or silt, or by glacial till. These deposits are largely confined to the buried valley so they are not visible on the surface and their regional extent and distribution are therefore not readily apparent. The confined and semiconfined aquifers are recharged by leakage through overlying confining beds and by precipitation falling on outcrop areas outside Essex County. Some recharge may also be derived from the underlying and adjacent Brunswick Formation.

The most productive artesian and semi-artesian aquifers in the stratified drift in Essex County occur as valley fill in stream valleys that were cut in the bedrock before the last glaciation. Consequently the size, shape, and distribution of the aquifers conform to the size, shape, and distribution of the bedrock valleys. The bedrock valley underlying the Newark area (shown on fig. 4) is filled with till and clay, and contains only minor amounts of water-bearing sand. Extensive subsurface exploration in western





Figure 11.—Distribution of valley-fill aquifers in Millburn and Livingston Townships, Essex County, N.


Essex and eastern Morris Counties has demonstrated that the valley-fill aquifers in Essex County are part of an extensive valley-fill aquifer system underlying much of these two counties (Vecchioli and others, 1968). Figure 11 shows the known distribution of valley-fill aquifers in western Essex County.

The most highly developed part of the valley-fill aquifer system is in western Millburn and southwestern Livingston. Four well fields tapping the Pleistocene sand and gravel are located in an area of less than 4 square miles. During 1965 an average of 13.6 mgd (million gallons per day) was pumped from these fields. Such continued heavy development has, naturally, lowered water levels in the aquifer. In 1925, the depth to water in the Canoe Brook well field of Commonwealth Water Company was about 30 feet below land surface. By 1965, the average depth to water in the same field had dropped to 83.5 feet below land surface.

Figure 12 shows the annual mean depth to water in the Commonwealth Water Company's Canoe Brook well field for the 20-year period 1947 to 1966. The water level has declined almost continuously since 1947. This is due in large part to increased demands placed on the adjacent Canoe Brook well fields of the Commonwealth Water Co. and East Orange Water Dept. for most of the period 1947 to 1961. Commonwealth Water Company's Passaic River well field was put into service in 1956 and although the demands on their Canoe Brook field were lessened, the combined pumpage (not shown) continued to increase. However, in spite of the fact that from 1961 to 1966 pumpage from the Commonwealth and East Orange Canoe Brook fields decreased, the water level in the Commonwealth Canoe Brook field continued to decline (fig. 12). Several factors probably have caused this continuing lowering of water level. The Passaic River well field taps the same aquifer and withdrawals there have undoubtedly had some effect on area water levels. In addition, Commonwealth's Canoe Brook well field area has had below average rainfall for 12 of the 13 years since 1953 with a consequent reduction in the amount of available recharge. The reduction in recharge together with increased demands during extended dry periods, especially from 1961 to 1966, have contributed to the steady decline of the water level in the aquifer.

Aquifer tests on the stratified drift deposits have been conducted by the U. S. Geological Survey at two localities in Essex County and at several places in Morris County. The reliability of the results of these tests are questionable for the following reasons: (1) the aquifers are not areally extensive; (2) it is impossible to control or eliminate outside interference; (3) it is real?





Aquiter name:
Qsd, Stratified drift
TRb, Brunswick Formation
TRwb, Watchung Basalt

# TABLE 2.-RECORDS OF SELECTED WELLS IN ESSEX COUNTY, N. J.-Continued

Remarks:
O.W., Owners well number

Well	Owner or Tenant	Oriller	Date Drilled	Alti- tude above mean sea level (ft)	Total depth drilled below land sur- face (ft)	Diam- eler of well (inches)	Depth to which well is cased (ft)	Screen setting (ft)	Aquifer	Static level below land surface (feet)	Yield (gpm)	Draw- down (ft)	Specific capacity (gpm ft)	Remarks
					CAL	DWELL BOI	ЮИСН							
ı	Mt. St. Dominic Acad.			420	876		100	none	TRb		25			
اعد	Duch True to-	Books a Well De II C	9.453	06.0		R GROVE TO			770	42		F.11		
Pk	Rich-Tex, Inc.	Burrows Well Drilling Co.	8- 4-51	250	300	6	97	none	TRwb	47	11	58	. 18	O, W, I
2-1	Rich-Tex, Inc.	Burrows Well Drilling Co.	11- 5-52	250	105	6	89	75-99	Qsd	43	80	32	2,5	O.W.2
3★	Brindell Goat Dairy	Algeier Bros,	6-24-58		110	6	28	none	TRWb	6	10	84	.13	
4.*	Board of Freeholders	Rinbrand Well Drilling Co.	12- 3-57		125	6	117	none	TRWb	70	198	35	5,66	
}					EAS	T ORANGE	(CITY)							
1	Colonial Life Ins. Co.	Artesian Well & Equip. Co.	5-10-49	180	357	10	34	none	ткь	26	323	93	3, 47	
2	Michael Stein & Co.	Parkhurst Well & Pump Co.	6- 3-49	180	150	8	45	none	ТRЬ	75	50	25	U, 0	
3	F. H. Taylor & Sons, Inc.	Burrows Well Drilling Co.	June, 1955	190	254	8	37	none	TRÞ	38	160	122	1, 31	
4	Food Fair Stores, Inc.	Burrows Well Drilling Co.	1956	180	210	8	44	none	11Rb	24		21		
5	New Munn Apts	Rinbrand Well Drilling Co.	6-10-55		200	н	39	none	ткь	20	но	60	1, 33	
					ESSEX	V FELLS BOR	OUGH			Ì				
1	Borough of Essex Fells	Artesian Well & Equip. Co.	2-28-42	243	423	10	110	none	TRWb	+8	300	108	2.8	0.W.8
2	Borough of Essex Fells	Artesian Well & Equip. Co.	March, 1959	280	92	17	61	61-88	Qsd	13	457	55	8.34	O.W. 14
3	Borough of Essex Fells	Artesian Well & Equip. Co.	10-18-41	285	93	10	72	72-92	Qsd	+3	410	50	8.0	O.W.7
4	Borough of Essex Fells	Artesian Well & Equip. Co.	ti-14-46	310	364	10	สร	none	TRwh	10	250	114	2. 19	O, W, 9
1						24	45	45-68						
- 5	Borough of Essex Fells	American Water Co.	Sept. 1927	345	97	16	68-81	81-97	Qsd	10	627	45	13.9	O.W. IA
٠,	Borough of Essex Fells	^	1933	325	565	10	<del>6</del> 5	none	TRwb	-19	146	151	. 97	O, W, 6
,	Borough of Essex Fells		1929	225	295	8		none	TRwb	8	400	92	4. 35	O, W, 5
я	A. Howard	H. A. Kieffer	4-15-56		250	6	92	none	TRWb	72	30	54	. 56	
9	F. Stearns, Inc.	***************************************	1959		196	6	100	поне	TRwb	63	40	43	. 93	
10	Essex Fells Country Club	H. A. Kieffer	8-15-56	500	300	8	38	попе	lkwb	7	55	tos	. 50	

#### TABLE 2.-RECORDS OF SELECTED WELLS IN ESSEX COUNTY, N. J.-Continued

Aquifer name: Qsd, Stratified drift TRb, Brunswick Formation TRwb, Watchung Basalt Remarks: O.W., Owners well number

Well	Owner or Tenant	Driller	Date Drilled	Alti- tude above mean sea level (ft)	Total depth drilled below land sur- face (ft)	Diam- eter of well (inches)	Depth to which well is cased (ft)	Screen setting (f1)	Aquifer	Static level below land surface (feet)	Yield (gpm)	Draw- down (ft)	Specific capacity (gpm ft)	Remarks
					FAI	RFIELD BOR	OUGH							
ì	Fairfield Borough	W. Beatty	1962		90	8	79	79 - 90	Qsd		350			
*	Republic Tool & Mig. Co.	Algeier Bros.	7-30-52	170	53	6	53		Qsd	2	40	8	5,00	
***	curtiss Wright Corp.	Artesian Well & Equip. Co.	1941	170	56u	10		none	TRwb	11	155	136	1, 14	O. W. 4
4 /	Fairfield Borough	H. A. Kieffer	12-26-53	170	185	6	83	попе	трь	20	36	20	1.80	O.W.1
5 <b>*</b>	Fairfield Borough	Burrows Well Drilling Co.	7- 9-64	167	350	10	85	попе	TRB	4	500	64	7.35	
6	De Witt Rubber Mfg, Co,	Algerer Bros.	7-16-54	170	142	6	86	none	IRP	2	25	13	1.92	
7 <b>*</b>	Curtiss Wright Corp.	Artesian Well & Equip. Co.	4- 5-43	175	490	10		попе	TRWb	32	275	85	3, 24	O, W, 6
**	Industry Publications	Algeier Bros.	9-15-54	180	100	6	57	попе	TRwb	15	15	10	1.5	
9.4	Williamson & Co., Inc.	H. A. Kieffer	5-15-53	190	510	6	74	попе	TRwb	13	25	55	.45	
10-	Green Brook Country Club	H. A. Kieffer	1958		300	8	53	none	TRb & TRwb	20	335	28	11.96	O.W.4
			ı			RIDGE BOR	орен							
1	S. Mendelsolm	Wm. Stothoff Co., Inc.	1-12-51	240	166	6	22	none	ТКР	45	30	3	10,00	
2	Chicle Products Co.		1920		757	6	110	none	ДКР	18	50	52	. 96	
l (	Fezem Memorial Home	Wm. Stothoff Co., Inc.	5-19-52	1ห5	IRV. 304 (	INGTON (TO	OWN) 66	none	ткь	75	78	25	3. 1	
2	Kles Diner, Inc.	Parkhurst Well & Pump Co.	3-10-55		250	8	47	none	TRb	31	65	69	. 94	
3	American Stores	Parkhurst Well & Pump Co.	7-17-51	160	402	8	45	none	ТКР	40	126	80	1.57	O.W.1
4	Olympic Park	A. J. Connally, Inc.	1928	158	300	10		попе	TRP	52	420	78	5, 38	O.W. 1
	Irvington Smelting &	Wm. Stothoff Co., Inc.	3-25-53		304	10	62		TRb (	40	300	22	13, 6	
	Refining Works		0 50°40		107	117	112	none	4817	70	and .		10, 0	
	Jersey Plastic & Die Casting Co.	Wm. Stothoff Co., Inc.	3-26-54	155	400	10	38	поне	Лкр	94	183	106	1.74	
,	Gallo Asphalt Co.	f. J. Bott	6- 9-61	150	201	6	107	попе	акь	46	200	24	8.3	
	Palnut Co.	Parkhurst WeII & Pump Co.	1 27-50	170	229	н	80	попс	цкь	45	60	6	10.0	
		_												

Remarks:

O.W., Owners well number

#### TABLE 2.-RECORDS OF SELECTED WELLS IN ESSEX COUNTY, N. J.-Continued

Aquifer name:
Qsd, Stratified drift
TRb, Brunswick Formation
TRwb, Watchung Basalt

AHi Depth Total Static tude depth Diamlevel above which Screen Draw-Specific Date drilled eter of below Yield Driller Aquifer Well Owner or Tenant mean well setting capacity Remarks Drilled below well land (gpm) 500 is (ft) (ft) (gpm/fl) land sur-(inches) surface level cased face (ft) (feet) (H) (H)MONTCLAIR (TOWN) Rapt & Ruden Parkhurst Well & Pump Co. 4-29-48 360 10 23 TRb 5 145 180 . 81 none Bond's Ice Cream, Inc. 3-10-50 510 157 21 TRb Parkhurst Well & Pump Co. none 15 150 55 2.73 1966 Town of Montclair 10 41 TRb 24 950 51 18.62 попе Hahne & Co. Parkhurst Well & Pump Co. 8-9-49 280 350 31 none TRb 18 350 182 1.92 O.W.2 June, 1955 260 75 M. Quadrel Burrows Well Drilling Co. 151 18 none TRb 33 -------- - -Montelair Auto Minit Man Rinbrand Well Drilling Co. 1-10-50 200 16 TRb 40 60 none NEWARK (CITY) Aluminum Finishing Co. J. Foster 7-20-53 50 150 6 55 none TRb 30 100 30 3.33 2 Wilbur B. Driver Co. Rinbrand Well Drilling Co. 7- 2-53 15 400 10 93 ТRЬ 45 240 155 1.55 O.W.5 none 3 390 Pittsburgh Plate Glass Co. Lauman & Co. 1940 12 . . . 12 90 TRb 9 ------none Mc Evoy Court Apartments Oct. 1939 200 Parkhurst Well & Pump Co. 206 6 35 none TRb 84 60 106 . 57 Columbia Theaters, Inc. Wm. Stothoff Co., Inc. 6-9-53 312 8 26 ТRЪ 20 140 32 4.38 none 190 Pabst Brewing Co., Inc. Artesian Well & Equip. Co. 3-14-49 685 14 39 TRb 59 557 67 8.31 O.W.4 none 185 687 240 120 Pabst Brewing Co., Inc. Artesian Well & Equip. Co. 7-17-50 14 55 none TRb 108 2.00 O.W.5 Newark Milk & Cream Co. Rinbrand Well Drilling Co. 75 190 Feb. 1949 25 700 10 80 60 . 39 TRb none 9 Continental Ins. Co. S. P. D'Alessio July 1965 300 8 58 TRb 77 85 72 1.18 none 10 Newark Center Corp. Garden State 2-18-55 - - -700 10-6 150 none TRb 81 89 144 . 62 O.W.1 Artesian Well & Pump Co. 11 117 43 13, 95 Kolker Chemical Works Wm. Stothoff Co., Inc. 12-11-51 12 802 12 127 none ТКЬ 600 O.W.2 12 Kolker Chemical Works Wm. Stothoff Co., Inc. TRb 76 300 13.63 O.W.1 4-27-49 8 359 10 98 none 13 Eureka Construction Co. Rinbrand Well Drilling Co. 1-23-59 10 500 90 none ТRЬ 25 75 225 . 33 8 14 P. Ballentine & Sons 1937 12 875 16 95 ткь 227 375 153 1.79 O. W. 8, Plant #2 none

\*-WITHIN 3 MILES DE SITE

4

# TABLE 2.-RECORDS OF SELECTED WELLS IN ESSEX COUNTY, N. J.-Continued

Aquifer name:
Qsd, Stratified drift
TRb, Brunswick Formation
TRwb, Watchung Basalt

Remarks: O.W., Owners well number

Well	Owner or Tenant	Driller	Date Drilled	Alti- tude above mean sea level (ft)	Total depth drilled below land sur- face (ft)	Diam- eter of well (inches)	Depth to which well is cased (ft)	Screen setting (ft)	Aquifer	Static level below land surface (feet)	Yield (gpm)	Draw- down (ft)	Specific capacity (gpm/ft)	Remarks
					NEWAR	K (CITY) - (	Continued							
15	Celanese Corp, of Amer.	P. H. & J. Colan	1924	12	805	16-10	95	попе	ТRЬ	176	400	28	14, 29	O,W.26
16	Celanese Corp. of Amer.	Layne-New York Co.	5-16-47	14	856	16-10	75	none	1Rb	147	778	40	19, 45	O,W.27
17	J. Hensler Brewing Co.	P. Chaffitelli	12-14-49	12	700	10-8	57	лопе	TRb	60	<b>4</b> 50	240	1.79	O.W.4
18	Synthetic Plastics Co.	Industrial Well & Pump Co.	1-15-63	14	600	8	145	none	TRb	150	300	110	2.73	O.W.1
19	Ablon Finishes, Inc.	Frank Bott	7-12-60	15	<b>50</b> 0	8	86	none	TRb	30	360	70	5.14	
20	Cotan Corporation		1930	10	290	8		none	TRb	140	160	95	1.59	
21	Universal Grain Co.	Wm. Stothoff Co., Inc.	10-18-51	10	303	8	79	none	TRb	143	200	53	3.77	
22	Mother's Food Products, Inc.		1959	11	400	8	107	none	TRb	94	125	8	15,62	
23	Kar Auto Service Co.	P. Chaffitelli	2- 8-50	208	300	6	35	none	1Rb	23	60	104	. 58	
24	Food Fair Stores	Burrows Well Drilling Co.	April, 1955	100	298	8	35	none	TRb	105	250	45	5, 56	
25	S. & S. Super Service Corp.	Rinbrand Well Drilling Co.	2-18-50	50	190	6	94	none	TRb	45	20			
:6	Rutherford & Delaney Holding Co.	Garden State Artesian Well & Pump Co.	7-31-56		220	8-6	42	none	TRb	22	100	73	1.37	O.W.1
7	Linde Air Products Co.	Artesian Well & Equip. Co.	July, 1954	10	500	12	44	none	TRb	17	124	190	. 65	
8	C-O Two Fire Equipment Co.	Parkhurst Well & Pump Co.	4 - 27 - 50	10	603	10	127	none	TRb	35	89	215	. 41	
9	Suburban Motor Lodge, Inc.	Rinbrand Well Drilling Co.	June, 1950	10	555	8	126	none	TRb	15	20	235	. 08	
0	S. B. Penick & Co.	Wm, Stothoff Co., Inc.	6- 7-61		400	10	75	none	TRb	60	644	23	28,00	O.W.2
	ļ				NORTH (	CALDWELL 1	BOROUGH	ļ	i					
1.4	Green Brook Country Club	H. A. Kieffer	July, 1951	310	300	8	33	none	TRWb TRb &	2 flowing	25	81	. 31	O, W. 3
2 🎢	Green Brook Country Club	H. A. Kieffer	March, 1925	290	301	8		none	TRwb	25 gpm	60			O.W. I. Rednilled 1962
1 1/4	A. Struss	H. A. Kieffer	8-16-55		182	6	42	поле	TRwb	65	25	5	5,00	
1	A. F. Leitner	Algeier Bros.	5-24-58		195	6	25	none	TRWb	25	7	125	. 05	

Remarks:

O.W., Owners well number

TABLE 2.-RECORDS OF SELECTED WELLS IN ESSEX COUNTY, N. J.-Continued

Aquifer name:
Qsd, Stratified drift
YRb, Brunswick Formation
TRwb, Watchung Basalt

Well	Owner or Tenant	Driller	Date Drilled	Alti- tude above mean sea level (ft)	Total depth drilled below land sur- face (ft)	Diam- eter of well (inches)	Depth to which well is cased (ft)	Screen setting (H)	Aquifer	Static level below land surface (feet)	Yield (gpm)	Draw- down (ft)	Specific capacity (gpm-ft)	Remarks
ĺ			i		SOUT	H ORANGE (V	TILLAGE)							
1	Village of South Orange		1913	132	274	8		попе	TRB		200			O, W. 1
2	Village of South Orange	Artesian Well & Equip. Co.	1950	1 33	182	10	40	none	ßР	25	170	67	2,54	O,W.2
3	Village of South Orange	Artesian Well & Equip. Co.	1950	134	115	10	40	none	ткь	28	300	11	27, 27	0,W,3
4	Village of South Orange	Artesian Well & Equip, Co.	1950	132	122	10	49	попе	IRb	28	250	50	5,00	O.W.8
5	Village of South Orange		1947	132	355	14		none	TIRH		190			O.W. 14
6	Village of South Orange	Burrows Well Drilling Co.	6- 1-56	148	350	12	45	none	т≀вь	9	560	41	13, 66	O.W. to
7	Village of South Orange	Buttows Well Drilling Co.	3-11-63	148	200	18-12	36	none	TRb	14	847	24	35, 29	O, W. 15
я	Village of South Orange	J. P. Harris	1929	134	301	ห	35	none	1RP	1	520	9	57,78	0.W. U
9	Village of South Orange	J. P. Harris	1931	137	382	16-12	52	попе	7Rb	20	200	90	2, 22	O, W. 12
10	Village of South Orange	J. P. Harris	€-20-30	138	439	16-12	18	none	TRb	7	490	7	70,00	O, W. 13
11	Village of South Orange	Burrows Well Drilling Co.	5 1-56	269	11:	12	26	none	TRb	+3	550	78	7, 05	O.W. 17
					VI	I I RON <b>a Bo</b> rot	≀GH				į			
1#	C. E. Drehman	H. A. Kieffer	10 - 1-57		200	6	38	none		45	18	39	. 46	
2.)	Montelair Golf Club	Rinbrand Well Drilling Co.	1-10-64		500	Ju-8	16	воне		20	138	210	, t-()	
a <b>X</b>	Claremont Diner, Inc.	Algerer Bros.	5-14-54	500	400	ж	15	none	TRb &	15	45	135	. 3.4	

\* - WITHIN 3 MILES OF SITE

Remarks:

O.W., Owners well number

O, W. 1

O. W. I

O.W.2

#### TABLE 2.-RECORDS OF SELECTED WELLS IN ESSEX COUNTY, N. J.-Continued

Aquifer name:
Qsd, Stratified drift
TRb, Brunswick Formation
TRwb, Watchung Basalt

5

6

Nickle Alkaline Battery

Rock Spring Country Club

Rock Spring Country Club

Alti-Depth Total Static tude depth Diamlevel above which Screen Draw-Specific Date Driller drilled eter of below Yield Well Owner or Tenant mean well Aquifer Remarks setting down copacity Drilled below well land (gpm) (ft) (gpm ft) land sur-(inches) surface level cased face (ft) (feet) (ft) WEST CALDWELL BOROUGH ķι 135 6 11-15-57 Mal Bros. Contracting Co. Algerer Bros. 180 TRwb 4 30 18 .37 Mt. Ridge Country Club Parkhurst Well & Pump Co. 1933 \_ - -252 8 119 TRwb 42 85 44 1,93 €2 none F3 Femcliff Golf Club 2-28-55 305 8 79 H. A. Kieffer 180 TRb 14 90 14 none 6,43 Elm-Tre Pool & Club H. A. Kieffer 1926 260 170 - - -4 none ТRЪ ---60 ----- -5 Caldwell Enterprises Burrows Well Drilling Co. 3- 9-56 100 61 none TRwb +3 110 63 1.75 Flowed 30 gpm at -- 3 Borough of Essex Fells 1957 335 254 18-12 100 13 Artesian Well & Equip. Co. none TRwb 262 164 1.59 O.W.13 7 Borough of Essex Fells Rinbrand Well Drilling Co. 1927 240 360 12-8 80 + 175 none TRwb - - -- -- --O.W. 4B Flowed 40 gpm 8 Botough of Essex Fells Rinbraud Well Drilling Co. 1924 240 185 TRwb 0 225 80 2,81 O. W. 4A none 9 S. Crane H. A. Kieffer 12-10-51 - - -250 87 8 TRwb 8 90 43 2,09 попе WEST ORANGE ı Borough of Essex Fells 1940 495 37 52-24 28 27-37 Osd 8 190 27 7,03 O.W.2 2 Bow & Arrow Manor, Inc. H. A. Kieffer 11-20-58 540 126 8 22 TRwb 28 37 1, 35 O.W.3 none TRb & 9- 8-54 102 3 Essex County Country Club Parkhurst Well & Pump Co. 560 115 8 21 +2 100 0.W.I none TRwb . 98 4 Nickle Alkaline Battery Rinbrand Well Drilling Co. 3-21-62 505 8 58 ТRЬ 12 190 213 O.W.2 none

8

8

46

20

22

none

нопе

none

15

110

273

TRb

TRb.

190

25

35

90

25

. 28

1.40



9-26-61

2-28-56

1957

- - ~

510

520

406

750

Rinbrand Well Drilling Co.

H. A. Kieffer

REFERENCE NO. 3

# SUMMARY OF GEOLOGY AND GROUND-WATER RESOURCES OF PASSAIC COUNTY, NEW JERSEY

By L. D. Carswell and J. G. Rooney

U.S. GEOLOGICAL SURVEY
Water-Resources Investigations 76-75

Prepared in cooperation with

NEW JERSEY DEPARTMENT OF ENVIRONMENTAL

PROTECTION, DIVISION OF WATER RESOURCES



SUMMARY OF GEOLOGY AND GROUND-WATER RESOURCES
OF PASSAIC COUNTY, NEW JERSEY

By L. D. Carswell and J. G. Rooney

#### ABSTRACT

Ground water in Passaic County occurs in intergranular openings of unconsolidated stratified deposits of Quaternary age and in joints and fractures in consolidated rocks of Precambrian, Paleozoic, and Triassic age.

The Brunswick Formation of Triassic age is the most important aquifer in the southeastern one-third of Passaic County. Reported yields of public supply and industrial wells range from 50 to 510 gallons per minute (3 to 32 litres per second) and the median yield is 130 gallons per minute (8 litres per second). Most of these wells are 200 to 400 feet (61 to 122 metres) deep. The median yield of all public supply and industrial wells over 300 feet (91 metres) deep and 8 inches (203 millimetres) or larger in diameter is 230 gallons per minute (15 litres per second). Crystalline rocks of Precambrian age are the major source of ground water for domestic use in the northwestern two-thirds of Passaic County. Reported well yields range from 1 to 200 gallons per minute (.06 to 13 litres per second). The median reported yield of domestic wells is 5 gallons per minute (.31 litres per second) and that of public supply wells is 30 gallons per minute (2 litres per second).

Other consolidated rocks--rocks of Paleozoic age and the Watchung Basalt of Traissic age--are utilized primarily for domestic water supplies in Passaic County. Reported yields of wells tapping the Paleozoic rocks range from less than 1 to 35 gallons per minute (.06 to 2 litres per second) and the median yield is 10 gallons per minute (.63 litres per second). Reported yields of domestic wells tapping the Watchung Basalt range from less than 1 to 40 gallons per minute (.06 to 3 litres per second) and the median yield is 12 gallons per minute (.76 litres per second). However, reported yields of nine industrial and commercial wells range from 50 to 180 gallons per minute (3 to 11 litres per second).

Unconsolidated stratified deposits of Quaternary age are locally an important source of ground water for public supply and industrial use in parts of Passaic County. These deposits have not been extensively explored but are potentially an important source of ground water for future development. Reported yields of wells tapping the stratified deposits range from 4 to 920 gallons per minute (.25 to 58 litres per second). The median reported yield of domestic wells is 16 gallons per minute (1 litre per second) and that of public supply and industrial wells is 130 gallons per minute (8 litres per

second. Depths of wells depend upon the thickness of the deposits. Reported depths range from 22 to 170 feet (7 to 52 metres).

The quality of ground water in Passaic County varies from one aquifer to another. Water from the Precambrian rocks is soft to moderately hard (34 to 104 milligrams per litre) and is low in dissolved solids (66 to 159 milligrams per litre). Water from the Brunswick Formation is moderately hard to very hard (89 to 540 milligrams per litre). The dissolved solids content ranges from 129 to 563 milligrams per litre). The occurrence of more highly mineralized water at depth in the Brunswick Formation is indicated by an analysis, made in 1885, of 16,000 milligrams per litre of dissolved solids at a depth of 2,050 feet (625 metres) in a well in Paterson. Water from two wells tapping the Quaternary deposits is moderately hard (65 and 83 milligrams per litre) and has dissolved solids contents of 122 and 133 milligrams per litre).

Water use from both surface and ground-water supplies in Passaic County averaged about 106 million gallons per day (4.6 cubic metres per second) in 1965. Ground water probably accounts for 5 to 10 percent of this total. Ground-water pumpage by the major public supply companies in the county has increased from 2.1 million gallons per day (.09 cubic metres per second) in 1951 to 4.39 million gallons per day (.19 cubic metres per second) in 1968. About 80 percent of the 4.39 million gallons per day (.19 cubic metres per second) was from wells tapping the Brunswick Formation in the southern part of the county.

# INTRODUCTION

# Purpose and Scope

This is one of a series of County ground-water reports authorized by the Water Supply Act of 1958 and its companion Water Bond Act. These reports present assembled data and interpretation on the availability, occurrence, movement, and chemical quality of ground water in New Jersey. This investigation was made by the U.S. Geological Survey in cooperation with the New Jersey State Department of Environmental Protection, Division of Water Resources. The report was prepared under the supervision of John E. McCall and Harold Meisler, consecutive District Chiefs.

# Location and Extent of Area

Pasaic County is located in northcentral New Jersey (fig. 1). It is bounded on the north by the State of New York and Bergen County, on the east by Bergen County, on the south by Essex and Morris Counties, and on the west by Sussex County. The county is shaped roughly like an hour glass with the top to the northwest, and the bottom to the southeast. It lies between longitudes 74°06'W and 74°30'W and latitudes 40°48'N and 41°12'N and contains 194 mi<sup>2</sup> (square miles) [502 km<sup>2</sup> (square kilometres)] of land area and 8 mi<sup>2</sup>

(21 km<sup>2</sup>) of water. Paterson is the county seat; other major communities include Passaic and Clifton.

# Previous Investigations

The geology of the southeastern third of Passaic County is described in the Passaic Folio (Darton and others, 1908). A northeast-trending 30-square mile  $(78 \text{ km}^2)$  outlier of Paleozoic rocks in the northwestern part of the county is described by Kümmel and Weller (1901). Hotz (1953) described the Precambrian igneous and metasedimentary rocks in a 15-square mile area (39 km $^2$ ) in the vicinity of Hewitt and Ringwood as a part of his study of magnetite deposits. The bedrock geology of the area immediately north of Passaic County in New York has recently been described by Offield (1967) who presents an excellent review of the rock types of the highlands and the stratigraphic terminology. Salisbury (1902) described the Quaternary deposits in his report on the glacial geology of New Jersey. The availability of ground water in Passaic County is summarized by Widmer and others (1966) in Water Resources Resume State Atlas Sheet No. 23 and its companion volumes for Atlas Sheets No. 22 and No. 26. The availability of ground water in Morris and Essex Counties is described, respectively, by Gill and Vecchioli (1965) and Nichols (1968). A report on the water resources of the Ramapo River basin, New Jersey, by Vecchioli and Miller (1973) covers a part of Pompton Lakes Boro and Wayne Township in Passaic County and an elongate area just to the northeast of the county.

# Methods Used in this Investigation

During this investigation records of more than 1,500 wells were collected and analyzed for information on well yields and depths, static water levels, and the thickness and lithology of Pleistocene deposits. Field work included the location of most of the public-supply wells and many of the industrial wells and reconnaissance of the geology of the county. Many of the wells for which records were available, particularly in the northwestern two-thirds of the County, were drilled for domestic use. The locations of most of the domestic wells used for this report are from applications for permit to drill submitted to the New Jersey Bureau of Geology by the prospective owner or driller.

Records of selected wells are given in table 2; their locations are shown in figure 2. Each well is identified by a well number which is prefixed with an abbreviation of the name of each township, city, or borough in which the well is located. Municipal abbreviations are as follows:

Municipality	Abbreviation	Municipality	Abbreviation
Bloomingdale	В1	Pompton Lakes	PL
Clifton	C1	Prospect Park	PP .
Haledon	<b>H1</b>	Ringwood	Ri
Hawthorne	Нw	Totowa	To
Little Falls	${f LF}$	Wanaque	Wn
North Haledon	NH	Wayne	Wy
Passaic	Ps	West Milford	WM
Paterson	Pt	West Paterson	WP

The wells within each municipality are numbered serially, generally starting from the northern margins of each municipality. Thus, well Ri-2 is located in the northern part of Ringwood and well Ri-30 is in the southern part.

# <u>Acknowledgments</u>

The cooperation of Dr. Kemble Widmer, the State Geologist of New Jersey, is gratefully acknowledged for providing access not only to the well-organized and voluminous file of well records maintained by the New Jersey Bureau of Geology, but in addition, to the manuscript copies of Water Resources Resumés of State Atlas Sheets No. 22 and 26 which are being prepared for publication by the State Survey. Other members of the New Jersey Geological Survey, including Joseph Miller, provided assistance during the data gathering phase of this investigation.

#### **GEOGRAPHY**

# Topography and Drainage

The northwestern two-thirds of Passaic County is in the New Jersey Highlands, a subdivision of the Reading Prong of the New England physiographic province. The southeastern one-third of the county is the Lowland section of the Piedmont physiographic province.

The Highlands are an area of moderate topographic relief largely underlain by gneiss of Precambrian age but also including an outlier of folded sedimentary rocks of Paleozoic age which form a series of parallel ridges and valleys in the western third of the Highlands area. The ridges and valleys formed on the rocks of Paleozoic and Precambrian age have a prominent northeast-southwest alignment reflecting the dominant structural orientation of the rocks as well as the direction of movement of the ice which overrode the area during the Wisconsin Glaciation. Hotz (1953, p. 159) reports that the topographic expression of major cross faults are well defined trench-like structures apparent on aerial photographs. These faults strike east-west, interrupt minor drainage lines, and offset small valleys and ridges.

Altitudes in the Highlands range from 1,491 ft (feet) [454 m (metres)] on Bearfort Mountain to 200 ft (61 m) on the Wanaque River at Pompton Lakes. The maximum local relief is 850 ft (259 m) between the crest of Bearfort Mountain and the valley immediately to the east. Northwest of the outlier of Paleozoic rocks, valleys partially filled with glacial deposits are at an altitude of about 1,200 ft (366 m). Immediately to the east of the outlier the valleys are at an altitude of 600 to 800 ft (183 to 244 m), and the valley of the Wanaque on the eastern side of the Highlands is at an altitude of 300 ft (91 m).

The Highlands in Passaic County are drained by the Pequannock, Wanaque, and Ramapo Rivers which join to form the Pompton River, a tributary of the Passaic River. A small area in the northwest corner of the County is drained by the northeastward-flowing Long House Creek, a tributary of the northward-flowing Wallkill River.

In the Highlands area, eastward-flowing streams generally have steeper gradients than streams parallel to the regional structure of the Precambrian and Paleozoic rocks. The eastward-flowing streams are presumably controlled by erosion along transverse joints and shear zones associated with cross faults; whereas, the valleys and local topographic lows containing Upper Greenwood Lake, Greenwood Lake, and the lower Wanaque River are all apparently developed along major longitudinal or oblique faults.

The Highlands area in Passaic County is largely developed as a watershed for surface-water supply; approximately one quarter of the land area used for this purpose is municipally owned. This area contains or partially contains Oak Ridge, Clinton, and Charlotteburg Reservoirs, and Echo Lake, which are regulated bodies of surface water in the Pequannock River drainage and are utilized for water supply by the City of Newark. Upper and Lower Greenwood Lakes and Wanaque Reservoir in the Wanaque River drainage are used for surface-water supply by the North Jersey District Water Supply Commission.

The Piedmont Lowland in Passaic County is underlain by igneous and sedimentary rocks of Traissic age. The sedimentary rocks throughout most of the area underlie gently rolling topography one to three hundred feet in altitude. This gently rolling topography is broken by the abrupt arcuate ridges of the First and Second Watchung Mountains and Packanack Mountain which are underlain by three successive sheets of basalt. The highest altitude in the Piedmont area is 885 ft (270 m) on High Mountain, a knob of the Second Watchung Mountain. The lowest altitude is sea level along the tidal portion of the Passaic River on the southeastern boundary of the County. Drainage is to the Passaic River which flows in an irregular but dominantly eastward direction across the Piedmont Lowlands traversing the Watchung Mountains through gaps at Little Falls and Paterson. The Pompton River flows southward from the Highlands across the Piedmont Lowlands joining the Passaic River near Mountain View after passing through a gap in Packanack Mountain. Smaller streams, in general, parallel the ridges of the Watchung Mountains.

Passaic County is entirely within the part of northern New Jersey that has been subject to Wisconsin Stage glaciations. Consequently, the topography shows the effects of both glacial erosion and deposition. In general, the ridges have been scraped clean and contain abundant bedrock outcrops; whereas, the valleys are filled with a variety of unconsolidated deposits which extend part way up the flanks of the adjacent high areas.

# Climate

The climate of Passaic County is continental in character being controlled largely by storms which move from west to east across the county. These storms are generally dominated by polar continental air masses in winter and tropical air masses in summer. Although part of the precipitation in Fassaic County results from the storms which move from west to east across the county, the heaviest rains are produced when coastal storms of tropical origin move inland.

Precipitation throughout the county averages 48 in (inches) [122 mm (millimetres)] annually and is normally well distributed throughout the year. Because the Highlands area is generally higher in altitude than the Piedmont Lowlands, the temperature in the Highlands averages several degrees cooler than in the Piedmont Lowlands in both summer and winter. Although both areas receive equal precipitation, the cooler Highlands receive more than 6 in (152 mm) more snowfall than the Lowlands.

At Paterson the frost-free periods average 192 days from April 16 to October 25. The frost-free period at Charlotteburg in Passaic County averages only 128 days, from May 20 to September 25. In the northwestern portion of the county the growing season is even shorter. The average July temperature is 75.9°F (24°C) at Paterson and 71.2°F (22°C) at Charlotteburg In January the average temperature is 31.9°F (0°C) at Paterson and 29°F (2°C) at Charlotteburg (U.S. Weather Bureau, 1959).

# Population and Economic Development

In 1960 the population of Passaic County was 406,518, a 20 percent increase over 1950. This increase has been predominately in the suburban areas such as North Haledon, Pompton Lakes, Totowa, and Wayne which over the 10-year period had population increases of 69.7, 102.9, 80.3, and 148.3 percent, respectively. Municipalities having the largest population are Clifton (32,084), Paterson (143,663), and Passaic (153,963). The population increased 27.2 percent in Clifton and 3.1 percent in Paterson and decreased 6.5 percent in Passaic.

The northwestern part of the county comprises 124 mi<sup>2</sup> (321 km<sup>2</sup>) or 65 percent of the total area of the county, but contains only 6 percent of the total population. This area of the county is used predominantly for recreation and water supply. The reservoirs and watersheds owned by Newark and the North Jersey District Water Supply Commission cover approximately one quarter of the area. The southern part of the county is highly industrialized. Manufacturing includes textile, apparel, leather products, metal products, and electrical and nonelectrical machinery. Only 3 percent of the land area in the county is devoted to agriculture.

#### GEOLOGY

# General Considerations

The bedrock underlying the Highlands is composed of crystalline rocks of Precambrian age, an outlier of sedimentary rocks of Paleozoic age, and a small fault-bounded wedge of black shale of Paleozoic age near Pompton Lakes. The bedrock geology of Passaic County is shown in figure 3. The crystalline rocks include the Franklin Limestone and metasedimentary and igneous gneisses. The outlier of Paleozoic age is bounded on the northwest by a fault which closely parallels the strike of the beds. On the east side of the outlier the sedimentary rocks lie unconformably on the Precambrian gneiss. The southeastern third of Passaic County, the Lowlands, is underlain by mudstone, sandstone, conglomerate, and basalt of Triassic age.

Unconsolidated deposits overlie the bedrock in both the Highlands and the Lowlands and are largely related to the last advance and retreat of the continental glacier across the area in Wisconsin time. These unconsolidated deposits are generally thick and continuous in valleys and on lower hill slopes and thin to absent on hilltops. The deposits on the upper slopes of the hills and hilltops were deposited directly by the glacier and are largely till consisting of an unstratified mixture of clay, silt, sand, gravel, and boulders. The deposits in the valleys and lower slopes of the hills locally contain till in addition to well-sorted stratified clays, sands, and gravels deposited by streams or in lakes.

# Precambrian Rocks

The Precambrian igneous and metasedimentary rocks in northwestern Passaic County have been referred to as Pochuck, Losee, and Byram in reports on the geology of the area (Johnson, 1950). These older map units have subsequently been found inadequate for the purposes of detailed mapping and have been discarded by recent workers (Sims, 1958; Hotz, 1953; Offield, 1967; and Smith, 1969). Recent practice has been to assign descriptive mineralogic terms to a much greater number of lithologic units mapped in the field. These units include; hypersthene-quartz andesine gneiss, pyroxene quartz feldspar gneiss, quartz feldspar biotite gneiss, amphibolite, granite and granitic gneiss, and Franklin Limestone. Distribution of these units is shown in figure 3. Because the occurrence and movement of ground water appears to be similar in all these lithologic units they are not described in detail in this report.

The Precambrian rocks are characteristically gneissic, granitoid, foliated, and structurally complex. The gneisses are cut by northeast-trending faults which parallel the regional strike of the rock units and by transverse (east-west) trending faults.

The regolith and soil that had developed on top of the Precambrian rocks during Tertiary time was almost entirely removed by Pleistocene glaciation.

Few drillers' logs indicate the presence of weathered and decomposed gneiss. The gneiss presents a fresh, unweathered appearance in outcrop. Salisbury (1894, p. 17) reported that the surface of the gneiss beneath the till was smooth and polished and that it was the exception to find it weathered.

# Paleozoic Rocks

Rocks of Cambrian, Ordovician, Silurian, and Devonian age in western Passaic County underlie a 2- to 3.5-mile (3 to 6 km) wide belt trending northeasterly from the Pequannock River to the New York State line. This belt is part of a synclinal outlier of Paleozoic rocks, approximately 60 mi (97 km) in length. The main outcrop area occurs 25 mi (40 km) to the northwest. The syncline is truncated on the northwest by a fault which places strata of Devonian age in contact with Precambrian gneiss. On the southeast side of the syncline quartzite of Cambrian age and conglomerate of Silurian age lie unconformably upon the gneiss. Kummel and Weller (1901) have mapped a small syncline within the belt of Paleozoic rocks on the west side of Greenwood Lake. The small syncline contains strata of Silurian and Devonian age and is truncated on the northwest by a fault that extends from the New York State line southeastward to the vicinity of West Milford.

Near Pompton Lakes an area of less than  $1 \text{ mi}^2$  (3 km<sup>2</sup>) is underlain by black shale of Ordovician age. According to Darton and others (1908) the shale is bounded by faults.

The Paleozoic sedimentary rocks of the outlier in western Passaic County are the Hardyston Quartzite of Cambrian age, the Kittatinny Limestone of Cambrian and Ordovician age, a black shale unit of Ordovician age, the Green Pond Conglomerate, Longwood Shale, and Decker Limestone of Silurian age, and the Kanouse Sandstone, Cornwell Shale, Bellvale Sandstone of Darton (1894), and Skunnemunk Conglomerate of Devonian age. The following brief descriptions of Paleozoic sedimentary rocks of Passaic County are based largely on the descriptions of Kümmel and Weller (1902).

Hardyston Quartzite—The Hardyston Quartzite of Early Cambrian age is the oldest unmetamorphosed sedimentary formation in Passaic County and underlies a narrow belt on the eastern side of the Paleozoic rock outlier. The Hardyston is about 30 ft (9 m) thick and is composed of vitreous blue quartzite which grades upward into calcareous sandstone which is white and very friable where weathered.

Kittatinny Limestone--The Kittatinny Limestone is a massively bedded, silicious, bluish gray limestone of Cambrian and Ordovician age. The contact between the Kittatinny and the underlying Hardyston is gradational. Erosion, prior to the deposition of the overlying Green Pond Conglomerate, has removed all but about 130 ft (40 m) of this unit which is 2,500 to 3,000 ft (762 to 914 m) thick in western New Jersey. The limestone occasionally contains pockets of conglomerate which were considered by Kümmel and Weller (1902, p. 8) to be masses of the overlying Green Pond Conglomerate that filled the fractures and crevices in the deeply weathered and eroded surface developed on top of the Kittatinny.

Black Shale. -- This black shale of Ordovician age underlies Pompton Lakes. Although it shows only a moderate degree of metamorphism, it was mapped as Hudson Schist\* by Darton and others (1908) because of its presumed equivalence to the schists of Ordovician age which crop out 20 mi (32 km) to the east along the Hudson River. Two small areas (not shown in figure 3) of similar nonfossiliferous black shale are found in the outlier of Paleozoic rocks near Oak Ridge Reservoir in western Passaic County and were referred to as Hudson River Shale\* by Kümmel and Weller (1902, p. 8). The black shale is probably equivalent to the Martinsburg Formation in western New Jersey. A few miles north of Passaic County in New York presumed Martinsburg equivalents have been subdivided into a number of distinct formations. Inasmuch as the correlation of the nonfossiliferous shale with either the section in New York or that of the type Martinsburg is uncertain, no formal stratigraphic name is applied to the unit here. As the area underlain by the shale is small, the shale is considered hydrologically unimportant for purposes of this report.

Green Pond Conglomerate. -- The Green Pond Conglomerate of Silurian age lies unconformably upon an erosional surface which cuts across rocks of Precambrian, Cambrian, and Ordovician age. The Green Pond characteristically has a pinkish color, is 1,200 to 1,500 ft (366 to 457 m) thick, and is a coarse silicious conglomerate which is interbedded with and grades into quartzite and sandstone. The Green Pond is very resistant to erosion thus forming the comparatively high steep slopes of Kanouse Mountain, a linear ridge extending from Charlotteburg north to West Milford. Locally, the basal beds are friable where they contain significant amounts of reworked Kittatinny Limestone but more typically the Green Pond contains silicious cement and is very hard.

Longwood Shale. -- The Longwood Shale of Silurian age crops out intermittently in a narrow belt to the west of Kanouse Mountain. It consists of about 200 ft (61 m) of red shale and conformably overlies the Green Pond Conglomerate. The cleavage in the shale generally obscures bedding.

<u>Decker Limestone.--</u>The Decker Limestone is a dark gray, impure, shaley, and silicious limestone. It is 40 to 50 ft (12 to 15 m) thick and is the youngest Silurian formation in the area.

Kanouse Sandstone.--The Kanouse Sandstone of Devonian age is 215 ft (65 m) thick. It consists of a lower white, thick bedded, fine grained quartzose conglomerate that is about 100 ft (30 m) thick and an upper greenish, hard thin-bedded quartzose sandstone. The conglomerate is usually friable but, locally, cementation with silica has formed a hard quartzite.

<u>Connwell Shale.--</u>The Cornwell Shale is a black to dark gray slaty shale having gradational contacts between both the overlying Bellvale Sandstone of Darton (1894) and the underlying Kanouse Sandstone. It is about 1,000 ft (305 m) thick.

\*The names Hudson Schist and Hudson River Shale have not been adopted by the U.S. Geological Survey.

Bellvale Sandstone of Darton (1894).--The Bellvale Sandstone is a dark-gray, hard, flaggy to thick bedded, fine- to medium-grained sandstone. The formation contains alternating beds of red and green shale, sandstone, and conglomerate near the top. Kümmel and Weller (1902, p. 23) report a thickness of 1,600 to 2,000 ft (488 to 610 m) for the Bellvale Sandstone.

Skunnemunk Conglomerate. -- The Skunnemunk Conglomerate is a purple and maroon, massively bedded conglomerate containing beds of reddish sandstone and shale. The formation is 2,500 ft (762 m) thick, very hard, and resistant to erosion. It underlies the comparatively high rugged terrain of Bearfort Mountain.

# Triassic Rocks

The rocks of Triassic age that underlie the southern one-third of Passaic County are the Brunswick Formation and the Watchung Basalt. See figure 3. The Brunswick and the Watchung are a part of the Newark Group which elsewhere in New Jersey includes two units (Stockton and Lockatong Formations), not present in Passaic County. The rocks generally have a monoclinal dip of 10° to 15° W., but they contain some gentle open folds such as those expressed by the arcuate form of the Watchung Mountains. The Newark Group is bounded on the northwest by a fault which places it in contact with Precambrian gneiss and Ordovician shale. The rocks are cut by a number of north- to northeast-trending high angle faults which are evident (see figure 3) where they offset the contact between the Watchung Basalt and the Brunswick Formation.

#### Brunswick Formation

The Brunswick Formation forms broad valleys between the Watchung Mountains and gently rolling lowlands east of First Watchung Mountain. The Brunswick consists of alternating beds of reddish-brown sandstone and mudstone. The texture of the rocks is generally coarser in the northern part of the area than in the southern part. Conglomerates occur a little below the base of the basalt flow underlying First Watchung Mountain and locally along the northwestern border of the outcrop area. These "border conglomerates" are composed of pebble derived from Precambrian gneiss and Paleozoic rocks that cropped out in the Highlands during Triassic time.

## Watchung Basalt

Intercalated between the beds of the Brunswick Formation are three sheets of basalt which form the crest of the First and Second Watchung Mountains and Packanack Mountain. Each basalt sheet is made up of a series of lava flows which outpoured during the deposition of the Brunswick Formation. Individual flows usually have vesicular zones at their tops and bases. The basalt sheets that form First and Second Watchung Mountains, and Packanack Mountain are approximately 600, 850, and 300 ft (183, 259, 91 m) thick, respectively (Darton and others, 1908, p. 10).

# Quaternary Deposits

Bedrock in Passaic County is largely concealed beneath unconsolidated deposits genetically related to the continental ice sheets that overran the entire county during the Wisconsin Stage of the Pleistocene Epoch. As the glacier advanced across the county existing drainage systems were blocked by ice and modified by glacial erosion and deposition. Stream gradients were temporarily altered by warping of the earth's crust as a result of the weight of the ice. This combination of factors resulted in constant readjustment of drainage in front of the ice sheet as it advanced and withdrew from the area. Many lakes were formed; the largest of these, known as Lake Passaic, covered the area which lies between the Second Watchung Mountain and the Highlands in Passaic, Essex, Morris, Union, and Somerset Counties. The development and subsequent drainage of Lake Passaic is described by Salisbury (1902) and Salisbury in Darton and others (1908).

Glacial deposits consist of boulders, gravel, sand, silt, and clay largely derived from the local bedrock. The deposits are broadly subdivided on the basis of whether they are stratified or unstratified. The unstratified deposits (till) are not sorted, contain rock fragments from clay size to boulders, and were deposited directly from the glacier. The stratified deposits are not only layered but moderately to well sorted as a consequence of their having been transported in meltwater and deposited in streams or lakes.

The stratified deposits of Passaic County are, in this report, grouped into three categories; (1) deposits formed prior to the last advance of the glacier, (2) deposits resulting from the last advance of the glacier, and (3) deposits formed after the retreat of the glacier and associated with present day drainage.

Stratified deposits formed prior to the last advance of the glacier in the county are thin [2 to 50 ft (.61 to 15 m) thick] sands and gravels which overlie bedrock and are overlain by till or lake beds. These deposits occur characteristically in or near the base of buried pre-glacial or inter-glacial stream valleys.

Stratified deposits resulting from the last advance of the ice sheet include kames, which were formed in contact with the ice, coarse outwash deposits, and lake deposits. The kames in general are on the flanks of the Watchung Mountains and between Second Watchung and Packanack Mountains in central Wayne Township. The coarse outwash deposits formed deltas in the highlands. Available well logs do not always permit a clear distinction to be made between coarse outwash deposits and sands and gravels deposited prior to the last advance of the glacier. Both deposits intertongue with and are overlain by finer grained sediments. Lake deposits consist largely of laminated silt and clay which are up to 100 ft (30 m) thick in the valleys between Second Watchung Mountain and the Highlands.

The lake deposits are overlain by deposits associated with present day drainage. These include swamp deposits of organic muck and alluvium on the flood plains of the major streams. Alluvium is composed of silt and fine sand and is generally not more than 20 ft (6 m) thick.

The areal distribution of the surficial deposits of roughly the southern one third of Passaic County is shown in the Passaic Folio (Darton and others, 1908). Surficial geology of the northern two thirds of the county is shown in Salisbury (1902). An indication of the distribution of Quaternary deposits is given by Rogers and others (1951) in an engineering soil survey of passaic County.

The thickness of the Quaternary deposits and the distribution of known subsurface lithologies in Passaic County are indicated in figure 4. This map is a first approximation as it is based on drillers' logs of variable quality and the locations and altitudes of wells have not been checked in the field. The deposits are thin to absent on the hills and are thickest in the present day valleys, particularly where they fill pre glacial or inter glacial valleys. Maximum known thickness is about 220 ft (67 m) in the valley of the Pequannock River near Pompton Lakes.

# Structure

The structural grain in Passaic County is formed by the northeast strike of the layers and foliations of the sedimentary, igneous, and metamorphic rocks, and the parallel trends of fold axis and major faults. The major northeast-trending faults bound large blocks and commonly have vertical displacements of thousands of feet. The northwest part of each structural block is depressed in relation to the adjoining block bringing rocks of Paleozoic and Triassic age adjacent to the much older Precambrian gneisses.

The Precambrian rocks trend northeast, dip southeast, and contain both isoclinal and open folds. They are cut by minor longitudinal and oblique reverse faults and transverse normal faults. Sims (1958, p. 54) reports that faults within the Precambrian rocks of the Dover district in Morris County have small displacements in contrast to the great faults that bound individual structural blocks. Several sets of vertical or steeply dipping joints occur in the Precambrian rocks. One set is parallel to the regional structure. A second set is transverse to it, and a third set is oblique to the regional structure. The transverse joints are the most abundant and the most prominent set (Sims, 1958, p. 47). Another set of joints is nearly horizontal or may dip gently in any direction and presumably is a result of sheeting due to the release of load by erosion.

The outlier of Paleozoic rocks contains a large syncline which is truncated on the west by a major northeast-trending normal fault which places rocks of Devonian age adjacent to rocks of Precambrian age. The Paleozoic rocks are cut by smaller northeast-trending reverse faults at both Newfoundland and Greenwood Lake. Joint sets in the Paleozoic rocks are parallel, transverse, and oblique to the regional strike of the beds and according to Sims (1958,

p. 48) "probably reflects prominent joint sets in the Precambrian rocks." The transverse joints appear to be the most prominent and apparently control the location of streams that transect Bearfort Mountain.

The Triassic rocks are bounded on the northwest by a major northeast-trending normal fault. In general the Triassic rocks have a monoclinal dip of 10° to 15° NW and contain shallow open folds such as those expressed in the arcuate trend of the outcrop of the Watchung Basalt. Minor north-trending normal faults cut the Triassic rocks and are apparent where they offset the contact between the basalt flows and the Brunswick shale. The Brunswick contains vertical joints. The major joint sets are parallel and transverse to the strike of the beds. Many of the flows of the Watchung Basalt contain prominent columnar structure.

A thorough discussion of the origin of vertical or steeply dipping joints is beyond the scope of this report. In a study of jointing, Hodgson (1961, p. 37) concluded that "systematic joints are produced by tidal forces through a fatigue mechanism and the direction of the joints is considered to be inherited by upward reflection of the joint pattern in pre-existing jointed rocks." The systematic joints in Triassic and Paleozoic rocks in Passaic County have the same basic trends as do the joints in the Precambrian rocks.

#### GROUND WATER HYDROLOGY

# **Principles**

Water is continually being exchanged in a circulatory pattern between the earth and the atmosphere. In general, the amount of precipitation ultimately determines the amount of water available for man's use. Some of the precipitation that falls on land evaporates where it falls, some is absorbed by plants that later transpire the water back to the atmosphere, some flows overland to streams, and some infiltrates into the ground to become ground water. The ground water is discharged to streams, and streams flow to the oceans where the water can be evaporated back to the atmosphere.

Ground water is the subsurface water in the zone of saturation--the zone in which all the rock voids are filled with water under pressure equal to or greater than atmospheric. The water table is the upper surface of this zone and in Passaic County occurs at depths of 20 to 40 ft (6 to 12 m) below land surface on hilltops and intersects the land surface in valleys where it is contiguous with the upper surface of streams, lakes, swamps, and reservoirs.

In unconsolidated deposits, and in friable consolidated rocks, ground water is stored in and moves through the intergranular openings. Ground water in the consolidated rocks of Precambrian, Paleozoic, and Triassic age occurs in and moves through cleavage planes, joints, fractures, and faults. These openings become fewer and tighter with increasing depth below the land surface but tend to be distributed in an orderly geometric attitude within rock units of homogeneous composition. The openings are better developed and enlarged in some rocks than others; however, the openings form a comparatively small volume in comparison to the volume of the rock as a whole.

The movement of ground-water in the Precambrian igneous and metamorphic rocks and the Paleozoic sedimentary rocks is probably largely in a direction transverse to the regional structure of the beds. Openings along the joint set transverse to the regional structure have probably been selectively enlarged by weathering more than those openings along joints parallel and oblique to the regional structure. The greater weathering of transverse joints is indicated by their greater abundance and prominence and by the dominant east-west alignment (parallel to the direction of dominant jointing) of streams cutting the Precambrian and Paleozoic rocks. A further suggestion that the movement of ground water in the Precambrian and Paleozoic rocks is controlled largely by the transverse joints comes from an analysis of streamflow data of West Brook and Ringwood Creek. West Brook, which traverses the regional structure, has higher flow per square mile than Ringwood Creek which parallels the regional structure. The mean flow for West Brook near Wanaque is  $1.94~(\mathrm{ft^3/s})/\mathrm{mi^2}$  (cubic feet per second per square mile) [.0212]  $(m^3/s)/km^2$  (cubic metres per second per square kilometre)] and for Ringwood Creek it is 1.65  $(ft^3/s)/mi^2$  [0.180  $(m^3/s)/km^2$ ]. Differences in low flow, which are composed almost entirely of ground-water discharge, between the two streams are shown in the table below. There is no known variation in thickness, composition, or distribution of the Pleistocene deposits, or difference in precipitation that would account for the higher flow of West Brook.

Average of the minimum mean discharge for designated number of days [(ft<sup>3</sup>/s)/mi<sup>2</sup>]

Stream	3	7	14	30	60	90
West Brook near Wanaque	0.123	0.138	0.167	0.215	0.332	0.454
Ringwood Creek near Wanaque	.095	.112	.137	.185	.283	.372

Water-bearing openings in the Brunswick Formation in New Jersey occur in discrete zones controlled by bedding. These tabular aquifers extend downdip for several hundred feet and are continuous along strike for thousands of feet. Hydraulic connection between the aquifers is generally poor. The movement of water in these aquifers under pumping and presumably under natural conditions is preferentially along strike (Vecchioli, 1967, and Vecchioli and others, 1969). Thus, discrete water bearing and nonwater bearing zones in the Brunswick form a series of tabular aquifers and aquitards ranging up to tens of feet thick and dipping to the west at approximately 10 to 15 degrees. The basalt flows that are intercalated with the Brunswick generally act as aquitards.

In Passaic County the ground-water reservoir is a few hundred feet thick and can be visualized as composed of a number of small basins separated by divides which at land surface coincide with surface-water drainage divides. In the subsurface these ground-water divides do not necessarily descend vertically through the zone of fresh water circulation but may in places become essentially horizontal where they form divides between shallow local flow systems and deeper and larger flow systems. Ground-water flow systems in the county are generally small, the largest underlying probably only a few square miles. No regional ground-water flow system underlies the entire area.

Areal variations occur in the thickness, porosity, and permeability of the rock within the zone of fresh-water flow. These variations are partly the result of changes in the chemistry of the water and its ability to weather and dissolve mineral matter as the water moves through the rocks. In the upland areas, water entering the water table contains dissolved oxygen, carbon dioxide, and humic acids which greatly aid in the weathering of rock. In contrast the water moving along the longest flow paths is alkaline and may be much closer to being in chemical equilibrium with the rock. Variations in thickness, porosity, and permeability may also be the result of areal variations in the rates of movement and volume of water transmitted through the rocks. On hilltops or divides a comparatively small volume of water enters and moves through the secondary openings, thus limiting the amount of weathering. On the other hand comparatively large volumes of water move beneath the flanks of major valleys. Movement of ground water in the valleys is generally upward to discharge. Because it is a discharge area, precipitation that falls on the area cannot enter the system and, therefore; certain forms of the weathering and particularly the oxidation of minerals is precluded.

Water-bearing fractures at different depths below land surface contain water under different hydraulic heads. On stream-drainage divides, hydraulic heads decrease with increasing depth and in major valleys they increase with increasing depth below land surface. In intermediate areas, including minor valleys, there may be reversals in the direction of head change with increasing depth below land surface. Most wells in the consolidated rock penetrate more than one producing fracture or zone of fractures which have different hydraulic heads. As a result, the observed water level in a well is characteristically a composite head and does not indicate the hydraulic head of any single water-producing zone. When a well penetrates separate fracture zones having different hydraulic heads some of the natural flow is short circuited through the well from the fracture having a higher hydraulic head to that having the lower head. A consequence of the internal flow in wells under nonpumping conditions may be the cleaning of openings which were partially sealed during drilling. Some of the variation in well yields noted in Passaic County may in part depend upon which part of the flow system the well penetrates and the consequent effect of internal borehole flow upon the cleaning of water-bearing openings.

In a study of the availability of water in igneous and metamorphic rocks in the southern Piedmont province Legrand and Mundorff (1952) found a relationship between well yields and the topographic location of the well. They found that wells located in draws have the highest yields and progressively smaller yields are found from wells in the following topographic locations: valleys, slopes, flats, and hills. Studies in similar terrains throughout the

New England and Piedmont provinces have in general confirmed the relationship between yields and topographic location of the wells. James (1967) in a study of the availability of water in the Precambrian crystalline rocks of the New Jersey Highlands found the same relationship between well yield and topographic location. Yields of wells penetrating the Precambrian rocks in Passaic County probably bear a similar relationship.

## Water-Bearing Properties of the Rocks

The rocks of Passaic County differ greatly in their ability to yield water to wells. Figure 5 shows the frequency distribution of reported yields of wells tapping the major rock units in Passaic County. Difference in well yields between rock units and variations in well yield within a rock unit depend in part upon the hydraulic characteristics—permeability, thickness, and storage coefficient—of the aquifer. For consolidated rocks, these characteristics depend upon the number, size and degree of interconnection of secondary openings which occur along structural features such as joints, faults, cleavage, and bedding. Other factors affecting well yields include; well diameter and depth, degree of well cleaning and development, and the hydraulic continuity of the aquifer with a source of induced recharge from a surface—water body.


#### Precambrian Rocks

t on


The Precambrian rocks are the major source of ground water for domestic use in the northwestern two-thirds of Passaic County. These rocks generally yield smaller quantities of water to individual wells than do the other major geologic units in Passaic County. Reported yields of wells tapping the Precambrian rocks in Passaic County range from less than 1 to 200 gal/min (gallons per minute) [.06 to 13 1/s (litres per second)]. The highest reported yields are obtained from wells that are located in the larger valleys near streams or large surface-water bodies such as Lake Erskine and Greenwood Lake.

The frequency distributions of reported yields of 415 domestic wells and of 21 public-supply wells are shown in figure 5. The median yield of the domestic wells is 5 gal/min (.32 1/s) and that of the public-supply wells is 30 gal/min (2 1/s).

Depths of wells drilled in Precambrian rocks vary considerably in Passaic County. They depend in part on the cost of well construction and on the quantity of water required for a particular use. Maximum reported depths are about 400 ft (122 m) and minimum depths are about 50 ft (15 m). The average reported depth is 160 ft (49 m). The deepest wells were drilled to obtain large public and industrial supplies; whereas, most of the shallower wells were drilled to obtain only small domestic supplies.



•



#### Paleozoic Rocks

The Paleozoic rocks are utilized primarily for domestic water supplies in Passaic County. Some of the Paleozoic units such as the Kanouse Sandstone, Green Pond Conglomerate, and Hardyston Quartzite (see figure 3) are locally friable and potentially may yield significant quantities of water to properly located wells. Reported yields of wells tapping the Paleozoic rocks in Passaic County range from less than 1 gal/min to 35 gal/min (.06 to 2 1/s). The median reported yield of 127 wells, almost all of which are domestic wells, is 10 gal/min (.63 1/s). The frequency distribution of these well yields is shown in figure 5.

Depths of wells drilled in the Paleozoic rocks in Passaic County range from about 50 ft (15 m) to 400 ft (122 m). The average depth of 32 selected wells listed in table 2 is 150 ft (46 m).

#### Triassic Rocks

## Brunswick Formation

The Brunswick Formation is the most important aquifer in Passaic County. It is the major source of ground water for public supply and industrial use in the county. Reported yields of 91 public supply and industrial wells range from 20 to 510 gal/min (1 to 32 1/s). The median yield is 130 gal/min 8 (1/s) (see figure 5). The median yield of all public supply and industrial wells over 300 ft (91 m) deep is 190 gal/min (12 1/s), and the yield of the deep wells that are 8 in (203 mm) or larger in diameter is 230 gal/min (15 l/s). The higher yields of the larger diameter wells are in part a result of decreased entrance losses to the well and may in part result from better cleaning and development of the well. Most of the high yielding wells are located in valleys in the more industrial areas, in Hawthorne, Paterson, Clifton and Passaic and are in or on the flanks of preglacial valleys containing comparatively thicker unconsolidated deposits. They are thus located in an environment where recharge to the aquifer may be induced. Smaller yields are generally obtained from domestic wells. The median reported yield of 92 domestic wells is 16 gal/min (1 1/s) (see figure 5). These wells have smaller diameters and are shallower and less developed than the public supply and industrial wells. Most domestic wells are between 150 and 250 ft (46 and 76 m) deep; whereas, most public-supply and industrial wells are between 200 and 400 ft (61 and 122 m) deep.

## Watchung Basalt

The Watchung Basalt is utilized primarily for domestic water supplies in Passaic County. Reported yields of 92 domestic wells range from less than 1 gal/min (.06 1/s) to 40 gal/min (3 1/s). The median yield is 12 gal/min (.76 1/s). Figure 5 shows the frequency distribution of yields of these domestic wells. Reported yields of nine industrial and commercial wells in Passaic County range from 50 to 180 gal/min (3 to 11 1/s). A few wells in adjacent Essex County have reported yields as high as 400 gal/min (25 1/s) (Nichols, 1968).

Depths of wells tapping the Watchung Basalt range from 30 to 600 ft (9 to 183 m). The average depth of 31 selected wells (table 2) is 250 ft (76 m).

## Quaternary Deposits

Stratified deposits of Quaternary age are an important source of ground water for public supply and industrial use in Wanaque and Pompton Lakes and along the western side of Wayne Township. These deposits are major sources of water in adjacent Morris County (Gill and Vecchioli, 1965) and along the Ramapo River in western Bergen County (Vecchioli and Miller, 1974). The deposits in Passaic County have not, for the most part, been extensively explored and are potentially an important source of ground water for future development. Interpretation of the thickness and probable lithology of stratified and unstratified deposits (fig. 4) provides an initial guide to locate probable stratified deposits of sufficient areal extent and thickness to supply suitable quantities of water to wells.

Stratified deposits of Quaternary age generally yield larger quantities of water to individual wells than do the other major geologic units in Passaic County. Reported yields of wells range from 4 to 920 gal/min (.25 to 58 l/s). The frequency distribution of reported yields of 33 public supply and industrial wells and of 47 domestic wells is shown in figure 5. The median yields of the domestic wells are 16 gal/min (1 l/s) and that of the public supply and industrial wells are 130 gal/min (8 l/s).

The maximum depths of wells tapping Quaternary deposits are limited by the thickness of the deposits. Reported depths of 23 wells (table 2) range from 22 to 170 ft (7 to 52 m). Most of the wells are between 50 and 125 ft (15 and 38 m) deep.

## Quality of Water

All natural water contains some impurities. Even rainfall is not chemically pure. It absorbs dust and also gases, such as carbon dioxide, from the atmosphere. Water in passing through the atmosphere and over and through the soil and underlying rocks acquires impurities as either dissolved or suspended matter. The physical and chemical nature of the dissolved or suspended matter determines the natural quality of the water and its suitability for any particular use.

The nature and concentration of impurities in water depend chiefly on the chemical composition of the soils and underlying rocks with which the water comes in contact, and upon the length of time that the water and rock have been in contact with each other. Generally, the longer water remains in contact with the soil and rock, the more dissolved matter it will contain. Suspended matter which consists largely of sediment derived from erosion at the land surface is not an important constituent of ground water.

Man's activities may impair the natural water quality. Disposal of industrial wastes and domestic sewage can pollute water supplies. Water can

also pick up matter that man has added to the environment such as that found in fertilizers, pesticides, and compounds used in snow and ice removal along highways. Dissolved minerals in natural water may be either harmful or beneficial so it is important to know the kind and concentration of minerals in our water supply and how they affect the use of the water.

Chemical constituents most commonly tested for in water are silica. iron, manganese, calcium, magnesium, sodium, potassium, bicarbonate, sulfate, chloride, fluoride, and nitrate. Concentrations of these elements are reported in this report in milligrams per litre (mg/1). Other properties of water that influence its use and degree of treatment are dissolved solids, hardness, specific conductance, pH, and temperature. The chemical composition and physical character of ground-water samples from Passaic County are shown by the results of analyses of samples given in table 3.

Standards of water quality vary considerably according to the intended use. The New Jersey Department of Health (1967) has established standards for maximum concentrations of many constituents in water that are to be used for potable purposes. The recommended maximum concentrations of certain specific chemical substances in New Jersey's potable water-supply systems are listed below:

Constituent	Recommended maximum (milligrams per litre)
	, ,
Chloride (C1)	
Hardness (as CaCO <sub>3</sub> )	0.3
Manganese (Mn)	
Nitrate (NO <sub>3</sub> )	
Sodium (Na)	
Total dissolved solids	

The N.J. Health Department further states that . . "these chemical substances should not be present in a water intended for potable purposes in excess of . . . the listed concentrations. Their presence may constitute grounds for the rejection of the supply if, in the opinion of the Department such substances, either singly or in combination, are present in such concentrations as would render the water unduly corrosive, unpalatable, hazardous to the consumer, or aesthetically objectionable." Most of the naturally occurring ground water in Passaic County is of better quality than the New Jersey potable standards except for high concentrations of iron, hardness, and dissolved solids in some areas.

Excessive concentrations of iron, 0.3 mg/1 or more, cause a reddishbrown staining on laundry and bathroom fixtures and gives the water an astringent taste. Corrosion of metallic surfaces such as copper piping also causes staining; for compounds of copper, it generally leaves a bluish stain.

Soft water and hard water are common terms in describing the quality of water supplies. Very soft water generally causes corrosion of metallic surfaces; whereas, hard water uses excessive amounts of soap in household laundering, also leaves a light scum in wash tubs, and is absorbed into laundered clothing. The hardness of water classification used in this report is as follows:

Hardness description		Range					
	(milli	grams	per	litre)			
Very soft		0	-	30			
Soft		31	~	60			
Moderately hard		61	-	120			
Hard	• • • • • •	121	-	180			
Vores Hond		Mass	a th	an 190			

The hardness of ground water studied in this investigation from all the different aquifers in Passaic County ranged from soft to very hard (34 mg/l to 540 mg/l).

Standards for water quality for industrial uses differ widely. Most industrial processes require water containing no more than 500 mg/l dissolved solids. Almost all the ground water used in Passaic County contains less than 500 mg/l dissolved solids. Water used for cooling may contain more than 500 mg/l dissolved solids, but should have a relatively constant and cool temperature. Temperatures of ground water are nearly constant throughout the year and generally range from about 10° to 15°C (Celsius) in most areas of Passaic County.

The quality of ground water in Passaic County varies considerably from one aquifer to another and from place to place within the same aquifer. These variations can be attributed mainly to (1) differences in the composition of the rocks within the aquifers, (2) the pattern of ground-water movement from recharge to discharge areas, and (3) the length of time water is in contact with the rocks and the depth of water circulation in each aquifer system.

Water from the Precambrian rocks ranges from soft to moderately hard (34 to 104 mg/1) and is low in dissolved solids (66 to 159 mg/1). (See table 3). Chloride concentrations in four samples ranged from 2.4 to 11 mg/1. Most of the water is slightly alkaline with an average pH of about 7.3. The relatively low mineral content of water from the Precambrian rocks is due mainly to the highly resistant nature of the rocks to weathering.

Only one sample of water was obtained from a well penetrating the Paleozoic rocks (Well WM-48). The water quality of this sample is quite similar to that from the Precambrian rocks.

The quality of water from the Quaternary deposits in Passaic County appears to be very good as indicated by the results of the two analyses


(Wells Wn-2 and Wn-8) in table 3. The water is only moderately hard (65 and 83 mg/1) and is low in dissolved solids (122 and 133 mg/1). It ranges from slightly acidic (pH 6.5) to slightly alkaline (pH 7.6). Although supporting data are not presently available, it is believed that the quality of water from the Quaternary deposits is similar to that in the underlying rocks. Hence, less mineralized and softer water would probably be found in the stratified drift underlain by the Precambrian rocks than in the stratified drift underlain by the Brunswick Formation.

The quality of water in the Brunswick Formation differs from that in the other aquifers in Passaic County. It is generally much more mineralized and its quality varies considerably more from place to place. Dissolved solids in 11 samples listed in table 3 range from 129 to 563 mg/l and average 314 mg/l. However, as much as about 16,000 mg/l of dissolved solids have been reported by Cook (1885, p. 116).

In general the water in the Brunswick is less mineralized in the recharge areas at higher altitudes and more mineralized in discharge areas at low altitudes. Figure 6 shows the general relation of altitudes of tops and bottoms of wells to dissolved solids from typical wells in the Brunswick Formation in Passaic County. Well Wn-3 located near Lionshead Lake in northern Wayne Township is at an altitude of 340 ft (104 m) above sea level and has the lowest dissolved solids--129 mg/l. Wells Hw-2, Hw-5, Hw-6, and Hw-7 are located entirely in Hawthorne Borough on the valley flanks of Goffle Brook. Well Ps-3 in the City of Passaic is at the lowest altitude, and the dissolved solids content is over 500 mg/l.

Water from the Brunswick Formation probably becomes more mineralized with increasing depths below land surface. Increasing mineralization of the water with increasing depth was reported as early as 1885 by Cook (1885, p. 115-117) for a test well drilled to a depth of 2,100 ft (640 m) in Paterson, N. J. During drilling of this well, water samples were collected at about 900 ft (274 m), 1,700 ft (518 m) and 2,050 ft (625 m) below land surface and contained about 230 mg/l, 6,000 mg/l and 16,000 mg/l of dissolved solids, respectively. The water at 1,700 ft (518 m) was mostly "sulfate of lime" while the water at 2,050 ft (625 m) was "strongly saline" and contained "408.46 grains per gallon of chloride of sodium" (about 6,900 mg/l of NaCl). This well is located above the present day tidal area of the Passaic River. The highly mineralized water found at depth is not related to present-day salt-water intrusion but, more likely, is characteristic of a residual saline water. Highly mineralized water probably occurs at similar depths elsewhere in the eastern part of the county.

Water from the Brunswick Formation is moderately hard to very hard. The average hardness for 12 of the 13 analyses (one analysis, well C1-12, is discussed separately below) in table 3 is 199 mg/l, and the minimum and maximum values are 89 and 340 mg/l, respectively. As the recommended maximum hardness of potable water by the New Jersey Department of Health is 150 mg/l, much of the ground water from the Brunswick used for potable supplies should be treated to reduce its hardness. The hardness is due mainly to the solution of calcium and magnesium sulfate minerals in the rocks. Gypsum (calcium sulfate), a highly soluble mineral, has been observed in cuttings from wells in the Triassic rocks (Herpers and Barksdale, 1951,



igure 6. -- Relation of dissolved solids to the altitudes of wells tapping the Brunswick formation.

p. 37) and undoubtedly contributes to the hardness of the water.

In some areas, particularly the more industrialized and urbanized parts of the county, the natural quality of water in the Brunswick Formation has been contaminated by man's activities. For example, water from a well in Clifton (Well Cl-12) has been contaminated by industrial waste water from nearby seepage pits. The water contains unusually high concentrations of iron, 25 mg/l; sulfate, 435 mg/l; and hardness, 540 mg/l. This water is acidic (pH 5.9). The low pH, together with a high reported carbon dioxide concentration, make this water excessively corrosive. The exceptionally high concentration of iron in this water is probably due to corrosion of pipes. Although this water is suitable for industrial cooling purposes, it is not suitable for potable supply according to the New Jersey Department of Health Standards. With continued use of this type of highly corrosive water, pipes and other plumbing fixtures would eventually have to be repaired or replaced.

#### WATER USE

Water use in Passaic County from both surface- and ground-water supplies averaged about 106 Mgal/d (million gallons per day) [5 m³/s (cubic metres per second)] in 1965 (N. J. Division of Water Resources, (personal commun., 1969). Of this total, demands for public supply accounted for 76 Mgal/d (3 m³/s); industrial use, 27 Mgal/d (1 m³/s); and irrigation, 3.0 Mgal/d (.13 m³/s). Total per capita use averaged 247 gal/d (gallons per day) [935 1/d (litres per day)]. Because of insufficient data, ground water use for all purposes could not be determined for this report. However, only a very small portion of the County's total requirements is presently derived from ground-water sources; probably between 5 and 10 percent of the total demand.

The major purveyors of surface water for use in Passaic County are: (1) Passaic Valley Water Commission which serves most of the public-supply requirements for Clifton, Little Falls, Passaic, Paterson, Prospect Park, and part of West Paterson; (2) Butler Water Bureau which serves Bloomingdale and Pompton Lakes; (3) Haledon Water Department which serves both Haledon and North Haledon; (4) Newark-Pequannock water systems which serve most of Wayne Township. The major purveyors of ground water for public supply and their monthly and annual pumpage in 1968 are shown in table 1. In 1968, ground-water withdrawals for public supply averaged 4.39 Mgal/d (.19 m³/s). About 80 percent of public supply withdrawals come from wells tapping the Brunswick Formation in Hawthorne and Wayne Townships in the more developed southern part of the county.

Seasonal variations in the total use of ground water can also be seen in table 1. Maximum monthly pumpage for the public supplies averaged about 140 percent greater during July and August 1968 than during February and March.

Table 1.--Use of ground water for public supply in Passaic County, N.J.--1968

(in million gallons per day)

(Data from records of New Jersey Division of Water Resources)

	January	February	March	April	May	June	July	August	September	<u>October</u>	November	December	Annual Average
Hawthorne Water Dept.	2.70	2.79	2.82	3,18	3,26	3.55	3,62	4.19	3.47	3.10	3.09	3.26	3.27
Wanaque Water Dept.	.62	.48	.41	.45	.69	.75	.87	.76	.58	.64	.79	.67	.65
Wayne Twp. Water Dept.	.22	.27	.28	.28	.28	.27	,27	.24	.23	.27	.26	.19	.26
West Milford Twp. Munic. Util. Auth.*	.04	.04	.04	.06	.07	.08	.12	.12	.10	.08	.06	.07	.07
Ringwood Boro (Windbeam Water Co.)	.15	.16	.15	.15 <u>e</u> /	.17 <u>e</u> /	.16 <u>e</u> /	.17 <sup>e/</sup>	.16 <u>e</u> /	.15 <u>e</u> /	.15 <sup>e/</sup>	.15 <sup>e</sup> /	.15 <del>e</del> /	,14 <u>e</u> /
Totals	3.73	3.74	3.70	4.12	4.47	4.81	5.05	5.47	4.53	4.24	4,35	4.34	4.39

e/Fatimared from 1967 data

Ground water, derived from wells, is utilized to some extent in all municipalities in the county. However, in the more suburban and rural areas, almost all water supply is from wells. In these less populated areas, wells are used for industiral, commercial, residential, and rural water requirements. In West Milford Township, for example, ground water is supplied to small communities by about 27 private water companies pumping from about 40 wells. Most of these wells tap aquifers in rocks of Precambrian and Paleozoic age and produce small to moderate quantities of water. Ringwood is supplied by many low yielding wells tapping Precambrian and Quaternary rocks.

Trends in ground-water pumpage by the major public-supply companies from 1951 to 1968 are shown in figure 7. Ground water pumpage has increased from 2.1 Mgal/d (.09  $m^3/s$ ) in 1951 to 4.39 Mgal/d (.19  $m^3/s$ ) in 1968.

Ground water pumpage, as well as total water use, is expected to increase substantially in the next 10 years. Future use will depend largely on an increasing population and an expanding economy. According to the N.J. Division of Water Resources (personal commun., 1969) the total water demand in Passaic County is expected to increase from 106 Mgal/G (5 m³/s) in 1965 to 142 Mgal/d (6 m³/s) in 1980. Public supplies are expected to account for about 70 percent of the total demands. Suburban areas and relatively undeveloped rural areas will show the largest increases in population with corresponding increases in water demands. For example, the population from 1960 to 1969 is estimated to have increased about 62 percent in Wayne Township, 80 percent in Ringwood, and 63 percent in West Milford (N.J. Bureau of Research and Statistics, 1970). In these areas ground water will play an important role in supplying the future water demands of the county.

<sup>\*</sup> Additional unknown quantities of ground water are supplied from about 40 low-producing wells to small communities throughout West Milford Township by about 27 private water




Figure 7. -- Ground-water pumpage by major public-supply companies in Passaic County, 1951-68.

## SUMMARY AND CONCLUSIONS

Passaic County, located in north central New Jersey is shaped roughly like an hour glass with the top to the northwest and the bottom to the southeast. The northwestern two thirds of the county is in the New Jersey Highlands and is underlain largely by gneiss of Precambrian age and an outlier of folded sedimentary rocks of Paleozoic age. The Highlands area is largely developed as a watershed for surface water supply; approximately one quarter of the land area used for this purpose is municipally owned.

The southeastern one-third of the county is in the Piedmont Lowland and is underlain by the Brunswick Formation and the Watchung Basalt of Triassic age. The Brunswick Formation consists of alternating beds of reddish-brown sandstone and mudstone. Conglomerate occurs locally along the northwestern border of the area underlain by the Newark Group and near the base of the lowest Watchung Basalt. The Brunswick Formation forms broad lowlands that are interrupted by First and Second Watchung Mountains and Packanack Mountain which are underlain by Watchung Basalt.

Bedrock in Passaic County is largely concealed beneath unconsolidated deposits genetically related to the continental ice sheets that overran the county during the Wisconsin Stage of the Quaternary Period. These deposits are thin to absent on hills and are thickest in present-day valleys. Maximum known thickness is about 220 ft (67 m) in the valley of the Pequannock River near Pompton Lakes.

Ground water occurs in the intergranular openings of unconsolidated stratified deposits and in joints, fractures, cleavage plans, and faults in consolidated rocks.

Water bearing openings in the Brunswick Formation occur in discrete zones controlled by bedding. The movement of water within these zones is preferentially along strike and hydraulic connection between water-bearing zones is generally poor. The movement of water in the Precambrian and Paleozoic rocks is largely transverse to the regional strike along joints which have been selectively enlarged by weathering.

The Brunswick Formation is the most important aquifer in Passaic County. It is the major source of ground water for public supply and industrial use in the county. Reported yields of public supply and industrial wells range from 50 to 510 gal/min (3 to 32 1/s), and the median yield is 130 gal/min (8 1/s). The median yield of all the public supply and industrial wells, which were drilled to depths of 300 ft (91 m) or greater, is 190 gal/min (12 1/s) and 230 gal/min (15 1/s) for those deep wells which were 8 in (203 mm) or larger in diameter. The deep wells of large diameter probably represent reasonable tests of the maximum yield available for their specific locations. The median reported yield of domestic wells is 16 gal/min (1 1/s). Most domestic wells are 150 to 250 ft (46 to 76 m) deep; whereas, most public supply and industrial wells are 200 to 400 ft (61 to 122 m) deep.

Crystalline rocks of Precambrian age are the major source of ground water for domestic use in the northwestern two-thirds of Passaic County. Reported well yields range from 1 to 200 gal/min (.06 to 13 1/s). The median reported yield of domestic wells is 5 gal/min (.32 1/s) and that of public-supply wells is 30 gal/min (2 1/s). The highest yields are obtained from wells located in the larger valleys near streams or large lakes.

Rocks of Paleozoic age and the Watchung Basalt of Traissic age are utilized primarily for domestic water supplies in Passaic County. Reported yields of wells tapping the Paleozoic rocks range from less than 1 to 35 gal/min (.06 to 2 l/s) and the median yield is 10 gal/min (.63 l/s). Reported yields of domestic wells tapping the Watchung Basalt range from less than 1 to 40 gal/min (.06 to 3 l/s) and the median yield is 12 gal/min (.75 l/s). However, reported yields of nine industrial and commercial wells in the basalt range from 50 to 180 gal/min (3 to 11 l/s), and a few wells in adjacent Essex County have reported yields as high as 400 gal/min (25 l/s).

Unconsolidated stratified deposits of Quaternary age are an important source of ground water for public supply and industrial use in parts of Passaic County. These deposits are major sources of water in adjacent Morris County and in western Bergen County. They have not been extensively explored in Passaic County but are potentially an important source of ground water for future development. Reported yields of wells tapping the stratified deposits range from 4 to 920 gal/min (.25 to 58 l/s). The median reported yield of domestic wells is 16 gal/min (1 l/s) and that of public supply and industrial wells is 130 gal/min (8 l/s). Depths of wells depend upon the thickness of the deposits. Reported depths range from 22 to 170 ft (7 to 52 m).

The quality of ground water in Passaic County varies from one aquifer to another and from place to place within the same aquifer. Water from the Precambrian rocks is soft to moderately hard (34 to 104 mg/l) and is low in dissolved solids (66 to 159 mg/l). Water from only one well tapping the Paleozoic rocks has been analyzed. It is similar in quality to water from the Precambrian rocks. Water from two wells tapping the Quaternary deposits is moderately hard (65 and 83 mg/l) and has dissolved solids contents of 122 and 133 mg/l.

Water from the Brunswick Formation is moderately hard to very hard (89 to 540 mg/l). The hardness is due mainly to solution of calcium and magnesium sulfate minerals (such as gypsum) in the rocks. The dissolved-solids content ranges from 129 to 563 mg/l. More highly mineralized water occurs at depth in the Brunswick Formation. This is indicated by an analysis of water which contained 16,000 mg/l dissolved solids at a depth of 2,050 ft (625 m) in a well in Paterson. In general, water in the Brunswick is less mineralized in recharge areas at higher altitudes and more mineralized in discharge areas at lower altitudes.


Water use from both surface and ground-water supplies in Passaic County averaged about 106 Mgal/d (5 1/s) in 1965. Ground water probably accounts for 5 to 10 percent of this total. Ground-water pumpage by the major public-supply companies in the county has increased from 2.1 Mgal/d (.09 1/s) in 1951 to 4.39 Mgal/d (.19 1/s) in 1968. About 80 percent of the 4.39 Mgal/d (.19 1/s) was from wells tapping the Brunswick Formation in the southern part of the county.


## REFERENCES

- Cook, G. H., 1885, Annual report of the State Geologist for the year 1885: New Jersey Geol. Survey Ann. Rept., 228 p.
- Darton, N. H., 1894, Geologic relations from Green Pond, N. J., to Skunnemunk Mountain, N. Y.: Geol. Soc. America Bull., v. 5, p. 367-394.
- Darton, N. H., Baley, W. S., Salisbury, R. D., and Kümmel, H. B., 1908, Description of the Passaic Quadrangle [New Jersey-New York]: U.S. Geol. Atlas, Folio 157.
- Gill, H. E., and Vecchioli, John, 1965, Availability of ground water in Morris County, New Jersey: New Jersey Dept. Conserv. and Econ. Devel., Div. Water Policy and Supply Spec. Rept. 25, 56 p.
- Herpers, Henry, and Barksdale, H. C., 1951, Preliminary report of the geology and ground-water supply of the Newark, N. J. area: New Jersey Dept. Conserv. and Econ. Devel., Div. Water Policy and Supply Spec. Rept. 10, 52 p.
- Hodgson, R. A., 1961, Regional study of jointing in Comb Ridge-Navajo Mountain area, Arizona and Utah: Bull. Am. Assoc. Petrol. Geol., v. 45, no. 1, 38 p.
- Hotz, P. E., 1953, Magnetite deposits of the Sterling Lake, N. Y., Ringwood, N. J. area: U. S. Geol. Survey Bull. 982-F, p. 153-244.
- James, A. D., 1967, The occurrence of water in the Precambrian crystalline rocks of the New Jersey Highlands: unpublished thesis submitted to the graduate School of Rutgers Univ., 74 p.
- Johnson, M. E., 1950, Revision of Lewis, J. V. and Kümmel, H. B., 1912, Geologic map of New Jersey: New Jersey Dept. Conserv. and Econ. Devel. Atlas Sheet 40.
- Kummel, H. B., and Weller, Stuart, 1902, The rocks of the Green Pond Mountain region: N. J. Geol. Survey Ann Rept. of the State Geologist for 1901, p. 3-51.

- LeGrand, H. E., and Mundorff, M. J., 1952, Geology and ground water in the Charlotte Area, North Carolina: North Carolina Dept. of Conserv. and Devel., Div. of Mineral Resources Bull. 63.
- New Jersey Bureau of Research and Statistics, 1970, 1969 population estimates for New Jersey: Trenton, N. J., New Jersey Dept. Conserv. and Econ. Devel., Div. Econ. Devel., Research Rept. Ser., 10 p.
- New Jersey State Department of Health, 1967, Potable water standards: State of New Jersey, 6 p.
- Nichols, W. D., 1968, Ground-water resources of Essex County, New Jersey: New Jersey Dept. Conserv. and Econ. Devel., Div. Water Policy and Supply Spec. Rept. 28, 56 p.
- Offield, T. W., 1967, Bedrock geology of the Goshen-Greenwood Lake area, New York: New York State Museum and Science Service, Map and Chart Ser. No. 9.
- Rogers, F. C., Lueder, D. R., and Obear, Donald, 1951, Engineering soil survey of New Jersey, Rept. No. 3, Passaic County: College of Eng., Rutgers Univ., Eng. Research Bull. 17.
- Salisbury, R. D., 1894, Surficial geology Report of progress, in Annual Report of the State Geologist for the year 1894: Geol. Survey of New Jersey, p. 1-149.
- 1902, The glacial geology of New Jersey: New Jersey Geol. Survey Final Rept. Ser., v. 5, 802 p.
- Sims, P. K., 1958, Geology and magnetite deposits of the Dover district, Morris County, N. J.: U. S. Geol. Survey Prof. Paper 287, 161 p.
- Smith, B. L., 1969, The Precambrian geology of the central and northeastern parts of the New Jersey Highlands in Geology of selected areas in New Jersey and eastern Pennsylvania and guidebook of Excursion for the Ann. Mtg. of the Geol. Soc. of America: Rutgers Univ. Press, p. 35-47.
- U. S. Weather Bureau, 1959, Climatography of the United States: No. 60-28, 16 p.
- Vecchioli, John, 1967, Directional hydraulic behavior of a fractured-shale aquifer in New Jersey, in International symposium on hydrology of fractured rocks, Yugoslavia 1965, Proc., v. 1: Internat. Assoc. Sci. Hydrology Pub. 73, p. 318-326.
- Vecchioli, John, Carswell, L. D., and Kasabach, H. F., 1969, Occurrence and movement of ground water in the Brunswick Shale at a site near Trenton, New Jersey: U. S. Geol. Survey Prof. Paper 650-B, p. B154-B157.

- Vecchioli, John and Miller, E. G., 1973, Water resources of the New Jersey part of the Ramapo River basin: U. S. Geol. Survey Water-Supply Paper 1974, 77 p.
- Widmer, Kemble, Kasabach, H. F., and Nordstrom, Phillip, 1966, Water Resources Resumé Atlas Sheet No. 23 parts of Bergen, Morris, and Passaic County: New Jersey Geol. Survey Geol. Rept. Ser. No. 10.





REFERENCE NO. 4

## PRELIMINARY ASSESSMENT OFF SITE RECONNAISSANCE INFORMATION REPORTING FORM

-
P TDD: 02-8904-65
[ ROAD
-
<b>-</b>
_
Discipline
METEOROLOGIST
ENTROUMENTAL SIEN
etc.):
Colm
<del></del>

Date: 5/9/81	
Site Name: SERVOMETER CORP	TDD: 07-8904-65
Site Sketch:	
Indicate relative landmark locations (streets, Provide locations from which photos are take	, buildings, streams, etc.).
·	
Roll Rolling	Treed
50T (52855)	
D Church	<b>@</b>
LITTLE FALLS TOA	D ,
Signature: Dulp Solution	Date: 5 9/89
Countersigned: 1	Date: 5/1/89

Date:
Site Name: SERVINETER CORP TDD: 02-8904-65
Notes (Periodically indicate time of entries in military time):
1425 amire at sete
- Site is active
- Site is not fenced
- surrounding properties covered
with vegetation (trees)
- No signs of stressed vegalation
1430 - Pictur 183 +153 Caken, 184 + 184
- Cerea of site is flat slight slope
L 3% Lown towards river
- Distinct oder of sewage em coming
from siver
- deschange sipe not visible
from road
1435 - Cheif Experations is curioto about
our presence Atis explained that
we work for EPA as subcontrato
J. Mayo gives business cand also gives an Comy Brochu's or name a context.
gives an Comy Brochu's or name a
Contact.
Signature: Philipsolith. Date: 5/9/89
Signature: Date: 5/9/89  Countersignature: Date: 5/18/89

Date: 5/9/89	
Site Name: SERVOMETER	TDD: 02-8904-65
Notes (Cont'd):	
1438 Prietre of	Deckman River
taken looke	peckman River ing Douth, Diveris from road. Priver south to north
not visible	from road. River
flows from	south to north
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
	\
Attach additional sheets if necessary. Pro	ovide site name, TDD number, signature,
and countersignature on each.	e alalao.
Signature: The Solit	Date: <u>\$79/89</u>
Countersignature:	Date:

Date: 5/9	/89		
Site Name: SERVON	ETER CO	RP TDD: _	52-8904-65
Photolog:			
Frame/Photo Number Date	Time	Photographer	Description
15-3/1P-3 5/9/8	1 1430	P. SOLINSKI	looking southers
15-4/1P-4 5/9/8	7 1431	P-SOLINSY	looking east at
15-5/18-5 5/9/8	<u>1438</u>	P. SOLINGE	dranage path looking south
	-		<u>at Peckman</u> <u>Piver</u>
	_		
<del></del>			
	_		
Attach additional sheet: and countersignature on	• .	Provide site name,	TDD number, signature,
	each.		-1-150
Signature: Duly	Jolet	Date: _	5/9/59
Countersignature:	May	Date: _	5/18/89

REFERENCE NO. 5

Date: ————	
Company	
Ву: ————	
Date: ————	
Contractor	
Ву:	
Date: —	
[FR Doc. 84-1452 Filed 1-23-84; 8:45 am]	
BILLING CODE 4500-50-MIA%	· ·

#### [OW-FRL-2460-3]

Brunswick Shale and Sandstone Aquifer of the Ridgewood Area, New Jersey; Final Determination

AGENCY: U.S. Environmental Protection Agency.

ACTION: Notice.

SUMMARY: Pursuant to Section 1424(e) of the Safe Drinking Water Act, the Administrator of the U.S. Environmental Protection Agency (EPA). has determined that the Brunswick Shale and Sandstone Aquifer, underlying the Ridgewood Area, is the sole or principal source of drinking water for Ridgewood, Midland Park, Glen Rock, and Wyckoff. New Jersey, and that the aquifer, it contaminated, would create a significant hazard to public health. As a result of this action. Federal financially assisted projects constructed in the Ridgewood Area and its streamflow source zone (upstream portions of Ho Ho Kus Brook and Saddle River Run drainage basins) will be subject to EPA review to ensure that these projects are designed and constructed so that they do not create a significant hazard to public health.

ADDRESSES: The data on which these findings are based are available to the public and may be inspected during normal business hours at the U.S. Environmental Protection Agency. Water Supply Branch. 26 Federal Plaza, New York, New York 10278.

FOR FURTHER INFORMATION CONTACT: Damina J. Duda, Water Supply Branch, 26 Federal Plaza, New York, New York 10278 (212) 284–1800.

SUPPLEMENTARY INFORMATION: Notice is hereby given that pursuant to Section 1424(e) of the Safe Drinking Water Act (42 U.S.C., 300f, 300h-3(e), Pub. L. 93-523), the Administrator of the U.S. Environmental Protection Agency (EPA) has determined that the Brunswick Shale and Sandstone aquifer of the Ridgewood Area is the sole or principal source of drinking water for Ridgewood. Midland Park, Glen Rock, and Wyckoff, New Jersey. Pursuant to Section 1424(e). Federal financially assisted projects constructed in the Ridgewood Area and its streamflow source zone (upstream portions of Ho Ho Kus Brook, and

Saddle River Run drainage basins) will be subject to EPA review.

## I. Background

Section 1424(e) of the Safe Drinking Water Act state:

(e) If the Administrator determines....... his own initiative or upon petition, that has an aquifer which is the sole or pa cipal drinking water source for the area and which, if contaiminated, would create a significant hezard to public health, he shall publish notice of that determination in the Federal Register. After the publication of any such notice, no commitment for Federal financial assistance (through a grant, contract, loan guarantee, or otherwise) may be entered into for any project which the Administrator determines may contaminate such aquifer through a recharge zone so as to create a significant hazard to public health, but a commitment for Federal financial assistance may, if authorized under another provision of law, be entered into to plan or design the project to assure that it will not so contaminate the aquifer.

On July 4, 1979, the Committee to keep Our Water Pure petitioned EPA to designate the Brunswick Shale and Sandstone Aquifer of the Ridgewood Area as sole source aquifer. On January 15, 1980, EPA published a notice in the Federal Register announcing a public comment period and setting a public hearing date. A public hearing was conducted on February 28, 1980, and the public was allowed to submit comments on the petition until March 28, 1980.

#### 11. Basis for Determination

Among the factors to be considered by the Administrator in connection with the designation of an under Section 1424(e) are: (1) Whether the aquifer is the area's sole or principal source of drinking water, and (2) whether contamination of the aquifer would create a significant hazard to public health.

On the basis of information available to this Agency, the Administrator has made the following findings, which are the basis for the determination noted above:

- 1. The Brunswick Shale and Sandstone Aquifer of the Ridgewood Area is the "sole source" of drinking water for the approximately 68,820 residents of Ridgewood, Midland Park, Glen Rock, and Wyckoff, New Jersey.
- 2. There is no existing alternative drinking water source or combination of sources which provides fifty percent or more of the drinking water to the designated area.
- 3. The Brunswick formation is a soft red shale interbedded with coarse grained sandstone. The aquifer is overlain by permeable unconsolidated glacial and recent deposits. As a result

of permeable soil characteristics, the Brunswick Shale and Sandstone Aguifer of the Ridgewood Area is highly susceptible to contamination through its recharge zone from a number of sources. including but not limited to, chemical spills, leachate from landfills, stormwater runoff, highway deicers, faulty septic systems, wastewater treatment systems, and waste disposal lagoons. The aquifer is also susceptible to contamination to a lesser degree from the same sources, through its streamflow source zone. Since ground water contamination can be difficult or impossible to reverse and since the aquifer in this area is solely relied upon for drinking water purposes by the population of the Ridgewood Area. contamination of the aquifer could pose a significant hazard to public health.

III. Description of the Brunswick Shale and Sandstone Aquifer of the Ridgewood Area, Its Recharge Zone and Its Streamflow Source Zone

The Brunswick Shale and Sandstone Aquifer is a soft red shale interbedded with coarse grained sandstone. The formation, located in northern New Jersey, is fairly large, extending south into Pennsylvania and north into New York, Igneous intrusions which form the Watchung Mountains and the Palisades. also form the western and eastern boundaries of the Burnswick formation. respectively. The area in which Federal financially assisted projects will be subject to review is the portion of the Brunswick Shale and Sandstone Aquifer in the Ridgewood Area, its streamflow source zone, and its recharge zone.

For the purposes of this designation. the Brunswick Shale and Sandstone Aquifer of the Ridgewood Area is considered to include the entire municipalities of Ridgewood, Midland Park, Glen Rock, and Wyckoff, New Jersey. It's recharge zone is considered to be one and the same with this area. The streamflow source zone is that portion of the drainage basins of Ho Ho Kus Brook and Saddle River Run located upstream of the Ridgewood area. This includes all or a portion of the following New Jersey municipalities: Waldwick, Allendale, Ramsey, Mahwah, Franklin Lakes. Ho Ho Kus. Saddle River, Upper Saddle River, Woodcliff Lake, Hillside, Washington, Montvale, as well as Ramapo Township, New York.

# IV. Information Utilized in Determination

The information utilize in this determination includes the petition, written and verbal comments submitted by the public, and various technical publications. The above data is

available to the public and may be inspected during normal business hours at the U.S. Environmental Protection Agency, Region II. Water Supply Branch, 28 Federal Plaza, New York, New York 10278.

## V. Project Review

EPA Region II is working with the Federal agencies that may in the future provide financial assistance to projects in the area of concern. Interagency procedures have been developed through which EPA will be coulied of proposed commitments by Federal .7 agencies for projects which could contaminate the Brunswick Shale and Sandstone Aquifer, upon which the Ridgewood Area is dependent for its sole source water supply. EPA will evaluate such projects and, where necessary, conduct an in-depth review. 71 including soliciting public comments where appropriate. Should the Administrator determine that a project ' may contaminate the aquifer through its recharge zone so as to create a significant hazard to public health, no commitment for Federal financial assistance may be entered into. However, a commitment for redera financial assistance may, if authorized under another provision of law. be entered into to plan or design the project to assure that it will not so contaminate the aquifer.

Although the project review process cannot be delegated, the U.S. Environmental Protection Agency will rely to the maximum extent possible on any existing or future State and local control mechanisms in protecting the ground water quality of the Brunswick Shale and Sandstone Aquifer on which the Ridgewood Area is dependent for its sole source water supply. Included in the review of any Federal financially assisted project will be coordination with the State and local agencies. Their comments will be given full consideration and the Federal review process will attempt to complement and support State and local ground water protection mechanisms.

# VI. Summary and Discussion of Public Comments

Most comments were generally in favor of designation. Two local governments submitted resolutions in support of designation. Only two commenters expressed any reservations regarding the designation.

One commenter expressed concern that the proposed designation would provide protection which is duplicative of State and local controls and may lead to unnecessary bureaucratic delays of

REFERENCE NO. 6

NUS CORPORATION		TELECON NOTE
CONTROL NO: 07-5904-65	DATE: 5/10/89	TIME: 1145
DISTRIBUTION:	NOMETER CORP	
	FILE	
BILL KOWACSKI	OF: TOWNSHIP OF CEDAR GROVE ENGINEERING OF	PHONE: (201) 239/40
P. Soli		(NUS)
DISCUSSION:	sources for	CEDAR GROVE
He Slated	that 80% of a	Water comes
from the Mon from Possiaes	th Jersey Water (	ommisser and
10% NJ amer	ican Supply.	all of these
Knowsof no	external fre	on Cedar From use
from for dri	nking Olse &	tated that the
is owned by	Newark.	(leservon
ACTION ITEMS:		


REFERENCE NO. 7


# Uncontrolled Hazardous Waste Site Ranking System

A Users Manual (HW-10)

Originally Published in the July 16, 1982. Federal Register

United States Environmental Protection Agency








TABLE 2
PERMEABILITY OF GEOLOGIC MATERIALS\*

Type of Material	Approximate Lange of Bydraulic Conductivity	Assigned Value
Clay, compact till, shale; unfractured metamorphic and igneous rocks	<10 <sup>-7</sup> cm/sec	0
Silt, losss, silty clays, silty loss, clay loss; less permeable limestons, dolomites, and sandstons; moderately permeable till	10 <sup>-5</sup> - 10 <sup>-7</sup> cm/sec	1
Fine sand and silty sand; sandy loams; loamy sands; moderately permeable limestone, dolomites, and sandstone (no karst); moderately fractured igneous and metamorphic rocks, some coarse till	10 <sup>-3</sup> - 10 <sup>-5</sup> cm/sec	2
Gravel, sand; highly fractured igneous and metamorphic rocks; permeable basalt and lavas; karst limestone and dolomite	>10 <sup>-3</sup> cm/sec	3

## \*Derived from:

Davis, S. N., Porosity and Permeability of Natural Materials in Flow-Through Porous Media, R.J.M. DeWest ed., Academic Press, New York, 1969

Freeze, R.A. and J.A. Cherry, Groundwater, Prentice-Hall, Inc., New York, 1979

#### TABLE 12

#### INCOMPATIBLE MATERIALS

In the lists below, the mixing of a Group A material with a Group B material may have the potential consequence as noted.

Group 4-A Group 1-B Group 4-B Group 1-A Alcohols Acid sludge Concentrated Group 1-A Acetylene sludge Aldehydes or 1-B wastes Acid and water Akaline caustic liquids Battery acid Halogenated hydrocarbons Group 2-A wastes Alkaline cleaner Nitrated hydrocarbons Chemical cleaners Alkaline corrosive liquids Unsaturated hydrocarbons Electrolyte acid Alkaline corrosive battery fluid Etching acid liquid Other reactive organic Caustic wastewater compounds and solvents Lime sludge and other or solvent Pickling liquor and other corrosive alkalies Lime wastewater corrosive scids Potential consequences: Fire, explosion, or violent reaction. Spent acid Lime and water Spent mixed acid Group 5-A Group 5-B Spent caustic Spent sulfuric acid Spent cyanide and sulfide Group 1-B wastes Potential consequences: Heat generation; violent reaction. solutions Potential consequences: Generation of toxic hydrogen cyanide or Group 2-B Group 2-A hydrogen sulfide gas. Any waste in Group 1-A or 1-B Aluminum Berylium Croup 6-A Group 6-8 Calcium Chlorates Acetic acid and other Lithium Chlorine organic acids Potessium Chlorites Concentrated mineral acides Sodium Chromic acid Group 2-A wastes Zinc powder Other reactive metals and Hyphochlorites Group 4-A wastes Other flammable and Nitrates metal hydrides Nitric acid, fuming combustible wastes Potential consequences: Fire or explosion; generation of flamable Perchlorates Permangapates hydrogen gas. Peroxides Other strong oxidizers Group 3-A Group 3-B Potential consequences: Fire, explosion, or violent reaction. Alcohols Any concentrated waste in Groups 1-A or 1-B Water Calcium Lithium Metal hydrides Potassium \$02C12, \$0C12, PC12. CH3, SIC13 Other water-reactive waste

Potential consequences: Fire, explosion, or heat generation; generation of flammable or toxic gases.

Source: Hazardous Waste Management Law, Regulations, and Guidelines for the Handling of Hazardous Waste. California Department of Health, Sacramento, California, February 1975.

## REFERENCE NO. 8

SUBJECT TO REVISION

WATER WITHDRAWAL POINTS AND NJGS CASE INDEX SITES WITHIN 5.0 MILES OF:

LATITUDE 404858 LONGITUDE 741127

## DRAFT

CALE, 1:63,360 Inch = 1 Mile)

MATER WITHDRAWAL POINTS

NIGS CASE INDEX SITES


NILE AND 5 MILE RADI INDICATED

nigs case index data retrieved from: New Jersey Geological Survey On 12/22/87

PLOT PRODUCED BY:

MJOEP DMISION OF WATER RESOURCES BUREAU OF WATER ALLOCATION CN-029 TRENTON, NJ 08625

DATE: 06/25/88



ranaatt	1-1 <del>-12</del> M1)	%i≰#41.117	11411	1	1 1 4 4	1-1-1-1-1	Of delication	દિવસીનું દ	i-p k-j	1417111	to a contract	er to effect to
5010	在感见关于民主员 自城集中员	4. 2.47.47	4	and the	11 11		ı	, ,	15.			n a 2
, Lie . 7	PUNTOLATE UNIT LITTE	48400163	1	4.1: 21	41 7161	+ 1		1. 7		Salar I	411.4	
17250917	(武士) 主国的 知為工作場(	HEAMONE EL		40 8.36	118.40	11	4			Seq 4	1.15.0	
2018 d	PONTCLAIR COLF CLOB	4.400150	4	44.14 产品 t	Historia	1.	C	1 .	1	7 2 7	. (1.)	
531.155	ESSEX FELLS: TOMESHIP	1.54.0(T.M)		diam's	41647	f*	İ,		2.1	0.7	La Say	: 1:
5339	RANDAY, CITY OF	HAMMAY KINDIS		404771	741639		4.7	27.	1 .		. 15.7	6171
ON WE	ESSEX CLUNTY, DEPT. OF FARIS	(金融)(45)	1	46417, 0	Alterty	£3	4.3	1.1			1.11 00	1.54
## (FS_	ESSEX COUNTY COUNTRY OLUM	Pr <b>斯</b> 提)		4414-615	4111515	!	41	1:			- 1	
72563F	ESSEX COUNTY HUSPITTAL CENTER		143	4014017	4141.4		1 1	:	614	vij	triffs.	1.0
2353P	ESSEX COUNTY HOSPITAL CENTER \	264046349	~y!	HAY ACT OF	241456		+ 4	1.5	$\{1.1\}$	25.24	64Hb	f a t
2005/3P	ESSEX COUNTY HOSPITAL CENTER	46/02613	ម	407.45	7414(3)			1.1	63-1	24.45	Cilliti	1.5
2563F	ESSEX COUNTY HUSPITAL CENTER	45 <b>x</b> 02612	7	468 635	44453		57	1.5	L 1-}	100	lalle:	100
5AJ27	ONANGE CITY	2643,9440	7	10 10 -	141111	. •	4	1	6.3	11.4	14117	t at a
5077	CRANCE CITY	2614444	13	404.51	41.45	F	- 2	1.5	1.7	(d <sub>e</sub> )	contact	4. it :
ラック	HASSAIC VALLEY WATER COMM.	LITTLE FRATS		400000	741.540		-1	* L	G.		Walter .	
53207.7	ORANGE CITY	ICM/4/52/2	8	<b>40</b> 4545	741.50		5 4	1.5	! '	4.4 :	144.0	, 1 <sub>1</sub> ,
101561W	HA-INE'S	26/00/11/18	2	404E	41312		1 .	ł	į	247	1111	1
≥184F	MUMIAINGIDE HOSPITAL	2804827	1.3	<b>40</b> 4900	41.4.7		i i	1.5	1 :	41/4 1	tile).	4 1
5245	MONICLAIR TOWN	1403466	GLINFLID #22	<b>404</b> E51	241548		11	1.5	1 '	11, 876	organists.	1.6.7
5245	MONTCLAIR TOWN	26414687	RAND W. #1	<b>40</b> 4822	7411257		Ī	1 .		493	( - H ( t	it an
#in: 155	MUNICLAIR TOWN	26 <b>/2</b> 4597	LURFAINE 3	405.035	741237		٠.١	1 1	į.	1; n 1	File Disc	F( .1l
2184	MOUNTAINGIDE HOSE1174	26 <b>x</b> 222396	1	404845	741218		Ø.G	1.5	1.5	-4 <b>k</b> )	Lillyn	i di I
5260	GLEN RIDGE WATER DEFT.	28.04827	2	40.46417	741210		Ø. /	1.5	1(k.)	4000	trajeta	$\mu$ $\mu$
2:67F	GLEN RIDGE COUNTRY CLUB	2604134	2	404975.	741145			1 !	(1)	la;1 <b>4</b> (1)	ित्तानः	. (
23357P	GLEN RIDGE COUNTRY CLUB	4600168	.3	4047.45			19.10		ιάς.	Auto)	(iller	14.
1226/F	G EN RIDGE CONTRY CLUB	28401652	1	40417 11	741137			1.1	£1.	0.3	(4)/201	ert kur
5129 5129	ELOUPFIELD TOAN	26434763	1	466686	741 1 TA3		1.1	1	6.2	a, d, t	(71)-1-1	* *
20436	NATIONAL STARCH & CHEMICA	2804514	1	464733	ANTICE.		1	1 :	0.7	like	trii-tr	i
0.52656111 10000000	FOREST HALL FIELD CLUB	PUND	i	404749 404749	741 (#51 741 (#51		1!	1	11	1.1	+ 4	r P
25.866+ 25284.5	OFFER MONTOLAIR COUNTRY CLUB	125 <b>0</b> 40/54 FOND		Attinuitie)	741041 741040		1	1 .	ul.	2.5	4 ejs is	8.0
	OFFER MONICLAIR COUNTRY CLUB	12404 390	44 25	46.00.00	741040 741035	i			t, i, i	1	11.50	17
2241	ULTER MONTGLAIR COUNTRY (2.11)	2801129	Ĺ	HET MET	741th 55			1 .	ig≹iri ark	ara Mad	r sejet	. ,
2.61	U-EFR MONICLAIR COUNTRY LLUR	2604805		405-41-41	7410.0	1		· • •	į, i	ni ur Naka	13444	
127777	HOLEMANN-LAROCHE INC.	46000156	3	460 4715	24 <b>0</b> 0227		. 1. 1	1		of an	orida	$A_{-k}$
22530	HOFFMAN LAROCHE INC.	48200155	્રાયા	467 (304)	740119			1.		ALS.	tollett	1. F
22339	HUFFMANN-LAROCHE INC.	-1340611577	5.3	HET ARES	2441/15		, 4	11	et.	FW 7 A	GHA.	
21.539	FUFFMANN-LARDOHE INC.	46 <b>/201</b> 5/8	3.2	-102-45252-3	7400A37				65.	11.50	GIM.	1. 1
207 3	THURANGUIONAL MINERALS & CHUN.	4640000172	1	46147000	74(3).(35)			1	(i)		bild	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
20/20-	INTERNATIONAL MINERALS & CLEM.	462000773		4614 (16)	740°-00			i	150		rais.	***
1.107.34	INTERNATIONAL MINERALS & CLIMA.	06051 E3	3	444 (44	41677647	i	1	1.1	4. 1 -		cilian	1
2351F	FERFIZCHE DODGE & OLOGOT	SEATA FEE	0	47	1466 615	1)	1.4	1.1	U.		1.414	
SM:F	THE AVIONICS DIVISION	58411834	1	4647.0	44000,44	1	4	(			++11	1.1
af∂1 č#1	III AVIONICS DIVISION	13504635	4	-1.44°. at 1	74(*), <b>1</b> 9			1:	1			6.
3013	ITT AVIONICS DIVISION	24411 Set )	4.	4041 0	1464), M			f :	1.			, * a
2001 (EF)	THE APPROPRIES DIVISION	,34(44)-,91,5	4 4 4 4 (	404 717	740840			1 1	:	241		£ % .
1651144	MUH. SWEISON CO., INC.	5 oB27717	1	406. 235	*46% 84°2	į	1		4.4	t's ·	. 1. 1	1.0
GL(X)	MALL DAG FOR TALEOURA	46.40(00)/20			7407.6		1.				1 - 1 - 1 -	4.0
54545	WAS LIBRUIT ON TRUNCOUGH	*1 : 4:0(Ap) : -1	53	462-15			1			ri I.	1	*
1.77	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	1、《集集集》	• •		240.000			· i	-		11.14	
SMAY 11	(37)公司基本证明 (3)第二十四分日本(4)	ke distribution in	*	Herritia	101-516			t		* * *	661	
	Francisco Company Comp	िर्वाद के स्वीर		Altro, Obs	· JET -j <sup>r</sup> s		1.75	1.1			11.	
: 104-H	(14)公司(1) (并打(利)(3)。	រស់ជាជាជា ស		0.175	Her See					" 1		i i
0.2464	Frankling (Marketter) (Frankling)	5.44 - 6.2	1	Harry Fra	The r	1 1		•				4.4

## DESCRIPTION OF WATER WITHDRAWAL POINTS

The Water Withdrawal Points listing contains the following fields:

CAPACITY: the pump capacity in gallons per minute

COUNTY: county the withdrawal point is in

DEPTH: depth of the well or pond

DISTANCE: distance in miles from center of circle

GEO1: the ground or surface water source GEO2: a secondary source of the water LAT: latitude of the withdrawal point

LLACC: accuracy of the latitude and longitude estimates LOCID: the local identification of the withdrawal point,

or a continuation of the SOURCEID field for surface water

LON: longitude of the withdrawal point

MUN: the municipality the withdrawal point is in

NAME: name of the permit, certificate, or registration holder NUMBER: Water Allocation permit, Agricultural Certification, or

Registration number

SOURCEID: the well permit number or other identifier for

the water withdrawal

The listing that you have requested includes most wells and surface intakes that are in the Water Allocation Permits, and representative sources from most of the Agricultural Certificates. Recognizing the fact that the list will contain errors and omissions, it is advisable to use this resource as a quide and to verify all data. We try to maintain an accurate database; however, we can not yet guarantee reliability. If you spot any errors we would be very grateful to hear about them. Please call or write to us in reference to the "Radius Program" at:

NJDEP
Division of Water Resources
Bureau of Water Allocation
CN-029
Trenton, NJ 08625

(609) 292-2957

Thank you.

Please see the attached sheets for definitions of the codes used in the Water Withdrawal Points listing.

## CODES USED IN THE WATER WITHDRAWAL POINTS LISTING

This packet contains information on the database codes that the Bureau of Water Allocation uses in the Water Withdrawal Points Listing.

COUNTY:	03 - Bergen 05 - Burlington 07 - Camden 09 - Cape May 11 - Cumberland	15 - Gloucester 17 - Hudson 19 - Hunterdon 21 - Mercer 23 - Middlesex 25 - Monmouth 27 - Morris	31 - Passaic 33 - Salem 35 - Somerset
GEO:	RECENT Surficial Depos	its	GRS
	PLEISTOCENE Glacial Undiffer Stratified Drift Terminal Morains Bridgeton Cape May Holly Beach Estuarine S Pennsauken  TERTIARY Beacon Hill Cohansey Cohansey & Kirk Kirkwood Upper Rio Grande Lower Piney Point Shark River Mar Manasquan Marl Vincentown Sand Hornerstown Mar  CRETACEOUS	tee  Mbr. and  Wood  Mbr.	GQGU GQSD GQTM GQBS GQCM GQCHB GQES GQPS  GTBH GTCH GTCK GTKW GTKWU GTKRG GTKWL GTKPP GTSR GTMQ GTVT GTHT
	Red Bank Navesink Mount Laurel Wenonah Mount Laurel & Marshalltown Englishtown Woodbury Merchantville Magothy	Wenonah	GKRB GKNS GKML GKWE GKMW GKMT GKET GKWB GKMV

Old Bridge Raritan Sayreville Sand Farrington Raritan/Magothy Potomac	GKROB GKR GKRSS GKRF GKMR GKP
TRIASSIC  Brunswick Formation  Lockatong Formation  Stockton Formation  Basalt	GTRB GTRL GTRS GTRBS
Diabase Conglomerate	GTRDB GTRCG
DEVONIAN Undifferentiated	GD
SILURIAN	
Bossardville Limestone	GSBD
Decker Formation Longwood Shale	GSDK GSLS
Poxono Island Fm	GSLS
Greenpond Conglomerate	GSGP
High Falls	GSHF
Shawangunk Fm	GSSG
ORDOVICIAN	
Martinsburg Fm	GOMB
Jacksonburg Fm	GOJB
Kittatinny Group	GOK
Outleaunee Fm Harmonyvale Mbr	GOKO GOKOH
Beaver Run Mbr	GOKOB
Epler	GOKE
Rickenbach	GOKR
CAMBRO ORDOVICIAN	
Kittatinny Fm	GCOK
CAMBRIAN	
Hardyston Quartzite	GCH
Allentown Fm	GCKA
Upper Mbr	GCKU
Limeport Mbr	GCKLP
Leithsville Fm Walkill Mbr	GCKL GCKLW
Hamburg Mbr	GCKLH
Califon Mbr	GCKLC
PRECAMBRIAN	
Granite	GPCGR
Gneiss	GPCGN
Undifferentiated	GPC

Franklin Lms	GPCFL
DELAWARE RIVER BASIN	
Unknown or Non-Specific	SD
Alloways Creek	SDALL
Alexsocken Creek	SDALE
Assiscunk Creek	SDASC
Assunpink Creek	SDASP
Big Timber Creek	SDBIG
Blacks Creek	SDBLA
Cooper's Creek	SDCOO
Crafts Creek	SDCRA
Crosswicks Creek	SDCRO
Delaware River	SDDEL
Flat Brook	SDFLA
Hakihokake Creek	SDHAK
Harihokake Creek	SDHAR
Jacob's Creek	SDJAC
Lockatong Creek	SDLOC
Lopatcong Creek	SDLOP
Mantua Creek	SDMNT
Musconetcong River	SDMUS
Nichisakawick Creek	SDNIC
Old Man's Creek	SDOLD
Paulins Kill	SDPAU
Pennsauken Creek	SDPEN
Pequest River	SDPST
Pohatcong Creek	SDPOH
Raccoon Creek Rancocas Creek	SDRAC SDRAN
Salem River	SDSAL
Wickecheoke Creek	SDWIC
wickecijeowe cieew	SDWIC
RARITAN RIVER BASIN	
Unknown or Non-Specific	SR
Lawrence Brook	SRLAW
Lower Raritan	SRLOW
Millstone River	SRMIL
North Branch Raritan	SRNBR
South Branch Raritan	SRSBR
South River	SRSRV
PASSAIC RIVER BASIN	
Unknown or Non-Specific	SP
Canoe Brook	SPCAN
Lower Mid-Passaic River	SPLMP
Lower Passaic	SPLOW
Passaic River	SPPAS
Peckman River	SPPEC
Pequannock River	SPPNK
Pompton River	SPPOM
Ramapo River	SPRAM
Rockaway River	SPROC
Saddle River	SPSAD

Upper Mid-Passaic River Upper Passaic River Wanaque River Whippany River	SPUMP SPUPP SPWAN SPWHI
ATLANTIC COASTAL BASIN  Unknown or Non-Specific Atlantic County Coastal Cape May County Coastal Cedar Creek Great Egg Harbor River Manasquan River Metedeconk River Monmouth County Coastal Mullica River Navesink River Ocean County Coastal Raritan Bay Shark River Shrewsbury River Toms River Tuckahoe River	SC SCATL SCCAP SCCED SCGRE SCMSQ SCMET SCMON SCMUL SCNAV SCOCE SCRAR SCSHA SCSHA SCSHA SCSHR
HUDSON RIVER BASIN Unknown or Non-Specific Hudson River Papakating Creek Pochuck Creek Wallkill River	SH SHHUD SHPAP SHPOC SHWAL
HACKENSACK RIVER BASIN Unknown or Non-Specific Hackensack River	SK SKHAC
RAHWAY RIVER BASIN Unknown or Non-Specific ' Rahway River	SY SYRAH
ELIZABETH RIVER BASIN Unknown or Non-Specific Elizabeth River	SE SEELI
DELAWARE BAY BASIN Unknown or Non-Specific Cohansey River Maurice River Stow Creek	SB SBCOH SBMAU SBSTO
S - accurate to +- 1 second F - accurate to +- 5 seconds T - accurate to +- 10 seconds M - accurate to +- 1 minute U - accuracy unknown	

LLACC:

MUN:  ATLANTIC COUNTY (01)  01 - Absecon City  03 - Brigantine City  05 - Buena Vista Twp  07 - Egg Harbor City  09 - Estell Manor City  11 - Galloway Twp  13 - Hammonton Town  15 - Longport Boro  17 - Mullica Twp  19 - Pleasantville City  21 - Somers Point City  23 - Weymouth Twp	02 - Atlantic City 04 - Buena Boro 06 - Corbin City 08 - Egg Harbor Twp 10 - Folsom Boro 12 - Hamilton Twp 14 - Linwood City 16 - Margate City 18 - Northfield City 20 - Port Republic City 22 - Ventnor City
BERGEN COUNTY (03)  01 - Allendale Boro  03 - Bergenfield Boro  05 - Carlstadt Boro  07 - Closter Boro  09 - Demarest Boro  12 - East Rutherford Boro  11 - Elmwood Park Boro  15 - Englewood City  17 - Fair Lawn Boro  19 - Fort Lee Boro  21 - Garfield Boro  23 - Hackensack City  25 - Hasbrouck Heights Boro  27 - Hillsdale Boro  29 - Leonia Boro  31 - Lodi Boro  33 - Mahwah Twp  35 - Midland Park Boro  37 - Moonachie Boro  39 - North Arlington Boro  41 - Norwood Boro  43 - Old Tappan Boro  45 - Palisades Park Boro  47 - Park Ridge Boro  49 - Ridgefield Boro  51 - Ridgewood Village  53 - River Vale Twp  55 - Rockleigh Boro  57 - Saddle Brook Twp  59 - South Hackensack Twp  61 - Tenafly Boro  63 - Upper Saddle River Boro  65 - Wallington Boro  67 - Westwood Boro  69 - Woodcliff Lake Boro	02 - Alpine Boro 04 - Bogota Boro 06 - Cliffside Park Boro 08 - Cresskill Boro 10 - Dumont Boro 13 - Edgewater Boro 14 - Emerson Boro 16 - Englewood Cliffs Boro 18 - Fairview Boro 20 - Franklin Lakes Boro 21 - Glen Rock Boro 22 - Glen Rock Boro 24 - Harrington Park Boro 25 - Hohokus Boro 26 - Haworth Boro 27 - Lyndhurst Twp 28 - Montvale Boro 29 - Montvale Boro 20 - Northvale Boro 20 - Ridgefield Park Village 21 - Oakland Boro 22 - Oakland Boro 23 - Ridgefield Park Village 24 - Oradell Boro 25 - Ridgefield Park Twp 26 - Rutherford Boro 27 - Rutherford Boro 28 - Saddle River Boro 29 - Teterboro Boro 20 - Teaneck Twp 21 - Teterboro Boro 22 - Washington Twp 23 - Wyckoff Twp
BURLINGTON COUNTY (05) 01 - Bass River Twp 03 - Bordentown City	02 - Beverly City 04 - Bordentown Twp

05 - Burlington City	06 - Burlington Twp
07 - Chesterfield Twp	
09 - Delanco Twp	08 - Cinnaminson Twp
	10 - Delran Twp
11 - Eastampton Twp	12 - Edgewater Park Twp
13 - Evesham Twp	14 - Fieldsboro Boro
15 - Florence Twp	16 - Hainesport Twp
17 - Lumberton Twp	18 - Mansfield Twp
19 - Maple Shade Twp	20 - Medford Lakes Boro
21 - Medford Twp	22 - Moorestown Twp
23 - Mount Holly Twp	
25 - Novi Handrey The	24 - Mount Laurel Twp
25 - New Hanover Twp	26 - North Hanover Twp
27 - Palmyra Boro	28 - Pemberton Boro
29 - Pemberton Twp	30 - Riverside Twp
31 - Riverton Boro	32 - Shamong Twp
	34 - Springfield Twp
35 - Tabernacle Twp	36 - Washington Twp
37 - Westampton Twp	38 - Willingboro Twp
39 - Woodland Twp	40 - Wrightstown
33 MOOGIANG IWP	40 - Wrightstown
CAMPEN COMME (AT)	
CAMDEN COUNTY (07)	
01 - Audubon Boro	02 - Audubon Park Boro
03 - Barrington Boro	04 - Bellmawr Boro
05 - Berlin Boro	06 - Berlin Twp
07 - Brooklawn Boro	08 - Camden City
09 - Cherry Hill Twp	10 - Chesilhurst Boro
11 - Clementon Boro	12 - Collingswood Boro
13 - Gibbsboro Boro	14 - Gloucester City
15 - Gloucester Twp	19 Uniden Weights Done
	18 - Haddon Heights Boro
16 - Haddon Twp	17 - Haddonfield Boro
19 - Hi-Nella Boro	20 - Laurel Springs Boro
21 - Lawnside Boro	22 - Lindenwold Boro
23 - Magnolia Boro	24 - Merchantville Boro
25 - Mount Ephraim Boro	26 - Oaklyn Boro
27 - Pennsauken Twp	28 - Pine Hill Boro
29 - Pine Valley Boro	30 - Runnemede Boro
31 - Somerdale Boro	32 - Stratford Boro
33 - Tavistock Boro	34 - Voorhees Twp
35 - Waterford Twp	36 - Winslow Twp
37 - Woodlynne Boro	
CAPE MAY COUNTY (09)	
01 - Avalon Boro	02 - Cape May City
03 - Cape May Point Boro	04 - Dennis Twp
05 - Lower Twp	06 - Middle Twp
07 - North Wildwood City	
00 - Con Tola Cit-	08 - Ocean City
09 - Sea Isle City	10 - Stone Harbor Boro
11 - Upper Twp	12 - West Cape May Boro
13 - West Wildwood Boro	14 - Wildwood City
<pre>15 - Wildwood Crest Boro</pre>	16 - Woodbine Boro
CUMBERLAND COUNTY (11)	
01 - Bridgeton City	02 - Commercial Twp
03 - Deerfield Twp	04 - Downe Twp
05 - Fairfield Twp	06 - Greenwich Twp
on - tattiteta imb	og - Greenwich imb

07 Ucherell The	00
07 - Hopewell Twp	08 - Lawrence Twp
09 - Maurice River Twp	
11 - Shiloh Boro	12 - Stow Creek Twp
13 - Upper Deerfield Twp	14 - Vineland City
ESSEX COUNTY (13)	
01 - Belleville Town	02 - Bloomfield Town
03 - Caldwell Boro	04 - Cedar Grove Twp
05 - East Orange City	06 - Essex Fells Boro
07 - Fairfield Boro	08 - Glen Ridge Boro
09 - Irvington Town	
	12 - Millburn Twp
	14 - Newark City
15 - North Caldwell Boro	
	18 - Roseland Boro
19 - South Orange Village	
21 - West Caldwell Boro	22 - West Orange Town
21 West Caldwell Dolo	22 - west Orange Town
GLOUCESTER COUNTY (15)	
01 - Clayton Boro	02 - Deptford Twp
03 - East Greenwich Twp	04 - Elk Twp
	06 - Glassboro Boro
05 - Franklin Twp	
07 - Greenwich Twp	08 - Harrison Twp
09 - Logan Twp	10 - Mantua Twp 12 - National Park Boro
11 - Monroe Twp	
13 - Newfield Boro	14 - Paulsboro Boro
15 - Pitman Boro	16 - South Harrison Twp
17 - Swedesboro Boro	18 - Washington Twp
19 - Wenonah Boro	20 - West Deptford Twp
21 - Westville Boro	22 - Woodbury City
23 - Woodbury Heights Boro	24 - Woolwich Twp
IUIDCON COIDIMI (17)	
HUDSON COUNTY (17)	02 - East Newark Boro
01 - Bayonne City	
03 - Guttenberg Town	04 - Harrison Town
05 - Hoboken City	06 - Jersey City
07 - Kearny Town	08 - North Bergen Twp
09 - Secaucus Twp	10 - Union City
11 - Weehawken Twp	12 - West New York Town
IUDIMEDDON COLDINA (10)	
HUNTERDON COUNTY (19)	03 - Bothloham Tum
01 - Alexandria Twp	02 - Bethlehem Twp
03 - Bloomsbury Boro	04 - Califon Boro 06 - Clinton Twp
05 - Clinton Town	
07 - Delaware Twp	08 - East Amwell Twp
09 - Flemington Boro	10 - Franklin Twp
11 - Frenchtown Boro	12 - Glen Gardner Boro
13 - Hampton Boro	14 - High Bridge Boro
15 - Holland Twp	16 - Kingwood Twp
17 - Lambertville City	18 - Lebanon Boro
19 - Lebanon Twp	20 - Milford Boro
21 - Raritan Twp	22 - Readington Twp
23 - Stockton Boro	24 - Tewksbury Twp
25 - Union Twp	26 - West Amwell Twp

MERCER COUNTY (21)  01 - East Windsor Twp  03 - Hamilton Twp  05 - Hopewell Boro  07 - Lawrence Twp  09 - Princeton Boro  11 - Trenton City  13 - West Windsor Twp	02 - Ewing Twp 04 - Hightstown Boro 06 - Hopewell Twp 08 - Pennington Boro 10 - Princeton Twp 12 - Washington Twp
MIDDLESEX COUNTY (23)  01 - Carteret Boro  03 - Dunellen Boro  05 - Edison Twp  07 - Highland Park Boro  10 - Metuchen Boro  12 - Milltown Boro  14 - New Brunswick City  09 - Old Bridge Twp  17 - Piscataway Twp  19 - Sayreville Boro  21 - South Brunswick Twp  23 - South River Boro  25 - Woodbridge Twp	02 - Cranbury Twp 04 - East Brunswick Twp 06 - Helmetta Boro 08 - Jamesburg Boro 11 - Middlesex Boro 13 - Monroe Twp 15 - North Brunswick Twp 16 - Perth Amboy City 18 - Plainsboro Twp 20 - South Amboy City 22 - South Plainfield Boro 24 - Spotswood Boro
MONMOUTH COUNTY (25)  30 - Aberdeen Twp  02 - Allentown Boro  04 - Atlantic Highlands Boro  06 - Belmar Boro  08 - Brielle Boro  10 - Deal Boro  12 - Englishtown Boro  14 - Farmingdale Boro  16 - Freehold Twp  17 - Highland Boro  19 - Howell Twp  21 - Keansburg Boro  23 - Little Silver Boro  25 - Long Branch City  27 - Manasquan Boro  29 - Matawan Boro  32 - Millstone Twp  35 - Neptune City Boro  37 - Ocean Twp  40 - Red Bank Boro  42 - Rumson Boro  44 - Sea Girt Boro  46 - Shrewsbury Twp  48 - Spring Lake Boro  36 - Tinton Falls Boro  51 - Upper Freehold Twp  53 - West Long Branch Twp	01 - Allenhurst Boro 03 - Asbury Park City 05 - Avon-By-The-Sea Boro 07 - Bradley Beach Boro 09 - Colts Neck Twp 11 - Eatontown Boro 13 - Fair Haven Boro 15 - Freehold Boro 39 - Hazlet Twp 18 - Holmdel Boro 20 - Interlaken Boro 22 - Keyport Boro 24 - Loch Arbour Village 26 - Manalapan Twp 28 - Marlboro Twp 31 - Middletown Twp 33 - Monmouth Beach Boro 34 - Neptune Twp 38 - Oceanport Boro 41 - Roosevelt Boro 43 - Sea Bright Boro 45 - Shrewsbury Boro 47 - South Belmar Boro 49 - Spring Lake Heights Boro 50 - Union Beach Boro

MORRIS COUNTY (27)	
01 - Boonton Town	A2 December Mars
	02 - Boonton Twp
03 - Butler Boro	04 - Chatham Boro
05 - Chatham Twp	06 - Chester Boro
07 - Chester Twp	08 - Denville Twp
09 - Dover Town	10 - East Hanover Twp
11 - Florham Park Boro	12 - Hanover Twp
13 - Harding Twp	14 - Jefferson Twp
15 - Kinnelon Boro	
	16 - Lincoln Park Boro
17 - Madison Boro	18 - Mendham Boro
19 - Mendham Twp	20 - Mine Hill Twp
21 - Montville Twp	23 - Morris Plains Boro
22 - Morris Twp	24 - Morristown Town
26 - Mount Arlington Boro	27 - Mount Olive Twp
25 - Mountain Lakes Boro	28 - Netcong Boro
29 - Parsippany Troy-Hills Twp	30 - Passaic Twp
31 - Pequannock Twp	32 - Randolph Twp
33 - Riverdale Boro	
	34 - Rockaway Boro
35 - Rockaway Twp	36 - Roxbury Twp
37 - Victory Gardens Boro	38 - Washington Twp
39 - Wharton Boro	
OCEAN COUNTY (29)	
01 - Barnegat Light Boro	33 - Barnegat Twp
02 - Bay Head Boro	03 - Beach Haven Boro
04 - Beachwood Boro	05 - Berkeley Twp
	07 - Douge Tem
06 - Brick Twp	07 - Dover Twp
08 - Eagleswood Twp	09 - Harvey Cedars Boro
10 - Island Heights Boro	11 - Jackson Twp
12 - Lacey Twp	13 - Lakehurst Boro
14 - Lakewood Twp	15 - Lavalette Boro
16 - Little Egg Harbor Twp	17 - Long Beach Twp
18 - Manchester Twp	19 - Mantaloking Boro
21 - Ocean Gate Boro	20 - Ocean Twp
22 - Pine Beach Boro	23 - Plumsted Twp
25 - Point Pleasant Beach Boro	24 - Point Pleasant Boro
26 - Seaside Heights Boro	27 - Seaside Park Boro
28 - Ship Bottom Boro	29 - South Toms River Boro
20 Shaffand mm	
30 - Stafford Twp	31 - Surf City Boro
32 - Tuckerton Boro	
PASSAIC COUNTY (31)	
01 - Bloomingdale Boro	02 - Clifton City
03 - Haledon Boro	04 - Hawthorne Boro
05 - Little Falls Twp	06 - North Haledon Boro
07 - Passaic City	08 - Paterson City
09 - Pompton Lakes Boro	10 - Prospect Park Boro
11 - Ringwood Boro	12 - Totowa Boro
13 - Wanaque Boro	14 - Wayne Twp
15 - West Milford Twp	16 - West Paterson Boro
6177W 6017-7- (66)	
SALEM COUNTY (33)	
01 - Alloway Twp	13 - Carney's Point Twp
02 - Elmer Boro	03 - Elsinboro Twp

OA Forem Nilamon Grank Man	OF Manufactor Man
04 - Lower Alloways Creek Twp	
06 - Oldmans Twp	07 - Penns Grove Boro
08 - Pennsville Twp	09 - Pilesgrove Twp
10 - Pittsgrove Twp 12 - Salem City	11 - Quinton Twp
12 - Salem City	14 - Upper Pittsgrove Twp
15 - Woodstown Boro	
SOMERSET COUNTY (35)	
01 - Bedminster Twp	02 - Bernards Twp
03 - Bernardsville Boro	04 - Bound Brook Boro
05 - Branchburg Twp	06 - Bridgewater Twp
07 - Far Hills Boro	08 - Franklin Twp
09 - Green Brook Twp	10 - Hillsborough Twp
11 - Manville Boro	12 - Millstone Boro
13 - Montgomery Twp	<pre>14 - North Plainfield Boro</pre>
<pre>15 - Peapack-Gladstone Boro</pre>	16 - Raritan Boro
17 - Rocky Hill Boro	18 - Somerville Boro
19 - South Bound Brook Boro	20 - Warren Twp
21 - Watchung Boro	_
•	
SUSSEX COUNTY (37)	
01 - Andover Boro	02 - Andover Twp
03 - Branchville Boro	04 - Byram Twp
05 - Frankford Twp	06 - Franklin Boro
07 - Fredon Twp	08 - Green Twp
09 - Hamburg Boro	10 - Hampton Twp
11 - Hardyston Twp	12 - Hopatcong Boro
13 - Lafayette Twp	14 - Montague Twp
15 - Newton Town	16 - Ogdensburg Boro
17 - Sandyston Twp	18 - Sparta Twp
19 - Stanhope Boro	20 - Stillwater Twp
21 - Sussex Boro	22 - Vernon Twp
23 - Walpack Twp	24 - Wantage Twp
UNION COUNTY (39)	00
01 - Berkeley Heights Twp	02 - Clark Twp
03 - Cranford Twp	04 - Elizabeth City
05 - Fanwood Boro	06 - Garwood Boro
07 - Hillside Twp	08 - Kenilworth Boro
09 - Linden City	10 - Mountainside Boro
11 - New Providence Boro	12 - Plainfield City
13 - Rahway City	14 - Roselle Boro
15 - Roselle Park Boro	16 - Scotch Plains Twp
17 - Springfield Twp	18 - Summit City
19 - Union Twp	20 - Westfield Town
21 - Winfield Twp	
WADDEN COINING (A1)	
WARREN COUNTY (41) 01 - Allamuchy Twp	02 - Alpha Boro
03 - Belvidere Town	04 - Blairstown Twp
05 - Franklin Twp	06 - Frelinghuysen Twp
07 - Greenwich Twp	08 - Hackettstown Town
09 - Hardwick Twp	10 - Harmony Twp
11 - Hope Twp	12 - Independence Twp
TT MONG TAN	Time herimenine Tah

13	-	Knowlton Twp	14 - Liberty Twp
15	-	Lopatcong Twp	16 - Mansfield Twp
17	-	Oxford Twp	18 - Pahaquarry Twp
19	-	Phillipsburg Town	20 - Pohatcong Twp
21	_	Washington Boro	22 - Washington Twp
23	_	White Tun	•

## DESCRIPTION OF NJGS CASE INDEX SITES

The NJGS Case Index Sites listing contains the following fields:

CONTAM: contaminate code

DISTANCE: distance in miles from center of circle

FMCODE1: NJGS primary formation code FMCODE2: NJGS secondary formation code

LAT: latitude of site LON: longitude of site

NAME: name and location of site

SITENUM: site identifier

STATUS1: current status of site

STATUS2: further description of site status

The data in this listing is down-loaded on a regular basis from the New Jersey Geological Survey's Case Index File. The actual transfer date is printed on the left side of the enclosed map. This file contains many of the identified potential pollution sites in the State, but does not include all of them. For example the file does not generally include spill sites. Recognizing the fact that this list may contain significant errors and omissions, it is advisable to use this resource as a guide and to verify all information.

If you have any questions, please call or write to us in reference to the "Radius Program" at:

NJDEP Division of Water Resources Bureau of Water Allocation CN-029 Trenton, NJ 08625

(609) 292-2957

Please see the attached sheets for definitions of the codes used in the NJGS Case Index Sites listing.

## CODES USED IN THE NJGS CASE INDEX SITES LISTING

This packet contains definitions of the database codes used in the NJGS Case Index Sites listing.

## CONTAM

- 00 = ORGANIC CHEM (VOLATILE)
- 01 = ORGANIC CHEM (NONVOLATILE)
- 02 = CHLOROFORM
- 03 = '1,2 DICHLOROETHANE'
- 04 = '1,1,1 TRICHLOROETHANE'
- 05 = TETRACHLOROETHYLENE
- 06 = DICHLOROETHYLENE
- 07 = TRICHLOROETHYLENE
- 08 = CARBON TETRACHLORIDE
- 09 = METHYLENE CHLORIDE
- 10 = ACETONE
- 11 = BENZENE
- 12 = TOLUNE
- 13 = XYLENE
- 14 = METHYL ISOBUTYL KETONE
- 15 = ETHYLENE DICHLORIDE
- 16 = METHYL ETHYL KETONE
- 17 = TETRAHYDROFURAN
- 18 = '1,2 DICHLOROETHENE'
- 19 = '1,1 DICHLOROETHENE'
- 20 = '1,1 DICHLOROETHANE'
- 21 = '1,1,2,2 TETRACHLOROETHYLENE'
- 22 = '1,1,2,2 TETRACHLOROETHANE'
- 23 = TRICHLOROFLUOROMETHANE
- 24 = CHLOROBENZENE
- 25 = ETHYLBENZENE
- 26 = '1,2 DICHLOROBENZENE'
- 27 = DICHLOROFLUOROMETHANE
- 28 = STYRENE
- 29 = ISOPROPYL ALCOHOL
- 30 = VINYL CHLORIDE
- 31 = HEXANE
- 32 = HEPTANE
- 33 = PHENTANE
- 34 = PHENOLS
- 35 = METALS
- 36 = LEAD
- 37 = IRON
- 38 = MERCURY
- 39 = CHROMIUM
- 41 = ARSENIC
- 42 = CADMIUM
- 43 = CHLORIDE
- 44 = SODIUM
- 45 = NITRATE

- 46 = SULFATE
- 47 = PESTICIDES
- 48 = HERBICIDES
- 49 = NATURAL RADIOACTIVITY
- 50 = 'PCB''S'
- 51 = GASOLINE
- 52 = DIESEL FUEL
- 53 = FUEL OIL
- 54 = INORGANIC CHEMICALS
- 55 = GREASES AND FATS
- 56 = SLUDGE
- 57 = ACID
- 58 = LEACHATE
- 59 = METHANE GAS
- 60 = DYE
- 61 = IODINE
- 62 = EXPLOSIVES
- 63 = PETROLEUM HYDROCARBONS
- 64 = PHARMACEUTICALS
- 65 = SURFACTANTS
- 66 = SEPTIC DISCHARGES
- 67 = RADIOACTIVE WASTE
- 68 = UNKNOWN
- 69 = TRICHLORETHYLENE
- 70 = COAL TAR
- 71 = ASBESTOS
- 72 = DIOXIN

## **FMCODE**

- 0000 = 'N/A'
- 0100 = QUATERNARY
- 0101 = MEADOW MAT
- 0102 = ALLUVIUM
- 0103 = FILL
- 0104 = BEACH SANS
- 0110 = GLACIAL, UNDIFFERENTIATED
- 0120 = GLACIAL, UNSTRATIFIED TILL
- 0130 = STRATIFIED DRIFT
- 0140 = MORAINE
- 0144 = TERMINAL MORAINE
- 0148 = RECESSIONAL MORAINE
- 0150 = BRIDGETON
- 0160 = CAPE MAY
- 0161 = HOLLY BEACH MBR
- 0170 = PENNSAUKEN
- 1000 = TERTIARY
- 1010 = BEACON HILL
- 1020 = COHANSEY SAND
- 1025 = COHANSEY KIRKWOOD
- 1030 = KIRKWOOD SAND
- 1031 = UPPER MEMBER
- 1032 = LOWER MEMBER

- 1033 = PINEY POINT MBR
- 1040 = SHARK RIVER MARL
- 1050 = MANASQUAN MARL
- 1060 = VINCENTOWN SAND
- 1070 = HORNERSTOWN MARL
- 2000 = CRETACEOUS
- 2010 = RED BANK AND TINTON SANDS
- 2020 = NAVESANK MARL
- 2030 = MOUNT LAUREL WENONAH SANDS
- 2034 = MOUNT LAUREL SAND
- 2038 = WENONAH SAND
- 2040 = MARSHALLTOWN FM
- 2050 = ENGLISHTOWN SAND
- 2060 = WOODBURY CLAY
- 2070 = MERCHANTVILLE CLAY
- 2080 = MAGOTHY RARITAN FM
- 2081 = MAGOTHY RARITAN UPPER MBR
- 2084 = MAGOTHY RARITAN MIDDLE MBR
- 2088 = MAGOTHY RARITAN LOWER MBR
- 2090 = MAGOTHY FM
- 2091 = AMBOY STONEWARE CLAY MBR
- 2092 = OLD BRIDGE SAND MBR
- 2093 = SOUTH AMBOY FIRE CLAY MBR
- 2094 = SAYREVILLE SAND MBR
- 2095 = WOODBRIDGE CLAY MBR
- 2096 = FARRINGTON SAND MBR
- 2097 = RARITAN FIRE CLAY MBR
- 3000 = TRIASIC JURASSIC
- 3010 = BOONTON FM
- 3020 = BASALT UNDIFFERENTIATED
- 3021 = HOOK MT BASALT
- 3030 = TOWACO FM
- 3022 = PREAKNESS BASALT
- 3040 = FELTVILLE FM
- 3023 = ORANGE MT BASALT
- 3050 = DIABASE
- 3060 = CONGLOMERATE (HAMMER CREEK)
- 3070 = BRUNSWICK FM
- 3080 = LOCKATONG FM
- 3090 = STOCKTON FM
- 4000 = DEVONIAN
- 4010 = SKUNNEMUNK CNGLM
- 4020 = BELLVALE SS PEQUANAC SH
- 4030 = KANOUSE SANDSTONE
- 4040 = MARCELLUS SHALE
- 4050 = ONONDAGE LS
- 4060 = ESOPUS GRIT
- 4070 = ORISKANY BECRAFT LS
- 4080 = NEW SCOTLAND COEYMANS
- 5000 = SILURIAN
- 5010 = BOSSARDVILLE LS
- 5020 = DECKER FM
- 5030 = LONGWOOD SHALE
- 5040 = POXONO ISLAND

- 5050 = GREENPOND CONGLOMERATE
- 5060 = HIGH FALLS
- 5070 = SHAWANGUNK CONGLOMERATE
- 6000 = ORDOVICIAN
- 6010 = MARTINSBURG SHALE
- 6011 = PEN ARGYL MBR
- 6012 = RAMSEYBURG MBR
- 6013 = BUSHKILL MBR
- 6020 = JACKONSBURG LS
- 6030 = ONTLEAUNEE FM
- 6031 = HARMONYVALE MBR
- 6032 = BEAVER RUN MBR
- 6040 = EPLER FM
- 6041 = LAFAYETTE MBR
- 6042 = BIG SPRINGS MBR
- 6043 = BRANCHVILLE MBR
- 6050 = RICKENBACK DOLOMITE
- 6060 = MANHATTAN SCHIST
- 7000 = CAMBRO ORDOVICIAN
- 7010 = KITTATINNY SUPERGROUP
- 8000 = CAMBRIAN
- 8010 = ALLENTOWN FM
- 8011 = UPPER MBR
- 8012 = LIMEPORT MBR
- 8020 = LEITHSVILLE FM
- 8021 = WALLKILL MBR
- 8022 = HAMBURG MBR
- 8023 = CALIFON MBR
- 8030 = HARDYSTONE SAND
- 9000 = PRE CAMBRIAN
- 9010 = GRANITE
- 9011 = HORNBLEND GRANITE
- 9020 = GNEISS
- 9021 = GRANITE GNEISS
- 9022 = HORNBLEND GNEISS
- 9023 = QUARTZ OLIGOCLAISE GNEISS
- 9030 = ALASKITE
- 9040 = SYENITE
- 9041 = SYENITE GNESS
- 9050 = PYROXENE GRANITE
- 9060 = MICROCLINE GNEISS
- 9070 = FRANKLIN LIMESTONE
- 9080 = AMPHIBOLITE
- 9090 = BIOTITE GNEISS
- 9091 = MIXED GNEISS;

## STATUS1

- 1 = INVESTIGATION 2 = AQUIFER RESTOR CONT
- 3 = REQUEST FOR GEOLOG
- 4 = MONITORING
- 5 = LITIGATION
- 6 = CLOSED

- 7 = OTHER
- 8 = BACKLOGGED
- 9 = TRANS PERMITS
- 0 = UNKNOWN
- F = FIELD REC PROVIDED

## STATUS2

- O = INVEST CONT
- A = CLEAN UP PLAN
- B = SAMPLING PLAN
- C = INITIAL INVEST
- D = RQST PRPSL (RFP)
- E = REMEDIAL INVEST
- F = FSBLTY STUDY (FS)
- G = PLAN, CONST REMEDIAL
- H = FREE PRODUCT RECOVERY
- I = DSLVD FRACTION RECOV
- J = FREE, DSSLVD RECOV
- K = CASE ABSORBED

REFERENCE NO. 9

ing the state of t

## NUS CORPORATION SUPERFUND DIVISION

PROJECT NOTES

TO: FILE: POOR RICHARDS DATE: 7/6/88
FROM: STAN SHULFER COPIES:
SUBJECT: TOUT Mont clair Water Wells
REFERENCE: POOR RICHARDS 02-8803-55
NJ64\$I
1:00 - 1:45 Met w/ Messes. Ferraro, and
Englishman. I recieved copy of
water test duta for 1988.
Both gentleman confirmed that
all three of the community wells
are contaminated w/ low levels
of volatile organics apparently
from dry cleaning establishments.
Ground water flow is generally in
a southern direction.
Population served by the Montelan
water system:
Montclair - approximately 38,000
Clifton - approximately 130 homes
x3.8 persons/home= 494
Little falls - approximately 120 homes  x3. 8 persons/home = 456
Glenkidge - unknown
would have to
Check w/ Glen-Ridge
Borough
These wells are currently only
used for peak demands during
summertime when the allocation from
NUS 443A 58 1182 Winnague Reservoir is exceeded. over
v

This water from wells is sumped into the distribution System. Water Quality 13 monitored at head as well as outire system. Water is blen Ridge via the perton of the Hen Ridge recieves water only from the ountied well. Mr. Ferraro stated he will send a copy of the water distribution system map when paper becomes awaitable for the behile print mucline. Massis Linglishman Stated that the borough in the past had samplet Toners Brook. There seemed to be Correlation with chloride in the stream the Montclar Wells. Copy at the Steam analysis results were Novided: See map for approximate locations Mr. Ferraro provided me with a copy of correspondence from N.J. DEP, about the closure of the YMCA well for high level of Tetrachloroethylene. Sec mup for approximate location.

REFERENCE NO. 10

.

.

•

## NUS CORPORATION TELECON NOTE CONTROL NO: DATE: TIME: 6/30/88 8.55 700 02-8803-55 POUR RICHARDS BRICS NJ64 BI BETWEEN: OF: Montclair water PHONE: KEUIN RYAN Bureau (201) 744-4600 SHULFER (NUS) spoke with Mr. Ryan concerning Mr. Ryan Stated that weils have been shut down are used water demand Glenfrell Wells were only Jersey Water locations are as Glenfield Well - located behind Glenfield High Schoo **ACTION ITEMS:** located at Chestnut S located at and North Mountain Av tested on a regular Jack Ferrarro,

Herb Englishman, Asst.

REFERENCE NO. 11

NUS CORPORATION AND SUBSIDIARIES

TELECON NOTE

CONTROL NO:	DATE: /	TIME:
	7/13/87	1130
DISTRIBUTION:		
Poor Richard	_	NJ64\$Z
Henry Bog danst	Ci Essex County Hos	OTAD (201) 228-8283
1,000	Center '	(30) 030 020 3
STAN	SHULFER	
DISCUSSION.	gdanski stute	d Heat
	8,9 and 10	
	ng water. 7	
_ demand	on water	is approximately
2,000 perso	ms. Wells	# 1-6 are
	n a dittere	
these will	probably be	abundaned
_ because of	The low g	field. Wells
are test	ed monthly	for Dueteria,
H-280 fa	rameters eve	ery 6 months
_ and mor	ganits once	every 3 years.
ACTION ITEMS:		

REFERENCE NO. 12

#### STAFF REPORT

In the matter of

Town of Montclair

Application No. 5245 to renew permit to divert water from three wells in the Town of Montclair, Essex County.

In compliance with the provisions of N.J.S.A. 58:1A-1 et seg., the Town of Montclair, Municipal Building, Montclair, New Jersey is presumed to have filed an application with the Division of Water Resources for renewal of a permit to divert a maximum of 62 million gallons of water during any month at a maximum rate of 1,398 gallons per minute from existing Well Nos. 1, 2 and 3, each 300 feet deep screened in the Brunswick formation. The wells are located in the Town of Montclair. Diversion is for the purpose of supplying water to the Town of Montclair, Borough of Glen Ridge and Township of Cedar Grove in Essex County, and also parts of the Township of Little Falls and the City of Clifton in Passaic County.

The applicant requests no increase in their existing diversion rights and no public notice is required.

## Background

1. This permit is a renewal of an allocation granted by the following:

Permit No.	Date	Source of Water	Diversion Amount (mgm)
1331	10/20/66	Well No. 1	18.60
1370	3/23/67	Well No. 2	31.00
1593	4/24/72	Well Nos. 1 & 2	45.00
1795	8/20/79	Wall Nos. 1, 2 & 3	62.00

2. The diversion includes the following:

Well	Well	Date	Depth	Pump Cap.	Yield
No.	Permit No.	Const.	(it.)	(gpm)	(abw)
1-Rand Well	26-3633	1/67	300	400	470
2-Glenfield Well	26-3687	12/68	300	600	950
3-Lorraine Well	26-4597	10/12/76	300	400	400

- 3. The diversion serves the following communities:
  - a. Town of Montclair
  - b. Borough of Glen Ridge
  - c. Township of Cedar Grove
  - d. Parts of the Township of Little Falls and City of Clifton in Passaic County

4. The present water supply is being derived from both surface and groundwater. The applicant is a partner in the Wanaque/Ramapo system in the amount of 5 percent; resulting in an allocation of 5.2 mod, base on 104 mgd safe yield, or 4.7 mgd, based on a safe yield of 94 mgd. The applicant's primary source of water supply is the Ramapo-Wanague Reservoir System, operated by the North Jersey District Water Supply Commission.

## Findings of Fact

1. A review of quarterly diversion reports for both surface and groundwater indicates the following water use:

Maximum Monthly Use (mgm)	Average Monthly Use (mgm)	Allocation (mgm)
208.86	158.39	62

- 2. The population served is approximately 55,014 which represents an average consumption of 92.8 gpcd, and peak consumption of 122.5 gpcd.
- 3. The following static water level data is available:

Well		water Levels		
NO.	When Const	ructed	Recent	
	(date)	(level)	(date)	(level)
1	1/67	19'	7/83	35'
2	12/68	20'	7/83	38 <b>'</b>
3	10/76	11'	7/83	25 <b>'</b>

4. The following long-term pumping test data is available:

Well	Date	Yield	Drawdown	Static	Pumping
No.	of Test	(gpm)	(feet)	Level (ft.)	Time (hrs.)
1	4/11/66	470	125	19	84
2	10/65	950	70	20	57.5
3	10/12/76	420	62	11	72

5. Public water supply wells within a 5-mile radius include the following:

Well	No. of	Depth	Distance
Owner	Wells	(ft.)	(miles)
City of Orange	7	51-124,500	2.0
Essex Fells Borough	16	40-550	3.3
South Orange Village	-		4.2
Passaic Valley water	Comm		4.2

6. Water, after use, is discharged to Passaic Valley Sewerage

Commission regional treatment plant for treatment and discharged to the Passic River. The treatment works are not under a sewer connection ban or other restriction imposed by NJDEP.

- 7. The water system has storage capacity of 2.5 MG steel tank, and 1.5 MG underground reservoir.
- 8. The applicant has the following interconnections with adjacent systems:

Size of Interconnection

Bloomfield 16"
City of Newark 20"
Commonwealth Water Company 16"

- 9. Applicant has agreement for sale of water to the following systems:
  - a. Township of Little Falls

Name of System

- b. Cedar Grove Township
- c. Glen Ridge Borough
- d. City of Clifton
- 10. The Montclair Sanitary Lanfill is about 1 mile away from the applicant's wellfield. The landfill is lined.

## Staff Analysis

- 1. The water use is within the range of national average and is in the public interest.
- 2. The applicant's primary source of water supply is the Ramapo-Wanaque Reservoir System, operated by the North Jersey District Water Supply Commission. The applicant is a partner in the system in the amount of 5 percent, thus, resulting in an allocation of 5.2 mgd, based on 104 mgd safe yield, or 4.7 mgd, based on a safe yield of 94 mgd. The applicant is not required to obtain water allocation permit for surface water diversion from the system. However, the applicant is required to report the amount of surface water diverted from the system quarterly to the Water Allocation Office.
- 3. Based on existing information (Hearing testimony, 1979, Engineering report Lorraine well) the diversion probably will not have an adverse affect on nearby wells. There was no significant change in static water level recorded despite many years of continuous operations. Therefore, natural replenishment of groundwater is probably occuring.
- 4. Diversion will not likely cause groundwater pollution. Within a one-mile radius there is one known sanitary landfill. However, the

landfill is lined to prevent leakage.

5. There is little probability of salt water intrusion because the diversion is far from the brackish waters and above sea level.

## Canclusions

- 1. The allocation is necessary and in the public interest.
- 2. The diversion will not contribute to groundwater pollution or salt water intrusion.
- 3. The diversion will not exceed natural replenishment, and will not unduly interfere with other users.

#### Recommendations

Issuance of the permit is recommended subject to the standard conditions and to the following specific conditions:

1. The amount of water that may be diverted under this renewal permit shall be as follows:

Well Permit No.	Well Name or Designation	Pump Capacity (gpm)	Formation
25-3687	Rand Well #1	400	Brunswick
26-3588	Glenfield Well #	2 600	Brunswick
26-4597	Lorraine Well #3	400	Basalt Flows

- 2. The total allocation from the above sources shall not exceed 62 million gallons per month at a maximum rate of 1,388 gpm.
- 3. All wells shall be metered. The total diversion for each month from each well shall be reported quarterly to the Water Allocation Office under Permit No. 5245. Applicant shall submit within 60 days of receipt of this permit a plan for monitoring diversions using the form available from the Water Allocation Office. Wells shall be equipped with a tag showing the well permit numbers listed above.
- 4. Diversion from the Ramapo-Wanaque Reservoir System shall be metered and the quantity diverted each month, shall be reported quarterly to the Water Allocation Office under Report No. 5245.
- 5. The applicant shall submit, with the fourth quarterly diversion report: (a) the total annual commercial/industrial water use; (b) the percent of unaccounted for water not metered; (c) the daily peak water consumption in gallons per capita per day.
- 6. Wells shall be constructed so that water level measurements can be made by tape at any time. Applicant shall submit with quarterly

diversion reports the static water level of wells identified in the monitoring plan (See 3. above). Measurement shall be made when the well pump has been shut down for a recovery period of 12 to 24 hours.

- The pumping equipment capacity shall not be increased without prior approval by the Division.
- 8. All new services shall be metered upon installation.
- All existing services shall be metered. A plan for installing meters in existing services satisfactory to the Water Allocation Office shall be submitted within six months of this approval.
- 10. The applicant shall adopt and implement to the satisfaction of the division, a continuous program to encourage water conservation in all types of use within the area served by the applicant. A report shall be submitted to the Division on or before June 30, 1984, and each year thereafter, on the actions taken pursuant to this program and the impact thereof.
- Permittee shall have the right to apply at any time for modification of this permit by submission of the appropriate application forms. Permittee may informally discuss the terms and conditions of this permit at any time with the Water Allocation Office. An application for renewal shall be filed 3 months prior to the expiration date.
- 12. If the permittee fails to comply with any of the terms and conditions herein, or in the public interest and after due process, this approval may be reviewed for possible modification or revocation thereof.
- 13. The Division, at its option, may cause the permit to be reviewed at intervals of not less than 5 years to examine the need for the allocation and to determine compliance with the terms and conditions of the permit and whether a modification to the permit is necessary.
- 14. The permittee is subject to initial, renewal and annual fees as may be prescribed by the regulations.
- 15. This permit shall expire on January 31, 1999.
- 16. This permit shall not become operative unless and until the applicant has filed with the Division within 60 days from the date of transmittal hereof, written acceptance of the terms and conditions hereby imposed.

Respectfully submitted,

Hoor Michiga Vlado Michna

Water Allocation Office


1-24-64 ERH OK WW

# DEPARTMENT OF CONSERVATION AND ECONOMIC DEVELOPMENT DIVISION OF WATER POLICY & SUPPLY

_	6.3685
Permit No.	W. 7000
Application N	a +334
County Esse	1270

## WELL RECORD

۱.	OWNER Town of Montclair ADDRESS Watchung Ave
	Owner's Well No. Three SURFACE ELEVATION (Above mean sea level)
•	LOCATION Glenfield Park South Bloomfield Ave Montclair N.J.
2.	DATE COMPLETED Oct 20 1966 DRILLER Rinbrand Well Drilling Co Inc
3.	
4.	DIAMETER: topl6x10 inches Bottom 10 inches TOTAL DEPTH 300 Feet
5.	CASING: Type <u>steel</u> Diameter 16x10 Inches Length 21-41 Feet
6.	SCREEN: Type none Size of Opening Diameter Inches Length Feet
	Range in Depth         Top
	Tail piece: DiameterInches LengthFeet
7.	WELL FLOWS NATURALLY Gallons per Minute at Feet above surface
	Water rises toFeet above surface
8.	RECORD OF TEST: Date Oct 20 1966 Yield 950 Gallons per minute
	Static water level before pumping 24 Feet below surface
	Pumping level 75 feet below surface after 73 hours pumping
	Drawdown 51 Feet Specific Capacity (7.6 Gals. per min. per ft. of drawdown
	How Pumped How measuredOrific
	Observed effect on nearby wells
9.	PERMANENT PUMPING EQUIPMENT:
	Type Mfrs. Name Owner to supply
	Capacity G.P.M. How Driven H.P R.P.M
	Depth of Pump in well Feet Depth of Footpiece in well Feet
	Depth of Air Line in wellFeet Type of Meter on Pump SizeInches
	(AverageGallons Daily
10.	USED FOR Public supply AMOUNT \begin{cases} Average Gallons Daily & AMOUNT \\ Maximum Gallons Daily & AMOUNT \end{cases}
11.	
	Taste no Odor no Color clear Temp. 54 of
12.	LOG 21 hard pan Bal red rock 150-250 Best Vedramples available?
13.	SOURCE OF DATA Rinbrand Well Drilling Co Inc
14.	DATA OBTAINED BY Adam F Rinbrand Date Nov 11 1966
	(NOTE: Use other side of this sheet for additional information such as log of materials penetrat analysis of the water, sketch map, sketch of special casing arrangements etc.)



ELSON T. KILLAM ASSOCIATES, INC.
HYDRAULIC AND SANITARY ENGINEERS
MILLBURN, N. J.

FORM 87

piri (ji)

# DEPARTMENT OF CONSERVATION AND ECONOMIC DEVELOPMENT DIVISION OF WATER POLICY & SUPPLY

Permit No. 26-	3687
Application No Essex	/33/
County	

# WELL RECORD

١.	OWNER Montclair Water Bureau ADDRESS Chestnut &N Fullerton
	Owner's Well No. ONE SURFACE ELEVATION (Above mean sea level)
2.	LOCATION Montclair N.J.
3.	DATE COMPLETED April 11 1966 DRILLER Rinbrand Well Drilling Co Inc
4.	DIAMETER: top 10 Inches Bottom 10 Inches TOTAL DEPTH 300 Feet
5.	CASING: Type steel Diameter 16x10 Inches Length 16&36 Feet
6.	SCREEN: Type Size of Opening Diameter Inches LengthFeet
	Range in Depth { TopFeet Geologic Formation
	Tail piece: DiameterInches LengthFeet
7.	WELL FLOWS NATURALLY Gallons per Minute at Feet above surface
	Water rises toFeet above surface
8.	RECORD OF TEST: Date April 11 1966 Yield 470 Gallons per minute
	Static water level before pumping Feet below surface
	Pumping level 122 feet below surface after 84 hours pumping
	Drawdown Feet Specific Capacity Gals. per min. per ft. of drawdown
	How Pumped Turbine How measured Orific
	Observed effect on nearby wells
9.	. Control of Supply
	Type Mfrs. Name
	Capacity G.P.M. How Driven H.P R.P.M
	Depth of Pump in wellFeet Depth of Footpiece in wellFeet
	Depth of Air Line in wellFeet Type of Meter on Pump SizeInches
10.	USED FOR Public supply  AMOUNT   Average Gallons Daily  Maximum Gallons Daily
11.	• • • • • • • • • • • • • • • • • • • •
	Taste no Odor no Color clear Temp. 54 of
12.	LOG 9 clay.13 red shale.bal same  (Give details on back of sheet or on separate sheet. If electric log was made, please
13.	SOURCE OF DATA Rinbrand Well Drilling Co Inc
14	Adom E Pinhmond

FORM 87

# DEPARTMENT OF CONSERVATION AND ECONOMIC DEVELOPMENT DIVISION OF WATER POLICY & SUPPLY


ermit No	46-3654
pplication	No
County Res	

# WELL RECORD

١.	OWNER Montclair Water Beaura ADDRESS Normal and Railroad
	Owner's Well No. Two SURFACE ELEVATION (Above mean sea level)
2.	LOCATION Montclair N.J.
3.	DATE COMPLETED June 7 1966 DRILLER Rinbrand Well Drilling Co Inc
4.	DIAMETER: top 10 Inches Bottom 10 Inches TOTAL DEPTH 300 Feet
5.	CASING: Type Diameter 16x10_inches Length 10x60 Feet
6.	SCREEN: Type Size of Opening DiameterInches LengthFeet
	Range in Depth { TopFeet Geologic Formation  BottomFeet
	Tail piece: DiameterInches LengthFeet
7.	WELL FLOWS NATURALLY Gallons per Minute at Feet above surface
	Water rises toFeet above surface
8.	RECORD OF TEST: Date June 7 1966 Yield 10 Gallons per minute
	Static water level before pumpingFeet below surface
	Pumping level 200 feet below surface after 4 hours pumping
	Drawdown 185 Feet Specific Capacity Gals. per min. per ft. of drawdown
	How Pumped How measuredPail
	Observed effect on nearby wells <u>none</u>
9.	PERMANENT PUMPING EQUIPMENT:
	Type Mfrs. Name NONE
	Capacity G.P.M. How Driven H.P R.P.M
	Depth of Pump in wellFeet Depth of Footpiece in wellFeet
•	Depth of Air Line in wellFeet Type of Meter on Pump SizeInches
10.	USED FORGallons Daily  AMOUNT {     AverageGallons Daily     MaximumGallons Daily
[]	•
	Taste no Odor no Color clear Temp. 50 °F
12.	LOG 30 clay 31 hard pan bal rock Are samples available? <u>yes</u> (Give details on back of sheet or on separate sheet. If electric log was made, viease furnish copy)
13.	
14	Tuly 27 1066

GRADE 0'- 4' LIGHT CEMENT GROU GRAY FINE SAND WITH SOME GRAY CLAY 10" STEEL CASI 4' - 7' RED HARDPAN 7' - 52 RED SHALE SOME VERY SOFT LAYERS. 300 52 - 300 10" ROCK HOLE REU SHALE 248 SOME VERY SOFT LAYERS FROM 60'- 155

REFERENCE NO. 13



REFERENCE NO. 14

!

. ....




MINIATURE METAL BELLOWS

501 LITTLE FALLS RD. · CEDAR GROVE, N.J. 07009 (201) 785-4630

Nonoc 138543

April 21, 1987

Ms. Lori Amato USEPA - Region II 26 Federal Plaza New York, N.Y. 10278



Dear Ms. Amato:

In accordance with the request of NJDEP's Frank Coolick in his 3/26/87 letter to Servometer Corporation, enclosed please find a copy of Servometer's Emergency Plan, Preparedness, Prevention and Contingency Plan (PPC), and the Hazardous Materials Training Manual.

You should retain this copy for use in the event of an emergency.

If there are any questions, please contact me.

Sincerely,

Servometer Corporation

Peter J. Holowachuk

President

PJH/jah

Enc.

80 C G CC CC

MAN MADER NOW THE MORREST NOW THE MORREST NOW THE MORREST NAMED AND THE MORREST NAMED AN

# SERVOMETER CORPORATION EMERGENCY PLAN

This emergency plan has been prepared for Servometer Corporation by Lancy Laboratories, Division of Lancy International, Inc. in accordance with NJPDES Regulations, N.J.A.C. 7:14A-3.12. The emergency plan, which is required of DSW permit holders, is designed to insure effective operation of the facility under emergency conditions.

As provided in Section 3.12(a)1 of the NJPDES regulations, this emergency plan has been developed by addressing pertinent information contained in Servometer's Preparedness, Prevention, and Contingency (PPC) Plan (Attachment A) as well as their Hazardous Waste Training Program (Attachment B). The purpose of the emergency plan as well as the PPC Plan and Hazardous Waste Training Program is to minimize and/or abate hazards to human health and the environment resulting from accidents and mismanagement of hazardous materials, fires, explosions, emission or discharge of hazardous constituents to air, soil, surface or groundwater, and other emergency situations that may occur at the facility. Servometer Corporation has developed procedures for preventive action and is prepared to implement emergency-response procedures in the event of an emergency situation.

Emergency situations may include, but are not limited to those emergencies caused by natural disaster, civil disorder, sabotage, strike, faulty maintenance, negligent operation, or accident. Although all of these emergency situations are possible, an emergency caused by natural disaster, civil disorder, or sabotage cannot reasonably be expected to occur at the Servometer facility. Therefore, emergency situations related to strike, faulty equipment, poor maintenance, negligent operation, or accidents will be primarily addressed as to their effects on the following:

- o Power Supply
- o Communication
- o Equipment
- o Supplies
- o Personnel
- o Security, and
- o Emergency Procedures

Power Supply: As discussed in the PPC Plan, External Factors (Page 15), Servometer Corporation should be minimally affected, from a safety standpoint, by a power outage. During a power outage, production in all departments would cease. Emergency flood lights are available for adequate lighting to shut-down production processes and an emergency telephone system exists to contact outside assistance, if needed.

Communication: As discussed in the PPC Plan, Internal and External Communications or Alarm Systems (Page 16), the Servometer facility is presently equipped with sufficient communication and alarm systems to provide immediate emergency instruction to facility personnel and to summon outside assistance.

Equipment: Emergency situations that arise from faulty maintenance or improper operation of equipment may occur within the Plating Department and/or the Wastewater Treatment Area. These areas are designed to collect any spillage and/or leakage from damaged equipment.

Routine inspections of facility equipment are conducted to identify and remedy any potential emergency situation.

Emergency-response equipment is available at Servometer to allow personnel to respond safely and quickly to emergency situations. Emergency Equipment (Page 24) of the PPC Plan, identifies the emergency equipment available at the facility.

Supplies: As discussed in the PPC Plan, Raw Material and Waste Inventory (Page 4), Servometer maintains a complete inventory of all potentially hazardous chemical supplies including raw materials, process materials, and wastewater treatment chemicals. Spills and/or leaks resulting from negligent operations or accidents would be contained within the specific areas where the materials are stored.

Personnel: As discussed in the PPC Plan, Employee Training Program (Page 17), all Servometer Corporation personnel are given training to enable them to understand the processes and materials with which they work, associated safety and health hazards, and practices for preventing and responding to emergency situations. The Hazardous Waste Training Program (Attachment B) emphasizes training in emergency procedures and use of emergency equipment. In addition, as presented in the PPC Plan, personnel are informed about Inspection and Monitoring (Page 12), Material Compatibility (Page 11), and Housekeeping Practices (Page 13).

Security: Security procedures during an emergency situation would be the same as during a non-emergency situation. As discussed in the PPC Plan, Security (Page 14), Servometer maintains a complete facility alarm system equipped with photo electric light beam sensors. Additional security measures include adequate lighting, locked entrances, and warning signs.

Emergency Procedures: In the event of an emergency situation, Servometer Corporation would implement their PPC Plan. Specific emergency procedures including duties and responsibilities of emergency coordinators are outlined in the Plan and include the following sections:

- o List of Emergency Coordinators (Page 18)
- o Duties and Responsibilities of the Emergency Coordinator(s) (Page 19)
- o Chain of Command (Page 22)
- o List of Agencies to be Notified (Page 23)
- o Evacuation Plan for Facility Personnel (Page 25)
- o Arrangements with Emergency Response Contractors (Page 26)

# PREPAREDNESS, PREVENTION, AND CONTINGENCY PLAN

SERVOMETER CORPORATION
501 LITTLE FALLS ROAD
CEDAR GROVE, NEW JERSEY

May 1984

LANCY LABORATORIES
DIVISION, LANCY INTERNATIONAL, INC.

# TABLE OF CONTENTS

INTRODUCTION			Pag	<u>ge</u>
GENERAL DESCRIPTION OF INDUSTRIAL ACTIVITY	•		•	1
ORGANIZATIONAL STRUCTURE FOR IMPLEMENTATION OF THE PPC PLAN	•	•	•	2
DESCRIPTION OF EXISTING EMERGENCY RESPONSE PLANS	•	•	•	3
RAW MATERIAL AND WASTE INVENTORY	•	•	•	4
SPILL AND LEAK PREVENTION AND RESPONSE	•	•	•	8
MATERIAL COMPATIBILITY	•	•	•	11
INSPECTION AND MONITORING PROGRAM	•	•	•	12
PREVENTIVE MAINTENANCE/HOUSEKEEPING		•	•	13
SECURITY	•	•	•	14
EXTERNAL FACTORS	•		•	15
INTERNAL AND EXTERNAL COMMUNICATIONS OR ALARM SYSTEMS	•	•	•	16
EMPLOYEE TRAINING PROGRAM	•	•	•	17
LIST OF EMERGENCY CO-ORDINATORS	•			18
DUTIES & RESPONSIBILITIES OF THE EMERGENCY COORDINATOR(S) .		•	•	19
CHAIN OF COMMAND	•	•	•	22
LIST OF AGENCIES TO BE NOTIFIED	•	•	•	23
EMERGENCY EQUIPMENT	•		•	24
EVACUATION PLAN FOR FACILITY PERSONNEL	:		•	25
ARRANGEMENTS WITH EMERGENCY RESPONSE CONTRACTORS	•	•		26
POLLUTION INCIDENT HISTORY	•	•	•	28
PPC PLAN REVIEW	•	•	•	29
POLLUTION INCIDENT HISTORY	•	•	•	28

# ATTACHMENTS

ATTACHMENT 1: Plant Layout Map

The Preparedness, Prevention, and Contingency (PPC) Plan contained within has been prepared for Servometer Corporation by Lancy Laboratories, a Division of Lancy International, Inc., under Project No. 001712. This PPC Plan has been prepared and submitted in accordance with the New Jersey Hazardous Waste Management Regulations, Title 7, Chapter 26.

#### INTRODUCTION

This Preparedness, Prevention, and Contingency (PPC) Plan was prepared in compliance with the New Jersey Hazardous Waste Management Regulations (N.J.A.C. 7:26-9.7) and Federal RCRA Regulations.

The purpose of the Plan is to minimize and abate hazards to human health and the environment from fire, explosion, emission or discharge of hazardous waste or hazardous waste constituents to air, soil, surface water, or groundwater. The Plan contains procedures for preventive actions as well as emergency procedures in the event of an accident. Employees are given training in all aspects of the PPC Plan so that preventive and emergency procedures are carried out in an effective and coordinated manner. In addition, the Plan has been reviewed with local emergency response agencies to familiarize them with the facility and its operations.

#### GENERAL DESCRIPTION OF INDUSTRIAL ACTIVITY

At its Cedar Grove, New Jersey facility, the Servameter Corporation manufactures miniature metal bellows, bellows assemblies, couplings and contacts for the aerospace and control valve industries. Basically, the manufacturing operation involves the electrodeposition (electroforming) of copper and nickel onto aluminum mandrels. Once the desired thickness is obtained, the aluminum mandrels are dissolved using a caustic solution.

Servometer operates a wastewater treatment system on-site which treats various spent process solutions containing dissolved metals, acids, alkalies, and cyanides. The system also treats rinse waters which flow continuously while the plant is operating. These rinsewaters represent a more voluminous but less concentrated source of wastes as compared to the process solutions. The effluent from the treatment system is discharged to the Peckman River under New Jersey Pollutant Discharge Elimination System (NJPDES) permit #NJ0027847.

The Servometer Corporation is classified as a hazardous waste treatment, storage, and disposal (TSD) facility-EPA I.D. #NJD002138543. Hazardous wastes generated by the facility include: caustic waste (D002), waste acid (D002), still bottoms from solvent (TCE) recovery unit (F001), wastewater treatment sludge (F006), and waste metal working oils (X726). All hazardous wastes are removed from the site within ninety (90) days of generation.

### ORGANIZATIONAL STRUCTURE FOR IMPLEMENTATION OF THE PPC PLAN

Implementation of the PPC Plan is the responsibility of the PPC Plan Committee. This Committee consists of the following employees:

Peter J. Holowachuk, President - Coordinator

Jayne A. Holowachuk, Vice President/Treasurer - Assistant Coordinator Kurt Haag, General Manager - Assistant Coordinator

Louis Fejes, Assistant General Manager - Assistant Coordinator

The coordinator will have the primary responsibility for implementing the plan. At his direction, the assistant coordinators will aid in carrying out the following duties and responsibilities of the committee:

- o Establish employee training programs which familiarize employees with the PPC Plan.
- Identify materials and wastes handled.
- o Conduct visual inspections.
- Review and document past incidents and spills.
- o Identify potential spill sources.
- o Establish spill-reporting procedures.
- o Coordinate spill cleanup activities.
- o Notify appropriate authorities when a spill has occurred.
- o Review new construction and process changes at the plant relative to the PPC Plan.
- o Review and evaluate at regular intervals, the effectiveness of the PPC Plan and institute changes where necessary.

# DESCRIPTION OF EXISTING EMERGENCY RESPONSE PLANS

This PPC plan is the first formal emergency response plan developed by Servameter Corporation for its Cedar Grove facility. Past emergency response practices have been reviewed, updated, and included in this comprehensive plan.

#### RAW MATERIAL AND WASTE INVENTORY

A complete inventory of all potentially hazardous chemical substances located at the plant has been compiled and documented in Table 1. This list is used to identify substances which have the potential for causing environmental degradation or endangerment of human health and safety through accidental releases.

Chemical substances located at the plant can be divided into four categories: raw materials, process materials, wastewater treatment chemicals, and waste materials. General information on materials in each of these categories is provided in Table 1. This table includes information concerning storage location, use in manufacturing operations, and storage volume. Although the plant has numerous process test reagents, they represent a small volume of overall chemical usage. In addition to the information provided in Table 1, chemical storage and usage areas are identified on a plant schematic in Attachment 1. Material safety data sheets are available to all employees who come into contact with these chemicals.

TABLE 1

RAW MATERIAL AND WASTE INVENTORY

The same of the sa

# A. RAW MATERIALS

en la la jaroja a en la la leggia de

Name	Location	Use	Storage Volume
Copper Cyanide	Plating Dept.	Plating Bath	100 lbs.
Nickel Sulfamate	Plating Dept.	Plating Bath	55 gal.
Nickel Chloride	Plating Dept.	Plating Bath	10 gal.
Aluminum	Machine Shop	Basis Metal	600 Lbs.
Stainless Steel	Machine Shop	Basis Metal	150 Lbs.

# B. PROCESS MATERIALS

Name	Location	Use	Storage Volume
1,1,1-trichloroethane	Cleaning Room	Degreasing	275 gal.
Sodium Hydroxide	Machine Shop	Dissolution of Aluminum Mandrels	2400 lbs.
Nitric Acid	Plating Dept.	Dissolution of Nickel from Aluminum Mandrel	60 gal.

# TABLE 1 (Continued

# C. WASTEWATER TREATMENT CHEMICALS

Name	Use	Stor Volu	age me
Calcium Hydroxide	pH adjustment	500	lbs.
Sodium Metabisulfite	Chromium reduction module	100	lbs.
Sulfuric Acid	pH adjustment	60	gal.
Sodium Hypochlorite	Cyanide oxidation module	100	gal.
Inhibitor LD	Cyanide oxidation module	5	gal.
Diphenylcarbazide Indicator	Chramic Acid spot test reagent	50	grans
Acetic Acid	Chromic Acid spot test reagent	500	mil.
Thyodene Indicator AR-16	Available chlorine titration test	2	pints
Sodium Thiosulfate	Available chlorine titration test	2	pints
Phenolphthalein Indicator	Cyanide spot test	50	cc.
Sodium Carbonate, anhydrous	Cyanide spot test	5	lbs.
Anmonium Hydroxide	Nickel spot test	100	CC.
Dimethylglyoximic Indicator	Nickel spot test	100	cc.
Potassium Icdate	Nickel spot test	100	cc.
Sodium Acetate	Copper spot test	200	cc.
Glacial Acetic Acid	Copper spot test	500	nıl.
Methyl Alcohol	Copper spct test	1	pint
Sodium Nitrate	Copper spct test	200	cc.

# TABLE 1 (Continued)

D. WASTE MATERIALS	c1	H.W. assification	Max. Storage Volume
Waste <u>Name</u>	Source —	D002	6000 gal.
Caustic Waste	Aluminum from Mickel parts Dissolution of	D002	330 gal.
Waste Acid	Degreasing unit	EOOl	275 gal.
TCE Still Bottoms	Wastewater Treatment	F006	1400 gal.
Wastewater Treatment Sludge	System  Metal Working	x726	300 gal.
Waste Cil			

#### SPILL AND LEAK PREVENTION AND RESPONSE

Areas where spills and leaks of potentially dangerous chemicals may occur have been identified so that particular attention can be given to appropriate pollution incident prevention measures. The following areas have been identified as the major areas where potential spills may occur:

Caustic Waste Storage Tank: The caustic waste generated from the dissolution of aluminum from nickel plated parts is currently stored in a 6000 gallon underground fiberglass tank. The tank is located beneath part of the driveway along the north side of the plant. If a leak were to develop in this tank, it would create a potential for soil and groundwater contamination. In order to prevent situation from occurring, Servometer intends to close the underground tank and replace it with an above ground system. The above ground system will be equipped with an automatic shut-off valve to prevent overfilling of the tank. It will also be easier to test and inspect the above ground system to prevent potential leaks from developing.

or leak should occur from the sulfuric acid bath used in the Plating Department, it would drain to the floor trough and be contained. From the floor trough it would be pumped to batch treatment in the waste treatment area. The Plating Department is under constant supervision and any potential for leak development would be identified and remedied before leading to an emergency situation.

المراجع المراجع

- o <u>l,l,l-Trichloroethane Unit</u>: A solvent vapor degreaser is in the Cleaning Room. Solvent is recycled in a closed loop within the unit. This minimizes the potential for a release of l,l,l-Trichloroethane. Still bottoms from the unit are routinely removed by a hazardous waste hauler.
- Plating Baths in the Plating Department: The floors in the plating areas are designed to collect any spillage and leakage and collect it in the floor spill sump. A sump pump will automatically transfer the floor spill to the batch treatment tank where it will be carefully tested and treated before discharge. The design of this system is such that no accidental discharges to the floor areas can find their way into the rinse water effluent and be diluted rather than treated prior to discharge.

Wastewater Treatment Area: If an unwanted discharge of treatment chemicals or waste residue occurs in this area, it will collect in a floor spill sump. The spilled material will automatically be transferred to a batch treatment tank before discharge.

# MATERIAL COMPATABILITY

Under normal conditions, materials used within the various production areas are compatable. The one exception is in the Plating Department where chlorine and cyanide in the Integrated Cyanide Treatment System can potentially generate a poisonous gas.

The Integrated Cyanide Treatment System is of the alkaline chlorination type designed to completely oxidize highly toxic cyanide into harmless carbon dioxide and nitrogen. This system consists primarily of a treatment rinse tank located in the plating line and a treatment solution reservoir located in the waste treatment area. The arrangement of the equipment is such as to provide for the addition of treatment chemicals to the treatment reservoir and recirculate the treatment solution between the reservoir to the treatment rinse tank. To provide satisfactory treatment, the treatment solution is maintained at a strength of 800 to 1200 ppm available chlorine and at a pH of 11.5-12.8.

Chlorine in contact with cyanide under the condition of depressed pH gives rise to the formation of toxic hydrogen cyanide and/or cyanogen chloride gases. Therefore, the pH of the treatment system is never allowed to fall below 9.5. In fact, it is automatically maintained at 12.5.

### INSPECTION AND MONITORING PROGRAM

A documented inspection schedule, separate from Servometer's PPC plan, has been prepared in accordance with the New Jersey Hazardous Waste Management Regulations. Information in this plan includes: a schedule of equipment and areas to be inspected; frequency of inspection; information to be recorded in an inspection log; copies of the inspection log sheets; and procedures to initiate corrective actions when problems are identified.

In addition to maintaining a documented copy of the program at the facility, a copy is on file with the New Jersey Department of Environmental Protection. Similar to the PPC Plan, the inspection schedule is reviewed periodically and updated to correspond with facility changes.

## PREVENTIVE MAINTENANCE/HOUSEKEEPING

The focus of the preventive maintenance program and good housekeeping practices is to eliminate conditions that could lead to accidental spills and safety hazards to plant personnel. In addition to addressing problems identified through the Inspection and Monitoring Program, the plant manager maintains a routine housekeeping program which includes:

- o Familiarizing employees with appropriate preventive maintenance procedures for their particular work area.
- o Assuring that work areas are kept clean and free of debris.
- o No Smoking signs are placed in appropriate places.
- o Assuring that correct labeling and placarding exists on all containers, process areas, work stations, buildings, exits, and entry points throughout the plant.
- o Documenting preventive maintenance inspection activities on the appropriate inspection log forms and maintaining them in the Facility Operating Record.

#### SECURITY

The regulations require that Servometer Corporation maintain security by minimizing the possibility for unauthorized entry by persons or livestock onto the active portion of the facility.

To meet these objectives, Servometer installed an alarm system which is tied in with all entrances. The system is also equipped with photo electric light beam sensors. At night, the facility is well lit both inside and out.

The facility operates 5 days/week, 24 hours/day. During working hours, all entrances and exits, except the main entrance, are locked. All visitors must register at the front entrance and be accompanied by a Servometer employee while in the facility. Warning signs are posted at the Plating Department entrances to ensure entry by authorized personnel only. During non-working hours, all entrances and exits are locked and a chain is secured across the driveway entrance.

### EXTERNAL FACTORS

Servometer Corporation should be minimally affected, from a safety standpoint, by external factors such as power outages, adverse weather condictions, and strikes. These factors are more likely to affect production output rather than safety.

During a power outage, production in all departments would cease. An extended power outage could cause serious losses of work-in-process in the Plating Department. Plating tanks are normally run 24 hours, 7 days per week for filtration purposes. A power outage would, therefore, affect the quality of the plating solution.

Although no emergency generator currently exists for long-term back up, Servometer is equipped with emergency flood lights and an emergency telephone system. In the event of a power outage, adequate lighting would exist to safely shut down production processes. The emergency phone system would be used to contact the power company and to call for other assistance if needed.

# INTERNAL AND EXTERNAL COMMUNICATIONS OR ALARM SYSTEMS

The facility is equipped with sufficient communication and alarm systems to provide immediate emergency instruction to facility personnel and to summon external assistance. Telephone and alarm systems are functional during power outages.

### EMPLOYEE TRAINING PROGRAM

All Servometer Corporation employees are given training to enable them to understand the processes and materials with which they are working, safety and health hazards, and practices for preventing and responding to spills. The program emphasizes training in emergency procedures and use of emergency equipment.

As required by the regulations, the Personnel Training Program is a documented program. In addition to training in emergency procedures, the training program covers other aspects of the PPC Plan such as inspection and monitoring, material compatability and housekeeping practices. Training records are also maintained which document specific employee training.

#### LIST OF EMERGENCY COORDINATORS

A primary coordinator and alternates have been designated the responsibility of coordinating activities during an emergency as specified in the following section. The Emergency coordinators for Servometer Corporation include:

Peter J. Holowachuk, President - Primary Coordinator

201/785-4630 (office)

201/839-3597 (home)

Jayne A. Holowachuk, Vice President-Treasurer - Alternate Coordinator

201/785-4630 (office)

201/934-6627 (home)

Louis Fejes, Assistant General Manager - Alternate Coordinator

201/785-4630 (office)

201/697-6174 (home)

Brian Itjen, Plating Foreman - Alternate Coordinator

201/785-4630 (office)

201/785-1297 (home)

At least one of these employees will be either on-site or on-call at all times. They are familiar with all aspects of the PPC Plan and have the authority to commit the resources necessary to carry out the PPC Plan.

#### DUTIES & RESPONSIBILITIES OF THE EMERGENCY COORDINATOR(S)

At all times, one of the emergency coordinators is either at the facility or on call. The emergency coordinator is familiar with all aspects of the facility's PPC plan, operations and activities at the facility, the location and characteristics of waste handled, the location of all records within the facility, and the facility layout. In addition, the coordinator has the authority to commit the resources needed to carry out the PPC plan.

In the event of an emergency, the emergency coordinator will immediately:

- activate facility alarms or communication systems to notify all facility personnel; and
- 2. notify local emergency response agencies if their help is needed.

Whenever there is a fire, explosion, emission, or discharge, the emergency coordinator will immediately identify the character, exact source, amount, and areal extent of any released materials. Concurrently, the emergency coordinator will assess possible hazards both direct and indirect, to human health or the local environment.

If the emergency coordinator determines that the facility has had an incident which could threaten human health or the environment, he will report his findings as follows:

If his assessment indicates that evacuation of local areas may be advisable, he will immediately notify appropriate local authorities. He will be available to help appropriate officials decide whether local areas should be evacuated; and

- 2. He will immediately notify the NJ Department of Environmental Protection (DEP) by telephone at 609/292-7927 and the National Response Center at 800/424-8802. Following the incident, a report concerning the event and any remedial actions taken will be prepared and will include the following information:
  - A. Name of the person reporting the incident.
  - B. Name, address, and identification number of facility.
  - C. Phone number where the person reporting the spill can be reached.
  - D. Date, time, and location of the incident.
  - E. A brief description of the incident including type of incident, nature of hazardous material involvement and possible hazards to human health or the environment.
  - F. The extent of injuries, if any.
  - G. For each material involved in the incident, the shipping name, hazard class, and quantity of the waste involved.

The report will be maintained in the Facility Operating Record within the Hazardous Waste Control files and updated into the PPC Plan on an annual basis.

During an emergency, the emergency coordinator will take all reasonable measures necessary to ensure that fire, explosion, emissions, or discharges do not occur, recur, or spread to other hazardous materials at the facility.

These measures will include, where applicable, stopping processes and operations, collecting and containing discharged waste, and removing or isolating containers. If the facility stops operations the emergency coordinator will monitor for leaks, pressure buildup, gas generation, ruptures in valves, pipes, or other equipment, where applicable.

Immediately after an emergency, the emergency coordinator will, with DEP approval, provide for treating, storing, or disposing of recovered waste, contaminated soil or surface water, or other materials destroyed by or associated with the contingency.

The emergency coordinator will ensure that, in the affected area of the facility:

- No waste that may be incompatible with the emitted or discharged material is treated, stored, or disposed of until cleanup procedures are completed; and
- All emergency equipment listed in the PPC plan is cleaned, replaced, if necessary, and fit for its intended use before operations are resumed.

# CHAIN OF COMMAND

In the event of an emergency or spill, the following employees should be contacted:

Peter J. Holowachuk, President

Office phone: 201/785-4630

Home phone: 201/839-3597

Jayne A. Holowachuk, Vice President-Treasurer

Office phone: 201/785-4630

Home phone: 201/934-6627

Louis Fejes, Assistant General Manager

Office phone: 201/785-4630

Home phone: 201/697-6174

Brian Itjen, Plating Foreman

Office phone: 201/785-4630

Home phone: 201/785-1297

### LIST OF AGENCIES TO BE NOTIFIED

In the event of an emergency or spill, the following local, state, and federal agencies may be notified. In the event of a major spill, at a minimum, the National Response Center and the New Jersey Department of Environmental Protection should be notified.

- \* o Cedar Grove Police, Fire, and Ambulance Service 201/239-4100
  - o Local Hospitals
    - Passaic General Hospital

201/365-4377

- St. Mary's Hospital

201/473-1000

\* o New Jersey Department of Environmental Protection

609/292-7927

609/292-5500

- \* o United States Environmental Protection Agency Region II 212/264-0980
  - o National Response Center

800/424-8802

o Suburban Essex Area Poison Control Center
201/992-5161

\*These organizations retain a copy of the PPC Plan for use in the event of an emergency.

### EMERGENCY EQUIPMENT

Emergency equipment is available to allow personnel to respond safely and quickly to emergency situations. Through the Personnel Training Program, employees are instructed on the availability, location, and use of emergency equipment. The following emergency equipment is provided by Servameter Corporation:

Equi	pment	Quantity
0	Portable fire extinguishers	17
0	Ladders	3
0	Stretcher	1
0	Portable lighting equipment	1
0	First aid kits	3
0	Self-contained breathing apparatus	1
0	Welding/cutting equipment	1
0	Portable pump	1
0	Chain hoist	2
0	Crane	1

### EVACUATION PLAN FOR FACILITY PERSONNEL

The second secon

The emergency coordinator on duty is responsible for determining when a facility evacuation is necessary.

Personnel have been instructed on evacuation procedures through the Personnel Training Program. Evacuation plans are posted in each department and include a diagram showing the route and exit to be used in case of an emergency.

### ARRANGEMENTS WITH EMERGENCY RESPONSE CONTRACTORS

The following Contractors are available to assist with the clean-up and disposal of hazardous substances in the event of an emergency. Although not required, most emergency response contractors prefer prior contact to provide information about the hazardous waste facility to enhance emergency preparedness. A brief description of the services provided and area served is provided below:

### 1. Advanced Environmental Technology Corporation (AETC)

24 hour Emergency Number - 201/347-7111

Contact - Andy Babij

AETC, located in Flanders, New Jersey, provides emergency clean-up and disposal services for any hazardous wastes including highly explosive materials. A staff of field technicians are on call 24 hours a day. Some of the equipment available includes a full range of personal protective equipment, material transfer and handling equipment and vacuum trucks. The major service area for AETC is New Jersey, Connecticut, Pennsylvania, Massachusetts, New York, Deleware, and Maryland.

### 2. SCA Services

24 hour Emergency Number - 201/465-9100

Contact - Chuck Boerner

SCA Services is a licensed hazardous waste disposal facility located in Newark, New Jersey. SCA does not routinely handle complete emergency response cases, however, they will provide these services on a case by case basis, depending upon the type of materials involved and environmental component involved.

### 3. O. H. Materials Inc.

24 hour Emergency Number - 800/537-9540

Contact - No specific contact required

O. H. Materials Inc. is a large-scale emergency response contractor with emergency team offices in 31 wide spread states. This outfit will clean-up and dispose of any hazardous material, including radioactive wastes. Service agreements are available to enhance preparedness but are not required.

### 4. Triangle Resource Industries

24 hour Emergency Number - 800/638-4442 (work hours)

800/638-4440 (after hours)

Contact - Walt Petzold

Triangle Resources Industries provide disposal services for Pack Laboratory Chemicals (PLC) in New Jersey and the surrounding states. Services include Pack, removal, and disposal of all types of laboratory chemicals.

### POLLUTION INCIDENT HISTORY


To date, there have not been any pollution incidents at Servometer Corporation. If any incidents occur in the future, they will be documented and incorporated into the Personnel Training Program so as to avoid a similar situation from occurring.

### PPC PLAN REVIEW

During the month of May each year, the PPC Plan will be reviewed by members of the PPC Plan Committee. The appropriate modifications will be made to reflect changes in plant operations or materials handling procedures.

In the space provided below, an authorized designate of the review committee must document that the review took place by signing his name and the date the review took place.

Authorized Signature	Review Date
1. File & Alowachuke 2. Jayne a. Holowachuke 3. Lau Fara	4-20-87 + 120/87 4/20/87
4. Brue 25th	4.20.87
5.	1 20 3 1
6.	
7.	
8.	



ACTION ITEMS:

```
TERRESTRIAL ORGANISMS
Shown in BROWN; species with special status shown in RED(F) or (5) indicates species protected by Federal or State Legislation (see text)
   SYMBOL
                                            SPECIES
                         PLANTS (301-350)
                                             Eastern hemlock
                                             Spleenwort
Spider lily
                                             Pond bush (S)
Watermilfoil (S)
                                              Hooded pitcher plant (S)
                                            Prickly pear cactus (S)
Trailing arbutus (S)
Eastern bumelia
Pitcher plant
                                             Baldcypress
Redbay
Seaside alder
Box huckleberry
                                             Purple fringeless orchid
Pink lady's slipper
Ebony spleenwort (S)
Orchids (S)
                                             Golden club
                                             Florida beargrass
East-coast coontie
Fall-flowering ixia
                                             Spoon-flower
Curtiss milkweed
                                              Sea lavender
                                             Needle palm
Yellow squirrel-banana
Beach creeper
Florida coontie
                                              Four-petal pawpaw
Bird's nest spleenwort
                                              Burrowing four-o'clock
Beach star
                                              Silver paim
                                              Dancing lady orchid
Tamarindillo
                                              Fuch's bromeliad
                                              Everglades peperomia
Buccaneer palm
                                             Slender spieenwort
Pineland jacquemontia
Mahogany mistletoe
Florida thatch
                                   347 Twisted air plant
348 Long's bittercress
349 Venus's flytrap
                           INVERTEBRATES (351-400)
                                   351 Monarch butterfly
352 Zebra butterfly
                           BIRDS (401-600)
                                   SHOREBIRDS (401-430)
                                                      Shorebirds
Terns
Gulls
                                            401
                                                      Forster's tern
Arctic tern
                                                      Roseate tern (S)
Common tern
Great black-backed guil
                                                       Laughing gull
Black skimmer (S)
Turnstones
                                                      Piping plover
American oystercatcher (S)
                                    WADING BIRDS (431-460)
                                            431
                                                       Wading birds
                                                       Herons
Egrets
Rails
Ibises
                                            433
                                                       Bitterns
Great blue heron (S)
                                                       Wood ibis (S)
                                                       Anhinga
Little blue heron (S)
Yellow-crowned night heron (S)
                                                       Black-crowned night heron Florida sandhill crane (S)
                                                      Florida sandhill crane (S)
Louisiana heron (S)
Limpkin (S)
Roseate spoonbill (S)
Snowy egret (S)
Magnificent frigate-bird (S)
Reddish egret (S)
Clapper rail
King rail
Virginia rail
Sora rail
                                     WATERFOWL (461-500)
                                                        Waterfowl
```

461

Swans

Harlequin duck Wood duck Fulvous tree duck

Geese Dabbling ducks Diving ducks Common eider

Newark

N. J.-N. Y.-PA.

69-805- -

40074-A1-E1-250

1:250 000-scale map of **Atlantic Coast** 


**Ecological Inventory** 





Produced by U. S. FISH AND WILDLIFE **SERVICE** 1980


AQUATIC ORGANISMS SPECIES PLANTS (1-50) 1 Irish moss 2 Rockweed NVERTEBRATES (51-100) Oysters Scallops Clams Worms Shrimp American lobster Blue crab Eastern oyster European cyster
Bay scallop
Deep-sea scallop
Calico scallop
Surf clam
Hard clam 63 64 65 66 67 68 Soft shell clam Brackish-water clam




ATLANTIC COAST ECOLOGICAL INVENTORY
NEWARK, N. J.-N. Y.-PA.
1980

General habitat boundary for indicated species; may be superceded by special


land use boundary . . . .






NEWARK 1234 6

.






## STATE OF NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION

DAVID J. BARDIN, COMMISSIONER


) TOF SEOL


### **LEGEND**

AREA SERVED BY PRIVATE WATER SERVICE COMPANIES
ARE A SERVED BY REGIONALLY OWNED WATER SERVICE COMPANIES
AREA SERVED BY MUNICIPALLY OWNED WATER SERVICE COMPANIES
AREA NOT PRESENTLY SERVED BY WATER SERVICE
PUBLIC SUPPLY WELLS
SURFACE WATER INTAKE
MAJOR WATER MAINS
TOWNSHIP BOUNDARIES
COUNTY BOUNDARIES
STATE BOUNDARIES
ALL MAP COORDINATES ARE FOR THE LOWER LEFT
HAND CORNER.



ANY CORRECTIONS OR ADDITIONAL INFORMATION WILL BE APPRECIATED







Surface Water Quality Standards N.J.A.C. 7:9-4

6. All waterways or waterbodies, or portions of waterways and waterbodies that are classified as PL only for those portions that are located within the boundaries of the Pinelands Area are classified as PL unless they are listed as FW1 waters in Index A. A tributary entering a PL stream is classified as PL only for those portions of the tributary that are within the Pinelands Area. Lakes are classified as PL only if they are located entirely within the Pinelands Area.

#### CLASSIFICATIONS:

FW1
FW2-TP -- FW2 Trout Production
FW2-TM -- FW2 Trout Maintenance
FW2-NT -- FW2 Non Trout
PL -- Pinelands Waters
SE1
SE2
SE3
SC

FW2-NT/SE1 (or similar designation) -- Indicates a waterway in which there may be a salt water/fresh water interface. The exact point of demarcation between the fresh and saline waters must be determined by salinity measurements and is that point where the salinity reaches 3.5 parts per thousand at mean high tide. The stream is classified as FW2-NT in the fresh portions (salinity less than or equal to 3.5 parts per thousand at mean high tide) and SE1 in the saline portions.

### **DESIGNATIONS:**

- (C1) -- Category 1 waters
- [tp] -- Indicates trout production in waters which are classified as FW1; this is for information only and does not affect the water quality criteria for any stream
- [tm] -- Indicates trout maintenance in waters which are classified as PL or FWl. For FWl this is for information only and does not affect the water quality criteria for any stream.

(Stockholm) - Brook between Hamburg Turnpike and Williamsville-Stockholm Rd. to its confluence with Lake Stockholm Brook, north of Rt. 23	FW1 [tm]
LITTLE POND BROOK (Oakland) - Entire length LOANTAKA BROOK	FW2-TP(C1)
(Green Village) - Entire length, except segment described below	FW2-NT
(Great Swamp) - Brook and all tributaries within the boundaries of Great Swamp National Wildlife Refuge	FW2-NT(C1)
LUD-DAY BROOK (Camp Garfield) - Source to confluence with a tributary from Camp Garfield	FW1
MACOPIN RIVER (Newfoundland) - Source to Echo Lake dam (Newfoundland) - Echo Lake dam to Pequannock River	FW2-NT FW2-TM
MEADOW BROOK (Wanaque) - Skyline Lake to Wanaque River	FW2-NT
MILL BROOK (Randolph) - Source to Rt. 10 bridge (Randolph) - Rt. 10 bridge to Rockaway River MORSES CREEK - Entire length MOSSMAN'S BROOK - See CLINTON BROOK	FW2-TP(C1) FW2-NT FW2-NT/SE3
MT. TABOR BROOK (Morris Plains) - Entire length NEWARK BAY (Newark) - North of an east-west line connecting Elizabethport with Bergen Pt., Bayonne up to the mouths of the Passaic and Hackensack Rivers	FW2-NT SE3
NOSENZO POND (Upper Macopin) OAK RIDGE RESERVOIR (Oak Ridge) OAK RIDGE RESERVOIR (Oak Ridge) - Northwestern tributary to Reservoir	FW2-NT(C1) FW2-TM FW1 [tm]
OVERPECK CREEK (Palisades Park) - Entire length  * PECKMAN RIVER (Verona) - Entire length PACACK BROOK	FW2-NT/SE2 FW2-NT
(Stockholm) - Source to Pequannock River, excluding Canistear Reservoir, except segments described separately below	FW2-NT
(Canistear) - Brook and tributaries upstream of Canistear Reservoir located entirely within the boundaries of the Newark Watershed	FW1
PASSAIC RIVER  (Mendham) - Source to Rt. 202 bridge  (Van Doren's Mill), except tributaries  described separately below	FW2-TM
(Paterson) - Rt. 202 bridge to Dundee Lake	FW2-NT
(Little Falls) - Dundee Lake dam to confluence with Second River	FW2-NT/SE2
(Newark) - Confluence with Second River to mouth	SE3



# Surface Water Quality Standards

### SURFACE WATER QUALITY STANDARDS

N.J.A.C. 7:9-4.1 et seq.

May 1985

once-through basis for the duration of the test, in accordance with N.J.A.C. 7:18.

"Fresh water(s)" means all nontidal and tidal waters generally having a salinity, due to natural sources, of less than or equal to 3.5 parts per thousand at mean high tide.

"FW" means the general surface water classification applied to fresh waters.

"FW1" means those fresh waters that originate in and are wholly within Federal or State parks, forests, fish and wildlife lands, and other special holdings, that are to be maintained in their natural state of quality (set aside for posterity) and not subjected to any man-made wastewater discharges, as designated in Index A incorporated into this subchapter.

"FW2" means the general surface water classification applied to those fresh waters that are not designated as FW1 or Pinelands Waters.

"Heat dissipation area" means a mixing zone, as may be designated by the Department, into which thermal effluents may be discharged for the purpose of mixing, dispersing, or dissipating such effluents without creating nuisances, hazardous conditions, or violating the provisions of this subchapter.

"Hypolimnion" means the lower region of a stratified waterbody that extends from the thermocline to the bottom of the waterbody, and is isolated from circulation with the upper waters, thereby receiving little or no oxygen from the atmosphere.

"Important species" means species that are commercially valuable (e.g., within the top ten species landed, by dollar value); recreationally valuable; threatened or endangered; critical to the organization and/or maintenance of the ecosystem; or other species necessary in the food web for the well-being of the species identified in this definition.

"Industrial water supply" means water used for processing or cooling.

"Intermittent stream" means a stream with a MA7CD10 flow of less than one-tenth (0.1) cubic foot per second.

"Lake, pond, or reservoir" means any impoundment, whether naturally occurring or created in whole or in part by the building of structures for the retention of surface water, excluding sedimentation control and stormwater retention/detention basins.

"LC50" means the median lethal concentration of a toxic substance, expressed as a statistical estimate of the concentration that kills 50 percent of the test organisms under

characteristics, but are suitable for a wide variety of other fish species.

"NPDES" means National Pollutant Discharge Elimination System.

"NT" means nontrout waters.

"Nutrient" means a chemical element or compound, such as nitrogen or phosphorus, which is essential to and promotes the growth and development of organisms.

"Outstanding National Resource Waters" means high quality waters that constitute an outstanding national resource (for example, waters of National/State Parks and Wildlife Refuges and waters of exceptional recreational or ecological significance) as designated in Index G incorporated into this subchapter.

"Persistent" means relatively resistant to degradation, generally having a half life of over 96 hours.

"Pinelands waters" means all waters within the boundaries of the Pineland Area, except those waters designated as FWl in this subchapter, as established in the Pinelands Protection Act N.J.S.A. 13:18A-1 et seq. and shown on Plate 1 of the "Comprehensive Management Plan" adopted by the New Jersey Pinelands Commission in November 1980.

"PL" means the general surface water classification applied to Pinelands Waters.

"Primary contact recreation" means recreational activities that involve significant ingestion risks and includes, but is not limited to, wading, swimming, diving, surfing, and water skiing.

"Public hearing" means a legislative type hearing before a representative or representatives of the Department providing the opportunity for public comment, but does not include cross-examination.

"River mile" means the distance, measured in statute miles, between two locations on a stream, with the first location designated as mile zero. Mile zero for the Delaware River is located at the intersection of the centerline of the navigation channel and a line between the Cape May Light, New Jersey, and the tip of Cape Henlopen, Delaware.

"Saline waters" means waters having salinities generally greater than 3.5 parts per thousand at mean high tide.

"SC" means the general surface water classification applied to coastal saline waters.

"SE" means the general surface water classification applied to saline waters of estuaries.

- (c) In all FW2 waters the designated uses are:
  - 1. Maintenance, migration and propagation of the natural and established biota;
  - 2. Primary and secondary contact recreation;
  - 3. Industrial and agricultural water supply;
  - 4. Public potable water supply after such treatment as required by law or regulation; and
  - 5. Any other reasonable uses.
- (d) In all SE1 waters the designated uses are:
  - 1. Shellfish harvesting in accordance with N.J.A.C. 7:12;
  - Maintenance, migration and propagation of the natural and established biota;
  - 3. Primary and secondary contact recreation; and
  - 4. Any other reasonable uses.
- (e) In all SE2 waters the designated uses are:
  - Maintenance, migration and propagation of the natural and established biota:
  - 2. Migration of diadromous fish;
  - 3. Maintenance of wildlife;
  - 4. Secondary contact recreation; and
  - 5. Any other reasonable uses.
- (f) In all SE3 waters the designated uses are:
  - 1. Secondary contact recreation;
  - 2. Maintenance and migration of fish populations;
  - 3. Migration of diadromous fish;
  - 4. Maintenance of wildlife; and
  - 5. Any other reasonable uses.
- (g) In all SC waters the designated uses are:
  - 1. Shellfish harvesting in accordance with N.J.A.C. 7:12:

### GRAPHICAL EXPOSURE MODELING SYSTEM

(GEMS)

### USER'S GUIDE

VOLUME 2. MODELING

### Prepared for:

U.S. ENVIRONMENTAL PROTECTION AGENCY
OFFICE OF PESTICIDES AND TOXIC SUBSTANCES
EXPOSURE EVALUATION DIVISION
Task No. 3-2
Contract No. 68023970
Project Officer: Russell Kinerson
Task Manager: Loren Hall

### Prepared by:

GENERAL SCIENCES CORPORATION 8401 Corporate Drive Landover, Maryland 20785

Submitted: December 1, 1986

### GEMS> I

### SERVOMETER CORPORATION

LATITUDE 40:52:10 LONGITUDE 74:13:26 1980 POPULATION

км	0.00400	.400810	.810-1.60	1.60-3.20	3.20-4.80	4.80-6.40	SECTOR
S 1	0	1584	8436	27211	63174	105896	206301
RING TOTA		1584	8436	27211	63174	105896	206301

GEMS> I

### SERVOMETER CORPORATION

LATITUDE 40:52:10 LONGITUDE 74:13:26 1980 HOUSING

км			.810-1.60			4.80-6.40	SECTOR TOTALS
S 1	0					38879	72629
RING	_	524	2971	8741	21514	38879	7262 <del>9</del>

	HUSES	POPULATION	DISTANCE
HOUSE COUNT OFF TOPO MA	35	133	0.25
	559	1717	0.5
	3530	10.153	1
	12,271	37,364	2
	33, 785	100, 538	3
	72,664	206, 434	4

gotteel July



## Etate of New Jersey DEPARTMENT OF ENVIRONMENTAL PROTECTION DIVISION OF WATER RESOURCES

DIVISION OF WATER RESOURCES CN 029 TRENTON. NEW JERSEY 08625

GEORGE G. McCANN, P.E.

DIRK C. HOFMAN, P.E. DEPUTY DIRECTOR

Certified Mail
Return Receipt Requested

Peter Holowachuk, President Servometer Corporation 501 Little Falls Road Cedar Grove, NJ 07009

AUG 20 1987

Dear Mr. Holowachuk:

Re: Response to comments and issuance of Final New Jersey Pollutant Discharge Elimination System (NJPDES) Discharge to Ground Water (DGW) Major Modification of existing NJPDES Discharge to Surface Water (DSW) Permit NJ0027847.

The following represents the New Jersey Department of Environmental Protection's (Department) response to comments submitted to the Department during the public comment period for the Draft Permit.

The comments submitted by the Servometer Corporation consisted of a letter detailing the history of the closure of the hazardous waste underground storage tank that initiated the issuance of the DGW Major Modification referenced above. Specific comments from the letter, with the Department response, follow.

### Comments:

"Servometer Corporation feels the subject draft modification and associated ground water monitoring requirements are unwarranted. This position is based upon results of the site investigation conducted in February 1987, and previous statements made by the Division of Waste Management regarding the necessity for ground water monitoring at the site."

"In March, 1986 the closure plan for the underground storage tank was submitted to DEP for review. Mr. Frank Coolick, Division of Waste Management, issued a comment letter dated April 23, 1986 which indicated closure of the underground tank would not necessarily exempt Servometer from ground water monitoring requirements. The letter also stated that the closure plan was submitted to the Division of Water Resources for review and that

'You will be notified by this bureau of the results of the Division of Water Resources review'."

"On March 26, over one month after the site investigation had been implemented, closure approval was given in a letter from Mr. Coolick. This letter indicated that Servometer would be subject to the ground water monitoring requirements of NJAC 7:14A-6. Based upon prior verbal approval of the site investigation, Servometer assumed that this reference to ground water monitoring was in the event soil contamination was identified."

"On April 28, Mr. Mejia informed Mr. Dale Skoff of Lancy Environmental Services that both he and Mr. Stephen Urbanik of the Division of Water Resources had reviewed the report and concurred with the recommendations."

Response: As was stated in the cover letter of the Draft Permit, the New Jersey Hazardous Waste Regulations, N.J.A.C. 7:26-1 et seq., and the NJPDES Regulations are the basis for ground water monitoring at all underground hazardous waste storage tank sites, not preliminary discussions held between representatives of the Department. Section 7:14A-6.15 (i) 4. of the NJPDES Regulations specifically mentions closure/post-closure monitoring:

"The owner or operator shall determine groundwater quality at each groundwater monitoring well at the compliance point as specified in the permit, but at least semi-annually during the active life of a regulated unit (including the closure period) and the post-closure care period."

Although the Department did not explicitly state that ground water monitoring would be required in previous correspondence, actions taken on closure are done 'at risk' until final closure approval is given in writing. The final closure plan approval states that "Servometer shall be subject to the ground water discharge permit requirements of N.J.A.C. 7:14A-6 for ground water monitoring." There is no statement that this condition is based on the results of the soil sampling and in fact the plan was approved "subject to the following conditions..." (including the ground water monitoring). Further, in a phone conversation on February 18, 1987 between Mr. Skoff and Mr. Urbanik, it was stated by Mr. Urbanik that a final decision on ground water monitoring would not be made until the final closure approval was Although approval of closure based on soil sampling alone was discussed between the Division of Water Resources-Bureau of Ground Water Quality Management (BGWQM) and the Division of Waste Management-Bureau of Hazardous Engineering (BHWE), these were discussions only. The result of these discussions was that ground water monitoring would be required expressly because it is a regulatory requirement. The Department does not issue verbal approvals of such work actions precisely to avoid such confusion over regulatory requirements.

### Comments:

"The site investigation, which consisted of sampling and analyses of eight soil borings in the vicinity of the underground tank and associated piping, showed that soil contamination did not exist in the vicinity of the tank. Based on these results, the 'potential' for discharge to ground water from the tank is for practical purposes non-existent."

"Servometer initiated this boring program after it was confident, based upon statements from the Division of Waste Management, that ground water monitoring would not be required unless soil contamination was identified from the boring program results."

"The final site investigation report was submitted to the Division of Waste Management on April 22, 1987. The report concluded that the tank had not leaked and that ground water monitoring was not necessary."

"Servometer recognizes that the cost of compliance should not be a consideration in enforcement of regulations. However, it should be noted that if Servometer is required to install ground water monitoring wells at this time, costs will be greatly increased over what the costs would have been by doing so as part of the February site investigation. For example, Servometer has drilled and backfilled borings which are in monitoring well locations required by the permit."

Response: The fact that analyses of soil samples indicates levels which are below acceptable limits for soil does not relieve a facility from ground water monitoring. Rather, a full soil/water scan must be completed. Complex soil/water interactions limit the value of soil testing as the only sampling mechanism utilized. Further, ground water standards are well below soil limits and the tank may have been located below the seasonally high ground water table. The soil borings did indicate moist and/or wet conditions.

It is difficult to coordinate a BHWE closure plan with the issuance of a NJPDES DGW Permit containing ground water monitoring requirements due to the constraints of public notice requirements. The Department recognizes the expense involved, but a monitoring system should have been in place since October of 1982 when the hazardous waste regulations went into effect and while the tank was in operation. Therefore, Servometer Corporation has been out of compliance with the hazardous waste regulations since October of 1982. This Permit Modification will bring the facility into compliance with these regulations.

The list of parameters to be sampled in the permit is less stringent than that required by the soil sampling and the NJPDES Regulations allow for relaxation of sampling parameters should ground water be within the Permit specified limits. In short, requirements are well below the minimum regulatory requirements for hazardous waste tank closures of this sort.

Enclosed is the previously Public Noticed Major Modification to your existing NJPDES/DSW Permit. This Modification is added to and made part of your Permit. This Major Modification is issued in accordance with the New Jersey Pollutant Discharge Elimination System Regulations, N.J.A.C. 7:14A-1 et seq. and you are required to comply with the terms and conditions of this Permit.

Within thirty (30) calendar days following your receipt of this Permit Modification, you may submit a request for an adjudicatory hearing to reconsider or contest the conditions of this Permit. Regulations regarding the format and requirements for requesting an adjudicatory hearing may be found in N.J.A.C. 7:14A-8.6 through 8.13. The request should be made to:

Administrator
Water Quality Management Element
Division of Water Resources
CN-029
Trenton, New Jersey 08625

If you have any questions on this action, please contact Stephen J. Urbanik of the Industrial Permits Section of the Bureau of Ground Water Quality Management at (609) 292-0424.

Sincerely yours

Robert Berg, Chief

Bureau of Ground

Water Quality Management

WQM204

**Enclosures** 

#### FACT SHEET

FOR THE NJPDES PERMIT TO DISCHARGE INTO THE GROUND WATERS OF THE STATE

#### Name and Address of Applicant:

Servometer Corporation 501 Little Falls Road Cedar Grove, NJ 07009

#### Name and Address of Facility Where Discharge Occurs:

Servometer Corporation 501 Little Falls Road Cedar Grove, NJ 07009

#### Receiving Water:

Ground Waters of the State. Glacial and alluvial overburden of the site is underlain by interbedded shale and sandstone of the Triassic Brunswick Formation and Triassic Watchung Basalt.

#### Description of Facility:

The Servometer Corporation manufactures metal bellows, couplings, contacts, and other metal components used in the manufacture of control valves and other related metal assemblies. Copper and nickel electroplating of aluminum parts is a major part of the operation (SIC Codes 3679, 3769, 3811, and 3823).

The following New Jersey hazardous wastes are generated in these operations:

D002--Caustic and acid waste.

F001--1,1,1 Trichloroethane solvent degreaser sludges.

F006--Plating wastewater treatment sludge.

X726--Waste machine oil.


Caustic waste will be stored in an above ground storage tank on closure of the existing 6,000 gallon capacity carbon steel underground caustic waste storage tank. This and other hazardous waste is transported off site for proper disposal. Non-hazardous waste treatment is regulated by the Discharge to Surface Water (DSW) portion of this permit.

## Description of Discharge:

This permit will assess any possible impacts on ground water quality from a 6,000 gallon capacity carbon steel underground caustic waste storage tank utilized from the Fall of 1974 until the Spring of 1987 to store caustic waste (D002). This tank may be in contact with the seasonally high ground water table.

#### Permit Conditions:

According to the attached General and Specific Conditions.





Water Resources

## STATE OF NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION CN 402

Trenton, N.J. 08625

#### **PERMIT**



58:10A-1 et seq. NJ0027847

The New Jersey Department of Environmental Protection grants this permit in accordance with your application, attachments accompanying same application, and applicable laws and regulations. This permit is also subject to the further conditions and stipulations enumerated in the supporting documents which are agreed to by the permittee upon acceptance of the permit. **Expiration Date** Permit No. Issuance Date Oct. 9, 1984 Effective Date Dec. 1, 1984 Revised: Sept. 1, 1987 NJ0027847 Revised: Oct. 1, 1987 November 30, 1989 Name and Address of Applicant Location of Activity/Facility Name and Address of Owner Servometer Corporation 501 Little Falls Road Servometer Corporation 501 Little Falls Road Cedar Grove, NJ 07009 501 Little Falls Road Cedar Grove, NJ 07009 Cedar Grove, NJ 07009 Statute(s) N.J.S.A. Type of Permit NJPDES-DSW/DGW Issuing Division Application No.

This permit requires the Servometer Corporation to:

monitor for any past and/or potential discharges to ground water from the use of a 6,000 gallon capacity carbon steel underground caustic waste storage tank. Ground water quality will be onitored according to the general and specific conditions of the permit.

Major Modification

Existing discharge to surface water (DSW) permit requirements are not changed through this permit ction and the permittee is not relieved from any of the requirements of the previously ssued permit.

Approved by the Department of Environmental Protection BY AUTHORITY OF:

GEORGE G. MCCANN, P.E., DIVISION OF WATER RESOURCES

ARNOLD SCHIFFMAN, ADMINISTRATOR WATER QUALITY MANAGEMENT

DATE

Part I-DGW-7-Closure/Post-Closure Page 1 of 4 (NJ0027847

GROUND WATER MONITORING REQUIREMENTS AND LIMITATIONS

The permittee shall install and sample a total of four ground water monitoring wells according to the schedule below. All ground water elevations <u>must</u> be determined prior to pumping and sampling the wells. Sampling of the wells shall be performed according to the methodology specified in Section 6.12 of the NJPDES regulations and the Department's <u>Field Procedures Manual for Water Data Acquisition</u>. The permittee shall sample for all parameters listed below. Sampling shall be performed and reported during the months which are specified for that parameter.

DADAMEMED	. TMTM3	TT ON	SZ	AMPLIN		SAMPLE		PORTI	1G
PARAMETER Elevation of top of i	LIMITA'			MONTI To Be		$\frac{\text{TYPE}}{\text{N/A}}$		MONTH JULY	OCT
well casing with cap				termin	_	11, 21	****	JAN	001
(to be determined one	ce but			On				0-2.	
reported as indicated			Inst	tallat	ion				
	•								
Depth to Water Table	from	top	MAR	JUNE	SEP	N/A	APR	JULY	OCT
of casing with cap re	emoved	•		DEC				JAN	
prior to sampling									
Depth to Water Table			MAR	JUNE	SEP	N/A	APR	JULY	OCT
original ground leve	l prio	r		DEC				JAN	
to sampling			-						
Aluminum		~~m	MAD	JUNE	CED	Grab	7 DD	JULY	OCT
Aluminum		ppm	MAK	DEC	SEP	Grab	AFK	JAN	OCI
				DEC				UAN	
Chromium (Hex.) &	0.05	ppm	MAR	JUNE	SEP	Grab	APR	JULY	ОСТ
Compounds	0.05	PP		DEC	0.01	0242		JAN	001
oompounab				220				0	
Chromium (Total)		ppm	MAR	JUNE	SEP	Grab	APR	JULY	OCT
				DEC				JAN	
Copper	1.0	ppm	MAR	JUNE	SEP	Grab	APR	JULY	OCT
				DEC				JAN	
Cyanide	0.2	ppm	MAR	JUNE	SEP	Grab	APR	JULY	OCT
				DEC				JAN	
Nickel		ppm	MAR	JUNE	SEP	Grab	APR	JULY	OCT
				DEC				JAN	
TT	<b>-</b> 0	su	MAD	TIINIT	מפט	Grab	ממג	JULY	OCM
рН	5-9	50	MAR	JUNE	SEP	Grab	APR	JAN	OCI
				DEC				OAN	
Total Volatile	*1	ppb		JUNE		Grab		JULY	
Organics by GC/MS	*	PPD		OUND		Orab		0011	
organics by GC/FIS									
Zinc & Compounds	5	mqq	MAR	JUNE	SEP	Grab	APR	JULY	OCT
22	_	E F		DEC		<del>-</del> <del>-</del>		JAN	

#### NOTES

<sup>\*1</sup> Volatile Organic Toxic Pollutants as defined in N.J.A.C. 7:14A-1.1 et seq., Appendix B can be reasonably divided into two classes; (A) carcinogens and (B) non-carcinogens.

Part I-DGW-7-Closure/Post-Closure Page 2 of 4 ( NJ0027847

Any chemical demonstrated to be carcinogenic to humans or experimental animals in a test peer-reviewed by either the National Toxicology Program of the U.S. Department of Health and Human Services or the International Agency for Research on Cancer will be considered to be a carcinogen (NJDEP Group A).

Chemicals which do not meet the criteria for placement NJDEP Group A will be placed in NJDEP Group B. NJDEP Group B is further divided into Group B-1, chemicals for which no State or Federal maximum contaminant level (MCL) exists, and Group B-2, chemicals for which a State or Federal MCL exists. Where both a State and Federal MCL exists, the more stringent shall apply. If any applicable State or Federal standard, limitation or prohibition is more stringent than limitation on the pollutant than the State or Federal the more stringent shall apply. Chemicals in NJDEP Group B-1 which do not currently meet the criteria for placement in NJDEP Group B-2 shall be transferred to NJDEP Group B-2 they meet the criteria for placement in NJDEP Group the future. Chemicals which do not currently meet the criteria for placement in NJDEP Group A will be placed in NJDEP Group B-1 or NJDEP Group B-2 and shall be transferred to NJDEP Group A if they meet the criteria for placement in NJDEP Group A in the future.

Currently, based upon scientific consensus, the following shall comprise NJDEP Group A and NJDEP Groups B-1 and B-2:

#### Group A

acrylonitrile
benzene
carbon tetrachloride
chloroform
1,2-dichloroethane
1,1-dichloroethylene
methylene chloride
1,1,2,2-tetrachloroethane
tetrachloroethylene
trichloroethylene
vinyl chloride
1,1,2-trichloroethane

#### Group B

acrolein
bromoform
chlorobenzene
chlorodibromomethane
chloroethane
2-chloroethylvinyl ether
dichlorobromomethane
1,1-dichloroethane
1,2-dichloropropane
1,3-dichloropropylene
ethylbenzene
methyl bromide
methyl chloride
toluene
1,2-trans-dichloroethylene

#### Group B-2

MCL\*

1,1,1-trichloroethane 200

\*EPA Proposed

Chemical compounds classified in NJDEP Group A are carcinogens and pose some level of risk even at low doses.

40 CFR Part 136-Method 624 shall be used to identify and monitor for the volatile organic compounds identified in Appendix B of the NJPDES Regulations. The GC/MS method 624 shall be utilized until the concentration of the constituents reach the corrective action criteria or the method detection limit, which ever is higher. If the method 624 method detection limit is higher than the corrective action criteria, 40 CFR Part 136 Methods 601, 602 and/or 603 shall then be utilized until the mandated corrective action criteria are achieved.

#### Corrective Action Criteria

- A. The corrective action criteria for ground water of 5 parts per billion (ppb) shall apply to individual chemical compounds classified in NJDEP Group A. Hence, the concentration of any compound in NJDEP Group A shall not exceed 5 parts per billion in ground water.
- B. The corrective action criteria for ground water of 50 parts per billion total Volatile Organic Toxic Pollutants shall apply to the sum of all compounds listed in NJDEP Group A and NJDEP Group B-1. Hence, the concentration of the sum of all compounds listed in NJDEP Groups A and B-1 shall not exceed 50 parts per billion in ground water.
- C. The corrective action criteria for ground water for the compounds listed in NJDEP Group B-2 shall be equal to or less than their individual State or Federal MCL, the more stringent shall apply. Hence, the concentration of any compound in NJDEP Group B-2 shall not exceed it's MCL in ground water.

The permittee shall complete the forms required on the "Monitoring Report - Transmittal Sheet" (Form T-VWX-014) which is included as a part of this Permit. Failure to submit sampling data on the forms required on the "Monitoring Report - Transmittal Sheet" shall be considered by the Department to be a violation of the Permit sampling requirements and may place the Permittee subject to civil and administrative penalties pursuant to N.J.S.A. 58:10A-10. It shall be solely the Permittee's responsibility to maintain an adequate supply of the required report forms.

Satisfactory ground water monitoring wells are defined in Section 6.13 of the NJPDES regulations and shall be subject to Departmental approval. If ground water monitoring wells do not meet these standards, they must be replaced with new wells meeting Departmental standards.

Part I-DGW-7-Closure/Post-Closure Page 4 of 4 ( NJ0027847

A Ground Water Monitoring Well Certification (Forms A and B) shall be completed for each existing and proposed monitoring Information for each well must be shown on a separate For an existing well, if the information required on the form. Ground Water Monitoring Well Certification (Forms A and B) cannot be determined or the ground water monitoring well is not adequately constructed to meet the requirements of this Permit, the Department reserves the right to require a replacement well. Criteria to be used by the Department in judging the adequacy of a well will be related to the ability of the well to provide a representative ground water sample at any time of the year specified by the Permit. Any replacement well must be installed within a 10 foot radius of the existing well. Inadequate or damaged existing wells must be properly sealed pursuant to 58:4A-4.1. Instructions regarding sealing may be N.J.A.C. obtained by contacting the Water Allocation Office at (609) 292-0580.

Form T-VWX-014 (

NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION
DIVISION OF WATER RESOURCES

## MONITORING REPORT - TRANSMITTAL SHEET

		NJPDES NO.		REPORTING PERIOD  MO. YR. MO. YR.		
		0101217181417		THRU THRU	i	
PERMITTEE:	Name	Servometer Corpo	ration			
	Address	01 Little Falls	Road			
	9	Cedar Grove, NJ	07009			
FACILITY:	NameS	Servometer Corpo	ration			
		501 Little Falls	Road			
		Cedar Grove, NJ		(County) Essex		
	Telephone	(201) 785-46	30			
FORMS ATTAC	HED (Indica	te Quantity of Each)		OPERATING EXCEPTIONS		
SLUDGE REPORT	S - SANITARY	Y			YES	NO
T-VWX-00	)7T.	.vwx.008	X-009	DYE TESTING		
SLUDGE REPORT	S - INDUSTRI	AL		TEMPORARY BYPASSING		
T-VWX-01	IDA T	VWX-010B		DISINFECTION INTERRUPTION		
WASTEWATER RE	PORTS			MONITORING MALFUNCTIONS UNITS OUT OF OPERATION		
T-VWX-01	1т.	VWX-012T-VW	X-013	OTHER		
GROUNDWATER  4 VWX-015		wx-016vwx	017	(Detail any "Yes" on reverse side in appropriate space.)		
NPDES DISCHAR	SE MONITOR	ING REPORT		NOTE: The "Hours Attended at Pk		
EPA FOR	M 3320-1			reverse of this sheet must also be con	npleted.	
AUTHENTICAT	infor of th subm	mation submitted in lose individuals immo nitted information is	this doc ediately : true, acc	t I have personally examined and am factorized that the sument and all attachments and that, by responsible for obtaining the informationate and complete. I am aware that the sum and including the possibility of firmation including the possibility.	ased on on, I be there ar	n my inquiry elieve the re significant
LICENSED OPE	RATOR			PRINCIPAL EXECUTIVE OFFICER of DULY AUTHORIZED REPRESENTATIVE	E	
Name (Printed)				Name (Printed)		
Grade & Registry	No		<del></del>	Title (Printed)		·· <del>···································</del>
Signature				Signature		
Date	,			Date		

#### NEW JERSE

## PARTMENT OF ENVIRONMENTAL PROTECTION OF WATER RESOURCES

#### WATER QUALITY MANAGEMENT ELEMENT

#### GROUND WATER ANALYSIS - MONITORING WELL REPORT

		YN									OINT PEN	Is	WI	D I	νo									
	Servometer Corporation Swib No.																							
	<u> </u>	ME													_									
	NJPDES NO. WELL PERMIT NO. SAMPLE DATE YR. MO.   DAY  NJ Q Q 2 7 8 4 7  9											OM	USE											
TI	HE S	CHI	EDL	JLE	INE	DICA	TE	D E	3E	LO	W IS TO BE OBSERVED FROM MO. YR. TO	MO. YR.												
											SUBMIT WITH SIGNED T-VWX-	014												S
SAMPLING MONTHS  [ 설 : : : : : : : : : : : : : : : : : :										.=		REMARKS												
1	Š	Ą	ANALYSIS UNITS PARAM								-	En			٧,	· L C	,E		ᆵ					
	x			x		K				x	Elevation of top of well casing with cap off (as specified in well completion report)	feet MSL: to nearest .01												
	х			x		Х				x	Elevation of original ground level (as specified in well completion report)	feet MSL: to nearest .01												T
	х	·		x		Х		T	7	x	Depth to water table from top of casing prior to sampling with cap off	feet: to nearest .01	8	2	5	4	E	3	T					T
	x			х		X		T		x	Depth to water table from original ground level prior to sampling	feet: to nearest .01	7	2	0	1	9	7					T	T
	X			Х		X		T	ŀ	x	Aluminum, Dissolved	UG/L as A1	0	1	l	10	) !	5	T					$\top$
							T	T	7		Barium, Dissolved	UG/L as Ba	0	1	0	C	, [	5	1	1			1	T
	Ì				i		T		i		Biochemical Oxygen Demand - 5 Day	MG/L	0	0	3	1		5	Ī			i	1	$\top$
	T	T				$\top$	T	T	1		Cadmium, Dissolved	UG/L as Cd	0	1	0	2	2 !	5	T					T
	T	Τ		П			7	T	1		Chloride, Dissolved	UG/L as CI	8	2	2	9	) !	5	Ť					T
	X			x		- X		T	7	x	Chromium, Dissolved	UG/L as Cr	0	1	0	3	1	o T			Г		$\exists$	7
	Х	_	T	х		x		T	-	х	Chromium, Dissolved, Hexavalent	UG/L as Cr	0	1	2	2	2 0	5						T
	T	T	T	П		丁	T	T	1	-	Chemical Oxygen Demand (COD), Dissolved	MG/L	0	0	3	4	1	1	T					T
Π	T	T	Τ	П		1		1	7		Coliform Group	N/100 ML	7	4	0	5	5 6	3				П		T
	1	T		П		T		T	1		Color	Pt - Co	0	0	0	18	3 0	7					1	T
	X		Π	х		X		T		x	Copper, Dissolved	UG/L as Cu	0	1	0	4	1	5	T			П		T
	Х			Х		Х		T		X	Cyanide, Total	MG/L as CN	0	0	7	2	2 0	न		T		П		T
	T	1	Γ	П			T	T	7	·	Endrin, Total	UG/L	-	-	-	9	_		T					T
	T						-	T			Fluoride, Dissolved	MG/L as F	-	<del>, -</del>	_	5	-		1	T			1	T
	T	1						T	1		Gross Alpha, Dissolved	Pc/L	<del> </del>	<del></del>	+	C	_		T	T		П		T
	T	1	T	П		7	T	$\top$	7		Gross Beta, Dissolved	Pc/L	_	-	_	C	_	_	1	T		П	1	T
	T		T	П			T	T	7		Hardness, Total as CaCO <sub>3</sub>	MG/L	•	•	-	C	-	_	1				1	T
	1					$\top$	T	1	7		Iron, Dissolved	UG/L as Fe	0	1	0	4	1	5	T	T			$\exists$	T
				П		$\neg$	1	$\top$	$\exists$		Lead, Dissolved	UG/L as Pb	0	1	C	4	1	9		T				T
	х		T	x		X				x	Nickel, Dissolved	UG/Las Ni	0	1	(		61	7	T	1				T
	х	$\neg$	_	х		X	_	T		X	pH Standard Units 0 0 4 0 0							T						
П	x	T		x		x	T	1	6	x l	Zinc, Dissolved	UG/Las Zn							Ī	1			1	$\top$
				استند					_•	الت	<u> </u>		29		_	_	٠.	33 3		—				40 41

## DEPARTMENT OF ENVIRONMENTAL PROTECT DIVISION OF WATER RESOURCES WATER QUALITY MANAGEMENT ELEMENT

## **GROUND WATER ANALYSIS - VOLATILE ORGANICS REPORT**

PLEASE TY	PE OR PRINT WITH BALLPOINT	PEN			
FACILITY	NAME Servometer Corp	oration		SW ID NO.	
LAB NAME					
Ţ	NJPDES NO. NJ 0 0 2 7 8 4 7	WELL PERMIT NO.	SAMPLE DATE YR.   MO.   DAY	NJ LAB CERT. NO.	WQM USE
THE SCHE	EDULE INDICATED BELOW IS TO		YR. TO MO. YR.		

### SUBMIT WITH SIGNED T-VWX-014

Feb.	Mar.	Apr.	Page 4	July	Aug.	Sept	Č	Z S	Ö Ö	ANALYSIS	UNITS	P	AR	MA	ETE	R			VA	LU	E		,
		T	x	Γ	Τ	Γ	Γ	Τ	Γ	Acrylonitrile	UG/L	3	4	2	1	5	1		П			$\top$	1
Π.		1	1	Г			Τ	Т	Π	Benzene	UG/L	3	4	0	3	0	Π		П	П	П	T	
		$\top$	$\top$		T		Τ	T		Bromoform	UG/L	3	2	1	0	4			$\Box$	$\neg$	П	T	Ī
П	T		П	Γ	T	Г	Γ	Τ		Carbon Tetrachloride	UG/L	3	2	1	0	2	П		П	コ	T	T	
	7		11				ŀ	Τ		Chlorobenzene	UG/L	3	4	3	0	1	ı		$\Box$	$\exists$	$\Box$	T	
			11	Π			Γ	T	Г	Chlorodibromoethane	UG/L	3	4	3	0	6	T		П	ヿ	$\Box$	T	-
	7	1	$\Pi$	Γ	1		Γ			Chloroform	UG/L	3	2	1	0	6	1		$\Box$	ヿ	$\sqcap$	丁	_
	T	1	$\top$				Γ			1, 1 - Dichloroethane	UG/L	3	4	4	9	6			$\Box$	ヿ	$\top$	丁	٦
	7	$\top$	$\Pi$				Γ	Τ		1, 2 - Dichloroethane	UG/L	3	4	5	3	1	Г			$\neg$	$\Box$	$\top$	٦
	1	$\top$	$\prod$				Γ			1, 1 - Dichloroethylene	UG/L	3	4	5	0	1			$\Box$	$\exists$	$\neg$	$\top$	-
	$\exists$	$\top$	$\prod$		1		Г			1, 2 - Dichloropropane	UG/L	3	_	5	4	1	Π		$\sqcap$	7		1	-
		$\top$	$\top$					Τ		Ethylbenzene	UG/L	3	4	3	7	1	Τ		П	$\neg$	$\sqcap$	$\top$	-
$\top$	T	$\top$	11		Π		Γ			Methylene Chloride	UG/L	3	4	4	2	3	Г		П	$\neg$	$\sqcap$	$\top$	-
	T	T	$\prod$				Τ	Г	Г	1, 1, 2, 2 - Tetrachloroethane	UG/L	3	4	5	_	6	Т		П	$\neg$	$\Box$	$\top$	_
$\sqcap$	1	$\top$	$\top$				Γ			Tetrachloroethylene	UG/L	3	4	4	7	5	Г		$\Box$	$\neg$	$\sqcap$	$\top$	_
			$\Pi$		Τ		Γ	T		Toluene	UG/L	3	4	0	1	2				$\neg$	$\sqcap$	$\top$	
	$\top$	$\top$	1	Γ			Γ			1, 1, 1 - Trichloroethane	·UG/L	3	4	5	0	6			П	$\neg$	$\sqcap$	$\top$	
			11				Т			1, 1, 2 - Trichloroethane	UG/L	3	4	5	1	1	Г				T	$\top$	
$\Box$	T	7	T		Τ		Τ			Trichloroethylene	UG/L	3	9	1	8	0			$\Box$		$\Box$	$\top$	_
,			11	Γ			Τ	Τ	Γ	Vinyl Chloride	UG/L	3	9	1	7	5	1					$\top$	_
$\Box$	$\top$	$\top$	$\prod$		Γ		Γ	T		Acrolein	UG/L	3	4	2	1	0					$\Box$	$\top$	_
		$\top$	11		Τ		Γ	T		Chloroethane	UG/L	3	4	3	1	1	1		П	$\Box$	一	$\top$	
	T	T	$\top$				Γ	T		2 - Chloroethylvinyl Ether	UG/L	3	4	5	7	6					T		_
$\Box$	T	7	$\dagger \dagger$		1			T		Dichlorobromomethane	UG/L	3	2	1	0	5	Г		$\Box$	$\neg$	$\sqcap$	1	
	T	T	11				Γ	T		1, 3 - Dichloropropylene	UG/L	3	_	6	-	9	-		П		$\sqcap$	十	_
$\sqcap$	7	十	11	Τ	T		T			Methyl Bromide	UG/L	3	4	4	1	3	1	1	$\Box$	$\neg$	$\sqcap$	十	-
	1	+	#	-	_		Τ	T		Methyl Chloride	UG/L	3	4	4	1	8	t	-	H	$\dashv$	$\sqcap$	+	-
	+	+	V	1	1		T	T	T	1, 2 - trans - Dichloroethylene	UG/L	3	<del></del>	+-	-	+	-	_	-	$\dashv$		+	-
$\Box$	$\top$	+	Ť		1		T	T	T	1, 2 Dichlorobenzene	UG/L	3		+	4	+	+-	$\vdash$	$\vdash \uparrow$	$\dashv$		+	-
	1	1	$\top$				١.	1		1, 3 Dichlorobenzene	UG/L	3	_	+-	+		_	Г	$\Box$	$\neg$	$\top$	$\top$	
								Ι		1, 4 Dichlorobenzene	UG/L	. 29 42 55 68	4	+	_	1	3 34 3 47 9 60 2 73		$\Box$	$\exists$		$\top$	

#### Special Conditions for all NJPDES/DGW Permits

- 1. All ground water monitoring wells shall be installed by a licensed New Jersey well driller, pursuant to N.J.S.A. 58:4A-6. A valid New Jersey permit, issued pursuant to N.J.S.A. 58:4A-14, to drill a well must be obtained from the Water Allocation Office, (609) 292-0580 of the Division of Water Resources prior to installation of any ground water monitoring wells. The permittee shall provide the Industrial Permits Section of the Bureau of Ground Water Quality Management ((609) 292-0424) a minimum of two weeks notification prior to the installation of any ground water monitoring wells required within this permit.
- 2. All new wells shall be constructed according to the attached Department specifications. All new wells shall be logged using the U.S.D.A. Soil Textural Classification System. For sites where inadequate geological information is available to properly design the well specifications, a Department geologist will finalize the well specifications prior to drilling. Failure to obtain prior Departmental approval may result in disapproval of the wells as constructed and may require new wells to be installed.
- 3. A ground water monitoring well as required by this permit is a monitoring device under N.J.S.A. 58:10A-10 and as such the permittee is required to maintain the wells in proper working order at all times. The permittee is further required to take any and all reasonable steps necessary to limit public access by constructing fences, barricades, or any other structures or means necessary to restrict access to the ground water monitoring well(s). Said structures shall be maintained to restrict access.
- 4. The owner or operator shall inspect each ground water monitoring well on a weekly basis for structural integrity and/or damage. The permittee shall maintain a complete inspection record indicating dates of inspection, inspector's name, and conditions observed. These records shall be made available to the Department upon request. Failure to maintain or submit records upon request shall be a violation of the conditions of this permit.
- 5. If the monitoring wells are damaged or are otherwise rendered inadequate for their intended purpose, the Administrator, Water Quality Management Element, shall be notified within five days in writing indicating:
  - (a) Which wells were damaged or rendered inadequate for their intended use;

- (b) The cause and extent of damage or the reason for the inadequacy;
  - (c) If the sampling schedule as required in this permit will be violated or if the results of the sampling may reasonably become misleading;
  - (d) The date that the well will again be operational. Damaged wells must be replaced or repaired within thirty (30) days after the damage has occurred. The wells must be sampled within five (5) days after they have been installed. A replacement well must meet the construction requirements established by the Department. A valid New Jersey well permit is required prior to the installation of the replacement well;
  - (e) The next date that the well will be sampled.

Failure to follow these procedures is a violation of this permit and may subject the permittee to the provisions of N.J.S.A. 58:10A-10.

- The permittee must obtain and analyze samples from the ground water monitoring system as required by this permit pursuant to the NJDEP Field Procedures Manual for Water Acquisition and as delineated in N.J.A.C. 7:14A-6.12. chain of custody record for each sample shall be maintained at the facility and may be requested and/or examined by the Department. The permittee or his/her agent shall evacuate the ground water monitoring well(s) according to procedures identified in Section 6.12 of the regulations no more than four (4) hours prior to sample collection.
- 7. All samples shall be analyzed by a New Jersey Certified Laboratory. Sampling results shall be reported on forms provided by the Division of Water Resources and attached as Part III of this permit. Information not reported on the above specified forms shall not be deemed to fulfill the reporting requirements of this permit. It shall be the permittee's responsibility to maintain an adequate supply of forms to report round water monitoring data to the Department.
- 8. All permit required ground water monitoring wells, piezometers and/or lysimeters shall be installed within 30 days of the Effective Date of the permit.

- 9. Within 60 days of the Effective Date of the permit, the permittee shall identify to the Department by written notification all ground water monitoring wells or piezometers installed on the permittee's property during the period in which the permittee owned or had control of the property. The locations of these ground water monitoring wells and/or piezometers shall be shown on a plot plan drawn to a scale suitable to the Department.
- 10. The permittee shall submit to the Department "Ground Water Monitoring Well Certifications Forms A and B" for each ground water monitoring well which is required to be sampled in the permit. The Ground Water Monitoring Well Certifications shall be submitted to:

Stephen J. Urbanik NJDEP-Div. of Water Resources Bur. of Ground Water Quality Management CN-029 Trenton, NJ 08625


within 60 days of the Effective Date of the permit.

- 11. The permittee shall sample the ground water monitoring wells in the following order:
  - 1. MW-1
  - 2. MW-2
  - 3. MW-3
  - 4. MW-4
- 12. a. In the event that ground water monitoring requirements and limitations are exceeded, within three (3) days after detection of the exceedence the permittee shall notify the Department of the exceedence.
  - b. The permittee shall submit to the Department a compliance monitoring program within thirty (30) days of written notification by the Department that the submission of the compliance monitoring program is required. The plan shall be in accordance with N.J.A.C. 7:14A-6.15 (j) and shall include an implementation schedule for further study to define the sources of contamination, the specific constituents of concern, and the vertical and horizontal extent of the plumes.
  - c. Within thirty (30) days of written Departmental approval of the ground water monitoring program required above, the permittee shall begin the approved study.


Part II-DGW-7-Cl re/Post-Closure Page 4 of 4 NJ0027847

- d. The approved ground water study shall be completed within 180 days of the Department's written approval of the program.
- Within thirty (30) days of the completion of the ground e. water study identified above, the results of the. study and recommendations concerning a corrective program shall be submitted to the Department in writing. Pursuant to N.J.A.C. 7:14A-6.15 (j) 10, in the event that the permittee can demonstrate to the satisfaction of the Department that the permittee is permit responsible party for the exceedences investigated as a result of this Special Condition , the permittee shall not be responsible for implementation of a corrective action plan as delineated

Based upon receipt of the data generated by the approved plan, the Department shall make a determination regarding the need for corrective actions. corrective actions are necessary the deemed by Department, implementation of such action will required through the issuance of an Administrative Order, and Administrative Consent Order, а Modification to the NJPDES Permit, and/or appropriate Departmental actions.



# New Jersey Department of Environmental Protection Unconsolid Led Monitor Well Specifications\*



NOT TO SCALE

#### **EQUIREMENTS:**

1. Notification to the NJDEP is required two (2) weeks prior to drilling. (609) 292-0424
2. State well permits are required for each monitor well constructed by the driller.

Report "use of well" on well permit application. Permit number must be permanently affixed to each monitor well.

## GROUND WATER

MONITORING WELL CERTIFICATION - FORM A - AS-BUILT CERTIFICATION (One form must be completed for each well)


Name of Permittee:	Servometer Corporation	
Name of Facility:	Servometer Corporation	
Location:	501 Little Falls Road	
I	Cedar Grove, Essex County	
NJPDES Permit No:	NJ 0027847	•
Allocation Section	(As assigned by NJDEP's Water	
Owner's Well Number or plans): Well Completion Data	(As shown on the application	
	f Casing (cap off) to ground	
surface (one-hundr		
• • · · · · · · · · · · · · · · ·	(one-tenth of a foot):	
	een From Top of Casing	
(one-tenth of a fo		
Screen Length (feet		
Screen or Slot Size	: `	
Screen Material:		
	VC, Steel or Other-Specify):	
Casing Diameter (Inc.		
	From Top of Casing at The ion (one-hundredth of a foot):	
■ Yield (Gallons per		
Length of time Well		Hours Minutes
Lithologic Log:	rumped of barred.	ATTACH ON BACK
_		All Inch on Dien
familiar with the iments and that, bas responsible for obtinformation is true	alty of law that I have person information submitted in this ded on my inquiry of those indication, I believe accurate and complete. I are so for submitted false informand imprisonment.	document and all attach- ividuals immediately ieve the submitted m aware that there are
Draft and and Draft		
Professional Engine	er's Signature	· ·
Professional Engi	neer's Name	
(Please type or		SEAL
	E	~ · · ·


Professional Engineer's License #


## THIS FORM MUST BE COMPLETED BY THE PERMITTEE OR MIS/HER AGENT


Name of Facility:  Location:  Servometer Corporation 501 Little Falls Road Cedar Grove, Essex County NJ 0027847  LAND SURVEYOR'S CERTIFICATION  Well Permit Number (As assigned by NJDEP's Water Allocation Section, 609-984-6831): This number must be permanently affixed to the well casing.  Longitude (one-tenth of a second): Latitude (one-tenth of a second):		RING WELL CERTIFICATION	- FORM D DOCATION CERTIFICATI
Cedar Grove, Essex County NJ 0027847  LAND SURVEYOR'S CERTIFICATION  Well Permit Number (As assigned by NJDEP's Water Allocation Section, 609-984-6831): This number must be permanently affixed to the well casing.  Longitude (one-tenth of a second): Elevation of Top of Casing (cap off) (one-hundredth of a foot): Downers Well Number (As shown on the application or plans):  AUTHENTICATION  I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.  PROFESSIONAL LAND SURVEYOR'S SIGNATURE  PROFESSIONAL LAND SURVEYOR'S NAME (Please print or type)	Name of Permittee: Name of Facility:	Servometer Corporation	
NJPDES Number: NJ 0027847  LAND SURVEYOR'S CERTIFICATION  Well Permit Number (As assigned by NJDEP's Water Allocation Section, 609-984-6831): This number must be permanently affixed to the well casing.  Longitude (one-tenth of a second): West			
Well Permit Number (As assigned by NJDEP's Water Allocation Section, 609-984-6831):  This number must be permanently affixed to the well casing.  Longitude (one-tenth of a second): Latitude (one-tenth of a second): Elevation of Top of Casing (cap off) (one-hundredth of a foot): Downers Well Number (As shown on the application or plans):  AUTHENTICATION  If certify under penalty of law that I have personally examined and amfamiliar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.  PROFESSIONAL LAND SURVEYOR'S SIGNATURE  PROFESSIONAL LAND SURVEYOR'S NAME (Please print or type)	NJPDES Number:		
Allocation Section, 609-984-6831):  This number must be permanently affixed to the well casing.  Longitude (one-tenth of a second):  Latitude (one-tenth of a second):  Elevation of Top of Casing (cap off) (one-hundredth of a foot):  Dwners Well Number (As shown on the application or plans):  AUTHENTICATION  I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.  PROFESSIONAL LAND SURVEYOR'S SIGNATURE  PROFESSIONAL LAND SURVEYOR'S NAME (Please print or type)	LAND SURVEYOR'S CER	TIFICATION	
Latitude (one-tenth of a second):  Elevation of Top of Casing (cap off)  (one-hundredth of a foot):  Dwners Well Number (As shown on the application or plans):  AUTHENTICATION  I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.  PROFESSIONAL LAND SURVEYOR'S SIGNATURE  PROFESSIONAL LAND SURVEYOR'S NAME  (Please print or type)	Allocation Section, This number must be	609-984-6831):	
Latitude (One-tenth of a second):  (One-hundredth of a foot):  Owners Well Number (As shown on the application or plans):  AUTHENTICATION  I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.  PROFESSIONAL LAND SURVEYOR'S SIGNATURE  PROFESSIONAL LAND SURVEYOR'S NAME  (Please print or type)	Longitude (one-tenth	of a second):	West _
Owners Well Number (As shown on the application or plans):  AUTHENTICATION  I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.  PROFESSIONAL LAND SURVEYOR'S SIGNATURE  PROFESSIONAL LAND SURVEYOR'S NAME  (Please print or type)	Latitude (one-tenth o	f a second):	North
Owners Well Number (As shown on the application or plans):  AUTHENTICATION  I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.  PROFESSIONAL LAND SURVEYOR'S SIGNATURE  PROFESSIONAL LAND SURVEYOR'S NAME  (Please print or type)			
I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.  PROFESSIONAL LAND SURVEYOR'S SIGNATURE  PROFESSIONAL LAND SURVEYOR'S NAME  (Please print or type)	Owners Well Number	· ·	tion
familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.  PROFESSIONAL LAND SURVEYOR'S SIGNATURE  PROFESSIONAL LAND SURVEYOR'S NAME  (Please print or type)			
PROFESSIONAL LAND SURVEYOR'S SIGNATURE  PROFESSIONAL LAND SURVEYOR'S NAME  (Please print or type)	AUTHENTICATION	•	
PROFESSIONAL LAND SURVEYOR'S NAME (Please print or type)	I certify under pendamiliar with the inments and that, base responsible for obtainformation is true significant penaltic	nformation submitted in ed on my inquiry of those aining the information, accurate and complete. es for submitting false	this document and all attach- e individuals immediately I believe the submitted I am aware that there are
(Please print or type)	I certify under pending and that, base responsible for obtainformation is true significant penaltic possibility of fine	nformation submitted in ed on my inquiry of those aining the information, accurate and complete. es for submitting false	this document and all attach- e individuals immediately I believe the submitted I am aware that there are
PROFESSIONAL LAND SURVEYOR'S NAME (Please print or type)	I certify under pendamiliar with the iments and that, base responsible for obtainformation is true significant penaltic possibility of fine	nformation submitted in ed on my inquiry of those aining the information, accurate and complete. es for submitting false and imprisonment.	this document and all attach- e individuals immediately I believe the submitted I am aware that there are
PROFESSIONAL LAND SURVEYOR'S LICENSE #	I certify under pen- familiar with the in- ments and that, base responsible for obtainformation is true significant penaltic possibility of fine	nformation submitted in ed on my inquiry of those aining the information, accurate and complete. es for submitting false and imprisonment.	this document and all attache individuals immediately I believe the submitted I am aware that there are information including the
PROFESSIONAL LAND SURVEYOR'S LICENSE #	I certify under pendamiliar with the imments and that, base responsible for obtainformation is true significant penaltic possibility of fine PROFESSIONAL LAND SEPROFESSIONAL SE	nformation submitted in ed on my inquiry of those aining the information, accurate and complete. es for submitting false and imprisonment.  URVEYOR'S SIGNATURE	this document and all attache individuals immediately I believe the submitted I am aware that there are information including the
	familiar with the iments and that, base responsible for obtainformation is true significant penaltic possibility of fine PROFESSIONAL LAND STAND	nformation submitted in ed on my inquiry of those aining the information, accurate and complete. es for submitting false and imprisonment.  URVEYOR'S SIGNATURE	this document and all attache individuals immediately I believe the submitted I am aware that there are information including the
	I certify under pendamiliar with the imments and that, base responsible for obtainformation is true significant penaltic possibility of fine  PROFESSIONAL LAND STATES (Please print of the	nformation submitted in ed on my inquiry of those aining the information, accurate and complete. es for submitting false and imprisonment.  URVEYOR'S SIGNATURE  URVEYOR'S NAME or type)	this document and all attache individuals immediately I believe the submitted I am aware that there are information including the

The Department reserves the right in cases of violation of permit specified ground water limits or Ground Water Quality Standards (N.J.A.C. 7:9-6.1 et seq.) to require that wells be resurveyed to an accuracy of one-hundredth of a second latitude and longitude. This shall not be considered to require a major modification of the NJPDES permit.









REFERENCE NO. 22

Please on to the reverse of this form and provide the requested information

SEPA		ENVIRONMENTA			ITY		IONS: If you		
INSTALLA- TION'S EPA						information	it in the space n on the label is	incorrect, d	raw a lin
1.D. NO.	   NJD002138	543				in the app	and supply th ropriate section	below. If the	ne label
I. STALLATION						below blan	nd correct, lea k. If you did n	ot receive a p	preprinte
INSTALLA- TION	SERVOMETE 501 LITTL		0			single site	olete all items. where hazardo	us waste is g	generate
ADDRESS	CEDAR GRO	VE, NJ 0:	7009				ored and/or dis		
				•			TRUCTIONS F before comple		
LOCATION IIL OF INSTAL- LATION	501 LITTL CEDAR GRO		D 2003				n requested her 010 of the Reso		
	toda diginal diginal di	بن با ا	· i.d i.d			Recovery A	let).		
FOR OFFICIAL	USE ONLY					<u> </u>			
			COMMENTS		<del></del>				-
C					1_1_			58	
INSTALLATI	ON'S EPA I.D. NUM	BER APPRO	OVED DAYER	ECEIVED					
EM2000	213854	331	800	814				·	
I. NAME OF INS	TALLATION	13 14 15	.,	- 34					
II. INSTALLATI	ON MAILING AD	DRESS	•				67		1) 1 C 1
		STREET OR P.O.	вох						
3						45			
	CITY	ORTOWN		ST.	ZIF	CODE			
4									
III. LOCATION	OF INSTALLATION	ON		40 41 4	E   47	- 51		_	4.00
	STRE	ET OR ROUTE N	JMBER		11				
5					Ш.	45			
c	CITY	OR TOWN	<del></del>	ST.	ZIF	CODE		: ,	
6									
IV. INSTALLAT	ION CONTACT	<u> </u>		40 41 43	2   47	- 51			e e Sasa
er T	NAME A	ND TITLE (last, fir	st, & job title)		<del>-                                    </del>	РНО	NE NO. (area co	ode & no.)	4
2 H o 1 o w	a c h u k	Morris	s Pres	ident	:	20	1 7 8 5	4630	
V. OWNERSHIP									$\mathbb{T}(\mathcal{K}_{\ell})$
<b>4</b> ≖ <u>€</u> 1 7 7 7 7 7		A. NAME OF II	NSTALLATION'S	LEGAL OWNE	R	<del></del>		<del></del>	•
F 15 16	meter	Corpor	ration					58	
enter the appropr	OWNERSHIP into box)		HAZARDOUS W	ASTE ACTIV					
F = FEDERA	- 1 11	X A. G	ENERATION	ÁL THE		TRANSPOR	RTATION (com	olete Item VI	<b>(1)</b> (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
M = NON-FE	54	39	REAT/STORE/DIS		60		OUND INJECT	ION	
VII. MODE OF	TRANSPORTATIO		<del></del>			5 / · · · · · · · · · · · · · · · · · ·	<u> </u>		
A. AIR	B. RAIL	C. HIGHWA	.γ ∐D. W/	ATER LE	. OTHE	R (specify):			
	SUBSEQUENT N		e vous installation	e first motification	on of he	zamoue was	to activity or a s	ubsequent n	otification
If this is not your f	irst notification, ente	r your Installation	s EP \ I.D. Numbe	r in the space pr	ovided I	below.	a activity of a l		
	化连续电子						C. INSTALLA	TION'S EPA	I.D. NO.
X A. FIRST	F NOTIFICATION		SEQUENT NOTIF	ICATION (com)					
			计双位性性对待性系统的	the state of the s				1 1 1 1	

		ı.p.	- F	ORC	FF	ıcı	AL USE C	NL	Υ.		
- 5					<u>_</u>	-,	1300	11		T/A	C
337	MΗ	711	N	YO		-//	385	4	3	וכו	1
_ 77			<u>د</u> (	1	-			_	_	-	
1	2							_	13	14	15

IX. DESCRIPTION OF HAZ	ARDOUS WASTES (co	ntinued from front						
A. HAZARDOUS WASTES FROM NON—SPECIFIC SOURCES. Enter the four—digit number from 40 CFR Part 261.31 for each listed hazardous waste from non—specific sources your installation handles. Use additional sheets if necessary.								
1	2	3	4	5	6			
F 0 0 1	F 0 0 3 F		F 0 0 9	23 26	23 - 26			
7	123   124	9 7	10	11	12			
		<del>                                     </del>	TTT	<del>                                     </del>				
123				131	73 - 76			
B. HAZARDOUS WASTES FRO specific industrial sources you	M SPECIFIC SOURCES. Er installation handles. Use a	Enter the four—digit no additional sheets if neo	umber from 40 CFR Pacessary.	art 261.32 for each list	ed hazardous waste from			
13	14	15	16	17	18			
23 - 26	23 - 26 23	26	23 - 26	23 - 26	23 - 26			
19	20	21	22	23	24			
23 - 26	23 - 26 23	27	28 28	29	30			
		<del></del>	<del>- 1 - 1 - 1</del>					
C. COMMERCIAL CHEMICAL F stance your installation handle				n 40 CFR Part 261.33	or each chemical sub-			
31	32	33	34	35	36			
23 - 26	23 - 26 23	26	23 - 26	23 - 26	23 - 26			
37	38	39	40	41	42			
23 - 26	23 - 26 23	25	27 26	23 26	23 26			
43	44	45	46	47	48			
23 - 26	23 - 26 23	26	23 - 26	23 - 26	23 26			
D. LISTED INFECTIOUS WAST hospitals, medical and research		number from 40 CFR	Part 261.34 for each li	sted hazardous waste fo	om hospitals, veterinary			
49	50	51	52	53	54			
23 - 26	23 26 23	26	23 - 26	23 - 26	23 26			
E. CHARACTERISTICS OF NO hazardous wastes your installa				nding to the characteris	itics of non-listed			
1. IGNITABLE	₹ 2. CO {D002}	RROSIVE	3. REACTIV		4. TOXIC			
X. CERTIFICATION				and the state of the state of	1.34			
I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.								
SIGNATURE	, , , , ,	NAME & OFFICIA	L TITLE (type or prin	t)	DATE SIGNED			
Morris H	cloudelink	Morris Holo	wachuk, Presi	dent	8/12/80			

EPA Form 8700-12 (6-80) REVERSE

P

REFERENCE NO. 23



ENVIRONMENTAL PROTECTION AGENCY RECENTAL

88 DEC 16 PH 1:39

HAZARBOUG MASTE FACILIBLES ERAUGH

## State of New Jersey

#### DEPARTMENT OF ENVIRONMENTAL PROTECTION

DIVISION OF HAZARDOUS WASTE MANAGEMENT

John J. Trela, Ph.D., Director 401 East State St. CN 028

Trenton, N.J. 08625-0028 (609)633-1408

Lance R. Miller Deputy Director

Responsible Party Remedial Actor

DEC 0 9 1988 V C/2004 - 1005 - 6 2 90 2 cm

4 5

Peter J. Holowachuk President Servometer Corporation 501 Little Falls Rd. Cedar Grove, NJ 07009

Michele M. Putnam

Hazardous Waste Operations

RE:

Deputy Director

Dear Mr. Holowachuk:

EPA ID No. NJD 002 138 543

The New Jersey Department of Environmental Protection (the Department) is in receipt of Servometer Corporation's certification of closure for the above referenced facility's underground hazardous waste storage tank. Previously, Servometer Corporation has been listed as a hazardous waste storage facility subject to permitting requirements because the facility filed a Part A permit application with the USEPA for storage of hazardous waste in a tank (SO2). Upon review of the file, the Department has reached the following conclusion regarding present hazardous waste activities at the above referenced facility.

- 1. The facility accumulates hazardous waste (Caustic waste-D002) on-site in a 6,000 gallon aboveground fiberglass tank for 90 days or less.
- 2. The facility accumulates hazardous waste (waste acid and waste oils) on-site in containers for 90 days or less.
- 3. The 1,1,1-Trichloroethane still bottoms (F001) generated in the closed loop solvent vapor degreaser unit are pumped directly from the unit by the waste hauler.
- 4. Wastewater treatment sludge (F006) is pumped from an integral part of the wastewater treatment systems by the waste hauler. The effluent from the treatment system is discharged to surface water under NJPDES permit #NJ0027847.

If the aforementioned conclusion are incorrect, or incomplete, please contact the Department immediately.

Assuming the aforementioned conclusion are correct, Servometer Corporation's facility identified by the following USEPA identification number:

#### NJD 002 138 543

is excluded from applicable hazardous waste treatment, storage, or disposal regulations under N.J.A.C. 7:26-1 et seq. based on the following:

- A. Tank storage of hazardous waste generated on-site is in accordance with the following:
  - 1. The 6,000 gallon aboveground fiberglass tank shall have sufficient shell thickness to ensure that the tank will not collapse or rupture. The facility shall perform daily inspections of the tank to detect ruptures, cracks, or any other deterioration and shall perform any repairs necessary to prevent a release of hazardous waste;
  - 2. The controls to prevent overfilling shall be maintained in accordance with N.J.A.C. 7:26-10.5(c);
  - 3. The tank storage area's secondary containment shall be maintained in accordance with N.J.A.C. 7:26-10.5(d);
  - 4. The tank shall be maintained to ensure at least 99 percent of the volume of each tank can be readily emptied by direct pumping or drainage;
  - 5. The tank shall be rendered empty, as defined at N.J.A.C. 7:26-1.4, every 90 days or less;
  - 6. All waste removed from the tank shall be shipped off-site to an authorized facility or placed in an on-site, authorized facility, as defined at N.J.A.C. 7:26-1.4; and
  - 7. While being accumulated on-site, the tank shall be clearly labeled or marked with the words "Hazardous Waste".
- B. Container storage of hazardous waste generated on-site is in accordance with the following:
  - 1. All such waste is, within 90 days or less, shipped off-site to an authorized facility or placed in an on-site authorized facility, as defined at N.J.A.C. 7:26-1.4.
  - The waste is placed in containers which meet the standards of N.J.A.C. 7:26-7.2 and are managed in accordance with N.J.A.C. 7:26-9.4(d).
  - 3. The date upon which each period of accumulation begins is clearly marked and visible for inspection on each container. While being accumulated on-site, each container shall be clearly labeled or marked with the words "Hazardous Waste" and labeled in accordance with 49 CFR 172.304.

C. The generator complies with the requirements for owners and operators of N.J.A.C. 7:26-9.6 and 9.7 concerning preparedness and prevention, contingency plans and emergency procedures as well as N.J.A.C. 7:26-9.4(g) concerning personnel training.

Your company's hazardous waste facility above is no longer included in DEP's list of "existing facilities" (see N.J.A.C. 7:26-1.4 and 12.3) and therefore does not need to conform with the interim operating requirements of N.J.A.C. 7:26-1 et seq. for "existing facilities". It is the company's responsibility to operate within conditions listed above. To operate a hazardous waste facility without prior approval from the DEP is a violation of the Solid Waste Management Act N.J.S.A. 13:1E-1 et seq.

This written acknowledgement of the exclusion of the subject company from the hazardous waste facility requirements under N.J.A.C. 7:26-1 et seq. is based expressly on the review of the aforementioned correspondence. This letter makes no claim as to the extent and physical condition of the actual hazardous waste activities occurring at the site mentioned above.

The issuance of this delisting letter by the Department does not indicate, or imply, and should not be construed as a waiver of any requirements pursuant to the New Jersey Water Pollution Control Act, N.J.S.A. 58:10A-1 et seq. and regulations promulgated thereunder concerning the New Jersey Pollutant Discharge Elimination System, N.J.A.C. 7:14-1 et seq. If your facility is in any of the regulated categories identified in the above cited regulations, you are hereby directed to apply for any and all permits necessary within ninety (or 180 days - at the option of DWR) to the Bureau of Ground Water Discharge Permits, CN 029, Trenton, New Jersey, 08625. Applications may be obtained by calling (609) 292-0424.

Financial assurances required by N.J.A.C. 7:26-9.10 and N.J.A.C. 7:26-9.13 are obviated by the termination of treatment, storage, or disposal facility status. Enclosed is an original copy of Valley National Bank Irrevocable Standby Letter of Credit Number 1503. The Trust Agreement and the Letter of Credit which funds the Trust are hereby released by the Department. The Department is sending the Trustee a copy of this letter as the authorization to release the Trust Agreement and Letter or Credit.

If you have any questions concerning this matter, contact Michael Gerchman of my staff at (609) 292-9880.

Very truly yours,

Ernest J. Kuhlwein, Jr., Chief

Ement & Kellwary

Bureau of Hazardous Waste Engineering

EP62/1m Attachment

c: Barry Tornick, USEPA
Yacoub E. Yacoub, BME
Ronald Bargiel, Valley National Bank

DOCUMENT: SERVOME2 FOLDER: LXMMCB

REFERENCE NO. 24



## State of New Jersey DEPARTMENT OF ENVIRONMENTAL PROTECTION

#### **DIVISION OF HAZARDOUS WASTE MANAGEMENT**

John J. Trela, Ph.D., Acting Director 401 East State St. CN 028 Trenton, N.J. 08625 609 633 1408

2 6 MAR 1987

Peter Holowachuk Servometer Corporation 501 Little Falls Road Cedar Grove, N.J. 07009

Dear Mr. Holwachuk:

RE: Closure Plan for Underground Storage Tank and Approval for Installation of New Tank at Servometer, EPA ID No. NJD 002 138 543. CP-86-11

The Bureau of Hazardous Waste Engineering has reviewed the revised closure plan for an underground tank, submitted by Servometer on August 20, 1986 and the 6,000 gal. tank replacement's design. The secondary containment system submitted on November 13 and December 18, 1986 has also been reviewed.

The Bureau finds the Closure Plan in compliance with the criteria set forth in N.J.A.C. 7:26-9.8. The plan is hereby approved subject to the following conditions:

- 1) The tank and soil sampling devices as well as the drill rig shall be decontaminated <u>before</u> initial use following the procedures outlined in Servometer's Closure Plan.
- Field blanks of the rinsates from the decontaminated underground tank and the split spoon sampler before its initial use are required.
- 3) The Department requires appropriate analytical testing of the tank cleaning effluent to determine whether or not decontamination of the tank was properly performed. If the tank is still contaminated, further cleaning will be required or it may have to be excavated and disposed of as hazardous waste.
- 4) If the soil underneath and around the tank or the tank discharge piping is contaminated, a remediation plan shall be implemented. Please submit to the Bureau a remediation plan within 30 days of

the date when the results of the analysis are received, if decontamination is indicated.

- 5) The tank and the manhole shall not be filled and paved on, until the soil analysis results are received and confirmed that no contamination is present.
- 6) Servometer shall notify Mr. Steve Urbanik from the Division of Water Resources, two weeks in advance from the date when the soil sampling will be performed. Mr. Urbanik can be reached at (609) 292-0424. At the same time Servometer shall also notify George Mejia from the Bureau so arrangements can be made to have the Bureau of Environmental Measurements and Quality Assurance witness the sampling.
- 7) Pursuant to N.J.A.C. 7:26-9.8(j), Servometer shall complete closure activities within 180 days of the date of this approval.
- Certification that the facility has closed in accordance with the specifications in the approved closure plan shall be provided by Servometer Corporation as well as an independent New Jersey registered professional engineer not later than 210 days after the date of their approval.
- Please be aware that if analytical results prove that the tank was properly decontaminated and the soil is free of contamination, a notice in deed to property is not required per N.J.A.C. 7:26-9.9(a).
- 10) Servometer shall be subject to ground water discharge permit requirements of N.J.A.C. 7:14A-6 for ground water monitoring.

The Bureau has also found the designs of the new fiberglass tank and the secondary containment system in compliance with N.J.A.C. 7:26-10.5 and hereby grants approval to drawings SE-1. rev b, SE-2 rev b, SE-3 rev b (views 1 and 2), SE4, SE-5 and specifications ver. c of July, 1986 by Finishing Technology, and for drawing No. 12875-1 by Burt Process Equipment dated 3/29/86. The tank has the following thickness:

Bottom Head	5/16 in.
shell 0-4 ft (bottom-up)	5/16 in.
shell 4-10 ft	1/4 in.
shell 10-14 ft	3/16 in.

Since these are minimum requirements, these thicknesses shall be maintained for the tank's life.

The secondary containment shall have a capacity of 6000 gals. The bottom pad shall be reinforced concrete, 8 inches thick with a permeability rating not greater than 10- cm/sec. in accordance with N.J.A.C. 7:26-10.5(d).

The tank shall be managed per N.J.A.C. 7:26-9.3(b) and shall be emptied of 99% of its contents every ninety days or less. The overfilling prevention control shall be maintained in proper operating condition. The contents of

tank shall be manifested off-site to an approved treatment, storage and disposal facility. In order to delist the facility in a timely manner, Servometer shall submit within thirty (30) days of the date of this approval, copies of the preparedness, prevention and contingency plans in accordance with N.J.A.C. 7:26-9.6 and 9.7, and personnel training program in accordance with N.J.A.C. 7:26-9.4(g). Also copies of the letters sent to the local Police and Fire Departments and to the local hospitals with the emergency plan must be provided. Be also reminded that two inspections by the fire Department are required every year.

The construction of the tank containment and installation of the tank is subject to an inspection and approval by the Bureau's engineers. Please, contact George Mejia at (609) 292-9880 upon completion of the construction to arrange for the inspection. After its approval, Servometer must empty the underground tank and start using the new tank. Servometer shall not store wastes in both, the old and the newly approved tank at any given time.

Should you have any questions, please contact George Mejia of my staff at (609) 292-9880.

Very truly yours,

Frank Coolick, Acting Assistant Director Hazardous Waste Regulation Element

c: Lori Amato, USEPA - Region II

Steve Urbanik, Ground Water

REFERENCE NO. 25

## INSPECTION REPORT

REPORT PREPARED FOR:	
☐ Generator	
☐ Transporter	
HWM (TSD) Facility  Closure	
	FACILITY INFORMATION
Name:	ServomeTer Corporation
Address:	501 Little Falls Rd.
•	Cedar grove, N.J. 07609
Lot:	102 Block: 378
County:	Essex
. Phone:	(201) 36 785-0756
EPA ID#:	NJD 06713 8543
	10/31/88
•	
	PARTICIPATING PERSONNEL
State or EPA Personnel:	Chris FeliceTti
	Syed Uddin
, Facility Personnel:	BerTram James Barcon
Report Prepared by Name:	Chris FeliceTTi
Region:	MeTro
Telephone#:	(201) 669-3960
·	mata
Reviewed by:	- Jutoury
Date of Parising	11-1-88

#### **SUMMARY OF FINDINGS**

#### FACILITY DESCRIPTION AND OPERATIONS

ServomeTer Comp m	anulartum	es electes	form.	bellows
In use in sin craft medics	l equipme	ent and o	the sa	essure
ServomeTer Comp m for use in our craft, medica demand situations.				•
aluminum manda	ils are ma	chined lo	the pu	uper
shape at ligh tolerances	then of	atted in	Thans	n-reaction
nichel. I be nexts are the	a "cooked	"in a ca	uster &	Cath
which dissolves the al	lemineem	lesvins	the nice	Rel
shape at ligh tolerances nickel. The parts are the which dissolves the al shell intent.	,	8		
and 1,1,1- tuckloroethe	2	10-11		
and if I wanted	ne is use	a for all	- wasen	<del></del>
	•		<del></del>	
•		•		
	•			
		<del> </del>		
	<del></del>	•		<del></del>
				· .
•				
		•		
		· · · · · · · · · · · · · · · · · · ·		
•		•		

:

. .

ノ/	pent couster	buth				
. l	pent coustice whe and cu	Iting or	le Prom	marl	ning	
	1.1.1- time	Cloudeth	age ,	from d	eghan	na
•					0	<u> </u>
				: ·		
				_		·
	· · · · · · · · · · · · · · · · · · ·					
	hazard <mark>ous w</mark> aste locati ste Codes)	ed on site, and	estimate the a	pproximate	quantities o	or each.
			·			
	3000 gal	causti	n soluti	~ ~ ~	tank-	-0002
	d			• .		•
	•		•			
		<del>1</del>	·	<del></del>	<del></del>	· ·
						<del></del>
	•			•		•
		•	· · · · · · · · · · · · · · · · · · ·	·	· · · · · · · · · · · · · · · · · · ·	•
,		•				

How have these activities changed so as to justify de	listing the company?
caustic	
Waste used to be stoned in an tank. Now caustin is stoned in an above ground to tank - labele every 40 days on less.	undereinound
took now courter to street i	a Goodal
alone append to took - labele	dend enstel
Andrea and Andrea and I have	. pros. singress.
every 10 orgs of sus.	
· · · · · · · · · · · · · · · · · · ·	
Do company records support the delisting request?	•
YES (Attach copies of records to the repo	.w+\
	,
NO (Explain)	
. 3	
The stiffer the department of the first terms of the stiffer terms of th	
Identify the hazardous waste located onsite, and esti	mate the approximate
quantities of each. (Identify Waste Codes)	
	<u></u>

	NO (Explain)	,					
		·					
				•			
	·	,	·			·	
				·			
		<del>, </del>	<del></del>				
			· · · · · · · · · · · · · · · · · · ·				
<del> </del>	<del></del>			<del></del>		· · · · · · · · · · · · · · · · · · ·	·
						<del></del>	
	·			·			
<del> </del>	<del> </del>	<del></del>	<del></del>			·	
			<del></del>	<del></del>	· · · · · · · · · · · · · · · · · · ·		
*	·	<del></del>		-	·		
		· · · · · · · · · · · · · · · · · · ·					·
			<del></del>				
,							. •
	1	<del> </del>					
<del></del>	<del></del>				<del></del>	· · · · · · · · · · · · · · · · · · ·	<del></del>
	- <del></del>	<del></del>		<del> </del>	<del></del>	<u>. ,</u>	
	·	<del></del>		<del></del>		<del></del>	<del> </del>

 $\bigcirc$ 

# CONFIDENTIAL - RECOMMENDATIONS

то:		•••
FROM:		DATE:
SUBJECT:		
		:
•		•
·		
		·
		-
:		
,	·	
<del></del>	,	
	·	·
		·
	·	
	•	
·		
		•
<del></del>		

REFERENCE NO. 26

Let's protect our earth

State of Rew Tersey

DEPARTMENT OF ENVIRONMENTAL PROTECTION

DIVISION OF HAZARDOUS WASTE MANAGEMENT

John J. Trela, Ph.D., Director 401 East State St.

CN 028 Trenton, N.J. 08625-0028 (609)633-1408

Lance R. Miller Deputy Director

Responsible Party Remedial Action

MEMORANDUM

SEP 2 9 1988

TO:

Michele M. Putnam

Hazardous Waste Operations

Deputy Director

Yacoub Yacoub, Chief

Bureau of Metro Enforcement

FROM:

Ernest Kuhlwein, Jr., Chief

Bureau of Hazardous Waste Engineering

SUBJECT:

Closure Inspection, Servometer Corporation, Cedar Grove

EPA ID No. NJD002138543

Attached for your review is a copy of the closure certification for the underground hazardous waste storage tank located at Servometer Corporation's Cedar Grove facility. The closure plan for this unit was approved by the DHWM on March 26, 1987, however modifications to the approved plan were A letter approving the modifications was issued on march 4, necessary. The storage tank has been decontaminated and excavated, and analysis of post-excavation soil samples indicates that no contamination of soil has occurred.

The facility currently has a New Jersey Pollutant Discharge Elimination System Permit (NJ0027847) which includes a major modification for discharge to groundwater from the underground hazardous waste storage tank. facility also has approval from the BHWE to accumulate hazardous waste in an aboveground tank for less than 90 days.

The BHWE requests that your office perform a closure inspection of the facility in order to confirm closure of this storage tank. A copy of the completed inspection report should be sent to the BHWE so the facility may be delisted from the TSD status.

If you have any questions concerning this matter, contact Michael Gerchman at (609) 292-9880.

EP62:pjb Attachment CLOSURE OBSERVATION

UNDERGROUND STORAGE TANK

SERVOMETER CORPORATION

CEDAR GROVE, N.J.

SUBMITTED BY:

QUAZZA & ASSOCIATES, INC. 122 Sherman Avenue Cedar Grove, NJ 07009 (201) 239-1258

67-64-43

August 5, 1988

#### **BACKGROUND**

Quazza & Associates, Inc. (QAI) was engaged by Lancy International, Inc. (LII) on behalf of Lancy Environmental Services Company (LESC) to review the Closure Plan for the removal of an underground hazardous waste storage tank for their client Servometer Corporation (SC). Additionally, QAI was to observe the removal of the storage tank in order to confirm that is was removed according to the Closure Plan approved by the New Jersey Department of Environmental Protection (NJDEP).

The following documents were reviewed and are included as Attachments:

- 1. Closure Plan dated March, 1986, Revised August 1986.
- NJDEP letter to SC dated March 26, 1987 approving Closure Plan with conditions.
- 3. LESC letter to NJDEP dated October 2,1987 modifying Closure Plan.
- 4. LESC letter to NJDEP dated November 9, 1987 modifying Closure Plan.
- 5. LESC letter to NJDEP dated January 19, 1988 modifying Closure Plan.
- NJDEP letter to SC dated March 4, 1988 approving LESC letter 1/19/88
   with additional requirements.
- 7. LESC letter to NJDEP dated May 25, 1988 submitting 3/29/88 sampling results and request for approval of Closure.

# Closure of Underground Storage Tank Servometer Corporation, Cedar Grove, N.J. EPA I.D. No. NJD002-138-543, CP-86-11

This report is made to certify that the closure of the underground storage tank at the Servometer Corporation in Cedar Grove, N.J. has been completed in accordance with the closure plan dated March 1986 (revised August 1986) and various modifications.

On Monday, December 7, 1987, the closure was initiated by Cute, Inc. of Midland Park, N.J. under the supervision of Mr. J. Kline of LESC of Zelionople, PA. This procedure was witnessed full time by the writer.

The residual wastes in the underground tank were removed by suction to a disposal truck operated by Freehold Cartage, Inc. (NJDEP License No. S2265). Reverse pumping was employed to remove the bulk of any sediments that might be present. The tank was then given an initial rinse via a high pressure spray nozzle using a boric acid solution. The rinse water was also removed by suction to the disposal tank truck.

The covering paving was then removed, and the underground tank was exposed by excavating the surrounding soil. The excavation was performed using the equipment supplied by Frank Jennings, Excavator, of Piscataway, N.J. under the direction of Cute, Inc. The removed paving and soil were placed on a plastic liner adjacent to the site. The underground tank was then removed and placed on a separate plastic liner.

At this point soil samples were taken at four points around the vessel location. No sample was taken from under the tank's position since a concrete support slab, unexpectedly, was discovered under the tank's former position. The soil samples were taken by Mr. J. Kline of LESC under the supervision and direction of Ms. H. Decerce of the NJDEP. Ms. Decerce, after consultation by phone with her superiors, stated the concrete slab need not be removed and that a soil sample from beneath the vessel's former position would not be required.

The excavated vessel was then cut open by torch to provide approximately a 3 foot by 3 foot opening in one head. One of the Cute, Inc. personnel, wearing full protective gear including face mask, then entered the tank for final cleanup.

Using cold, and then hot, boric acid solution sprayed through the high pressure nozzle, the tank was rinsed till not only visually clean of any and all sediments but till the final rinse was at a pH of 6. All rinse waters were removed by suction to the disposal tank truck.

Soil samples, and final tank rinse water sample, were then packed and shipped as manifested samples to the U.S. Testing Laboratories in Hoboken, N.J.

The excavated soil was covered with plastic sheeting and the excavated vessel was wrapped in plastic sheeting pending release from the NJDEP after review of soil and rinse water analyses. The excavated hole was to

be covered with plywood and then plastic sheeting although this was not yet performed during the writer's stay.

Results of the tests by the U.S. Testing Laboratories indicated that elevated pH conditions existed in the northeast corner of the excavated area. All other samples and test criteria were acceptable. At this point, the excavated tank was cut-up and disposed of by Cute, Inc. (This activity was not witnessed).

On January 19, 1988 a plan for additional sampling and analysis for the northeast corner of the excavated area was submitted to the NJDEP by LESC. The plan was approved by the NJDEP, with modifications, on March 4, 1988.

On Tuesday, March 29, 1988, the additional sampling was performed jointly by employees of SC and Cute, Inc. This procedure was witnessed full time by the writer.

Approximately 15 cubic feet of soil were removed from the northeast corner of the excavation and placed in steel drums suitable labeled "Hazardous" pending approval from the NJDEP for disposal.

Three (3) soil samples were obtained from the northeast corner above the concrete pad in accordance with the plan as approved. An additional fourth sample was also taken in this area, but two feet below the existing

pad. The soil sampling was again performed under the supervision and direction of Ms. Decerce of the NJDEP. All samples were shipped as manifested samples to the U.S. Testing Laboratories in Hoboken, N.J.

The excavation was then backfilled. The northeast corner was lined with plastic sheeting and filled with clean sand brought to the site by Cute, Inc. This was done to simplify re-excavation and additional sampling, if required, without contamination from the remainder of the backfill. The balance of the excavation was backfilled with the soil, and debris, originally removed.

Test results indicated that the required samples taken above the concrete pad met all the criteria of the closure plan. The fourth sample taken two feet below the pad indicated pH values only slightly above the established criteria.

On May 29, 1988, LESC requested that the NJDEP consider that the closure of this underground storage tank had been performed satisfactorily and permit final closure of the site.

Verbal approval by NJDEP has been received by LESC and the excavation site will be suitably paved and closed by SC at a later date.

Ralph A. Brummer, P.E.

for Quazza & Associates, Inc.

## PROFESSIONAL ENGINEER CERTIFICATION OF CLOSURE

I, Ralph A. Brummer	, a registered
(Name)	
professional engineer, hereby certify, to the	best of my knowledge
and belief, that I have made visual inspe	ction(s) of the
Servometer Corporation, 501 Little Falls Road, C	edar Grove, NJ 07009,
(Name and Address of Facility	)
and closure of the Underground Waste Caust	ic Storage Tank
has been performed in accordance with the r	egulations and the
facility's closure plan as revised on November	9, 1037 including an
additional distilled deionized water rinse	of sample devices
following the non-phosphate detergent wash.	
Hold Dummer	July 29, 1988
Signature	Date
13579	New Jersey
Professional Engineering License Number	For State of
122 Sherman Avenue, Cedar Grove, NJ 07009	(201) 239–1258

Business Address and Telephone Number

#### OWNER CERTIFICATION OF CLOSURE

I, PETER J. HOLOWACHUK	, of
- (Owner or Operator)	
SERVOMETER CORPORATION, 501 LITTLE FALLS ROAD, CEDAR GRO	VE, N.J. 07009 hereby
Channe and Address of Facil	ity)
state and certify that, to the best of my knowledge	and belief, the UNDERGROUN
WASTE CAUSTIC STORAGE TANK at the above named	•
in accordance with the regulations and the facility	's closure plan, and that
closure was completed on the 29th day of	AUGUST
19 88 .	
·	
The A. Adownhal	8/29/88
Signature	To to



#### LANCY ENVIRONMENTAL SERVICES COMPANY

DIVISION OF LANCY INTERNATIONAL, INC. An Alcoa Separations Technology Company

(412) 772-0044 P.O. Box 419, Pittsburgh, Pennsylvania 15230-0419 Street Address: 181 Thorn Hill Road, Warrendale, Pennsylvania 15086-7527 FAX (412) 772-136023

Telex 86,6258

SASTE HAZA ASSENENT PROCRAMS

December 17, 1987

Ms. Denise Bear New Jersey Department of Environmental Protection Division of Hazardous Site Mitigation Bureau of Environmental Measurements and Quality Assurance 383 West State Street Trenton, NJ 08618

Dear Ms. Bear:

Please find enclosed a copy of the analytical data required by your office related to the Servometer Corporation's underground storage tank closure.

We would greatly appreciate your expeditious review of this data as Servameter wishes to complete closure by the end of 1987.

If you should have any questions or comments concerning the data submitted by U.S. Testing Company, Inc., please feel free to call me.

Sincerely,

Lancy Environmental Services Company

Jeffrey S. Holmes, P.E.

Environmental Engineer

JSH: csb Enclosure

cc: Peter Holowachuk - Servometer Corporation

George Mejia - NUDEP



# United States Testing Company, Inc.

#### Chemical Services Division

1415 PARK AVENUE . HOBOKEN, NEW JERSEY 07030 . 201-792-2400

#### REPORT OF TEST

December 10, 1987

NUMBER

CLIENT:

Lancy International Inc. 181 Thorn Hill Road Warrendale, PA 15086 Attn: Jeff Holmes

75761

SUBJECT:

Seven (7) samples identified as #1, #2, #3, #4, Water sample 6, Field Blank and Trip Blank, submitted on 12/7/87

#### AUTHORIZATION:

Purchase Order # 25066

#### PURPOSE:

Analyze samples for Aluminum, Arsenic, Oil & Grease and pH

#### PROCEDURE:

Samples were analysed in accordance with the following methods:

"Methods for Chemical Analysis of Water and Wastes," USEPA, Environmental Monitoring and Support Laboratory, Cincinnati, Ohio, March, 1979, EPA-600/4-79-020

"Test Nethods for Evaluating Solid Waste, Physical/Chemical Nethods," USEPA, Office of Solid Waste and Emergency Response, Washington DC, July 1983 SW-846, 2nd edition

#### RESULTS:

,	<u> 3 1 </u>	# 2	<u># 3</u>	<u># 4</u>
pH <b>#</b>	7.05	7.60	7.70	10.30
Oil & Grease, mg/kg	<10.	<10.	<10.	<10.

pH done on 1:10 leachate

lietals results attached

SIGNED FOR THE COMPANY

Page 1 of

 $S_{i,l}$ 

liaryann Gambino

BY

New York • Chicago • Los Angeles • Tulsa • Memphis • Philadelphia • Richland

UNITED STATES TESTING COMPANY, INC. REPORTS AND LETTERS ARE POR THE EXCLUSIVE USE OF THE CLIENT TO WHOM THEY ARE ADDRESSED AND THEY AND THE NAME OF THE UNITED STATES TESTING COMPANY, INC., OR ITS SEALS OR INSIGNIA ARE NOT TO BE USED UNDER ANY CIRCUMSTANCES IN ADVERTISING TO THE GENERAL PUBLIC AND THEIR COM-MURICATION TO ANY OTNERS OR THE USE OF THE MADE OF UNITED STATES TESTING COMPANY, INC. MUST RECEIVE OUR PRIOR WRITTER APPROVAL. OUR REPORTS APPLY ONLY TO THE STAMBARDS OR PROCEDURES INCRITIFIED, TO THE TESTS COMBUTED, AND THE STEED AND/OR INSPECTIONS MODE. UNLESS OTNERWISE SPECIFIED: THE TEST AND/OR INSPECTION RESULTS ARE NOT INDICATIVE OR REPRESENTATIVE OF THE QUALITIES OF THE LOT FROM WHICH THE SAMPLE WAS TAKEN OR OF APPARENTLY IDENTICAL OR SHAILAR PROD-UCTS AND NOTHING CONTAINED IN OUR REPORTS SHALL AS DEEDED TO IMPLY OR MEAN THAT UNITED STATES TESTING COMPANY, INC. CONDUCTS ANY QUALITY CONTROL PROGRAM FOR THE CLIENT TO WHOM THE REPORT IS ISSUED. SAMPLES NOT DESTROYED IN TESTING ARE RETAINED A MAXIMUM OF THIRTY DAYS. U.S. EPA Contract Laboratory Program Sample Management Office P.O. Box 818 - Alexandria, VA 22313 703/557-2490 FTS: 8-557-2490

Date 12/9/87

# COVER PAGE INORGANIC ANALYSES DATA PACKAGE

Lab Name US Testing	Case No. 7576/
SOW No. 784	Q.C. Report No. 76/
Sample Num	nbers
EPA No. Lab ID No.  #1 75761-1  #2 -2    #3 -3    *** Adver Sample -5    Trip blank -6    Trip blank -7	EPA No. Lab ID No.
Comments:	
ICP Interelement and background corrections	applied? Yes No
If yes, corrections applied before or	
Footnotes:	
NR - not required by contract at this time Form I:  Value - If the result is a value greater the detection limit but less than the contract the value in brackets (i.e., method used with P (for ICP/Flame A)  U - Indicates element was analyzed for detection limit value (e.g., 10U).	an or equal to the instrument ontract required detection limit, [10]). Indicate the analytical A) or F (for furnace).

U.S. EPA Contract Laboratory Program Sample Management Office P.O. Box 818 - Alexandria, VA 22313 703/557-2490 FTS: 8-557-2490	
INORGANIC	ANALYSIS DATA SHEET
LAB BAME US Testing	CASE NO. 7576/
sow No. 784	
LAB SAMPLE ID. NO. 75761-1	QC REPORT NO76/
Elements Id	entified and Measured
Concentration: Low X	
Matrix: Water Soil-	<del></del>
1. Aluminum 7260.	kg)dry weight (Circle One)  P 13. Magnesium
2. Antimony	14. Manganese
3. Arsenic 2.18	F 15. Mercury
4. Barium	16. Nickel
5. Beryllium	17. Potassium
6. Cadmium	18. Selenium
7. Calcium	19. Silver
8. Chromium	20. Sodium
9. Cobalt	21. Thallium
10. Copper	22. <u>Tin</u>
11. <u>Iron</u>	23. Vanadium
12. <u>Lead</u>	24. Zinc
Cyanide	Percent Solids (%)
as defined on Cover Page	o EPA, standard result qualifiers are used. Additional flags or footnotes explaining Definition of such flags must be expliciting, however.
	•
-	
	Lab Manager
•	/

U.S. EPA Contract Laboratory Program Sample Management Office P.O. Box 818 - Alexandria, VA 22313 703/557-2490 FTS: 8-557-2490	EPA Sample No.   #2
INORGANIC A	NALYSIS DATA SHEET
LAB EAME US Tosting	CASE NO. 7576/
SOW NO. 784	
LAB SAMPLE ID. NO. 75761-2	QC REPORT NO. 76/
J <u>75 / 47 /</u>	do um out not
Florence Ide	and filed and Management
· · · · · · · · · · · · · · · · · · ·	entified and Measured
Concentration: Low	
Matrix: Water Soil X	SludgeOther
	dry weight (Circle One)
1. Aluminum 7910 f	2 13. Magnesium
2. Antimony	14. Manganese
3. Arsenic 1.48 F	15. Mercury
4. Barium	16. Nickel
5. Beryllium	17. Potassium
6. Cadmium	18. Selenium
7. Calcium	19. Silver
8. Chromium	20. Sodium
9. Cobalt	21. Thallium
10. Copper	22. Tin
11. Iron	23. Vanadium
12. Lead	24. Zinc
Cyanide	
Cyanida	Percent Solids (%)
	EPA, standard result qualifiers are use
	. Additional flags or footnotes explainin Definition of such flags must be explici
and contained on Cover Pa	
0	
Comments:	
•	Lab Manager
	<u> </u>

U.S. EPA Contract Laboratory Program Sample Management Office P.O. Box 818 - Alexandria, VA 22313 703/557-2490 FTS: 8-557-2490	EPA Sample No. 1.  #3  Date /2/9/87
INODCANIC A	NALYSIS DATA SHEET
LAB HAME US TESTING	
	case no. <u>7576/</u>
	<b>—</b> //
LAB SAMPLE ID. NO. 75761-3	QC REPORT NO
	ntified and Measured
Concentration: Low	Medium
Matrix: Water Soil	SludgeOther
ug/L or mg/k  1. Aluminum 8590  2. Antimony  3. Arsenic .0 F</th <th>dry weight (Circle One)  13. Magnesium  14. Manganese  15. Mercury</th>	dry weight (Circle One)  13. Magnesium  14. Manganese  15. Mercury
4. Barium	16. Nickel
5. Beryllium	17. Potassium
6. Cadmium	18. Selenium
7. Calcium	19. Silver
8. Chromium	20. Sodium
9. Cobalt	21. Thallium
10. Copper	22. Tin
ll. Iron	23. Vanadium
12. Lead	24. Zinc
Cyanide	Percent Solids (%)
Footnotes: For reporting results to as defined on Cover Page. results are encouraged. and contained on Cover Pa	EPA, standard result qualifiers are used Additional flags or footnotes explaining Definition of such flags must be explicit
	Lab Manager
	<del></del>

U.S. EPA Contract Laboratory Program Sample Management Office P.O. Box 818 - Alexandria, VA 22313 703/557-2490 FTS: 8-557-2490	EPA Sample No. 7.  #4  Date /2/9/87
INORGANIC AN	ALYSIS DATA SHEET
LAB FAME US Testing	CASE NO. 7576/
SOW NO. 784	CASE NO/3 / W/
LAB SAMPLE ID. NO. 75761-4	-d vo
LAB SAMPLE 10. NO. 15 /61-4	QC REPORT NO. 761
<del></del>	tified and Measured
Concentration: Low	Medium
Matrix: Water Soil X	Sludge Other
_	
ug/L or mg/kg	dry weight (Circle One)
1. Aluminum //400. P	13. Magnesium
2. Antimony	14. Manganese
3. Arsenic /127 F	15. Mercury
4. Barium	16. Nickel
5. Beryllium	17. Potassium
6. Cadmium	18. Selenium
7. Calcium	19. Silver
8. Chromium	20. Sodium
9. Cobalt	21. Thallium
10. Copper	22. Tin
11. Iron	23. Vanadium
12. Lead	24. Zinc
Cyanide	Percent Solids (Z)
Footnotes: For reporting results to as defined on Cover Page.	EPA, standard result qualifiers are use Additional flags or footnotes explaining efinition of such flags must be explicit
	Lab Manager
	/

U.S. EPA Contract Laboratory Program Sample Management Office P.O. Box 818 - Alexandria, VA 22313 703/557-2490 FTS: 8-557-2490	Nater Sample  Date 12/9/87
INORGANIC ANA LAB HAME US Testing SOW NO. 784 LAB SAMPLE ID. NO. 75761-5	CASE NO. 7576/ QC REPORT NO. 76/
Concentration:  Matrix: Water Soil	MediumOther
1. Aluminum 5/000 P	dry weight (Circle One)  13. Magnesium  14. Manganese  15. Mercury  16. Nickel  17. Potassium  18. Selenium  19. Silver
8. Chromium  9. Cobalt  10. Copper  11. Iron	20. Sodium 21. Thallium 22. Tin 23. Vanadium
12. Lead Cyanide	24. Zinc Percent Solids (%)
as defined on Cover Page.	PA, standard result qualifiers are used Additional flags or footnotes explaining efinition of such flags must be explicite, however.
	Lab Manager

U.S. EPA Contract Laboratory Program Sample Management Office P.O. Box 818 - Alexandria, VA 22313	TreloBland
703/557-2490 FTS: 8-557-2490	Date /2/9/87
INORGANIC AN	ALYSIS DATA SHEET
LAB EAME US TESTING	case no. 7576/
SOW NO. 784	
LAB SAMPLE ID. NO. 75761-6	QC REPORT NO
Elements Iden	tified and Measured
Concentration: Low X	Medium
	Sludge Other
(ug/L) or mg/kg	dry weight (Circle One)
1. Aluminum /90 P	13. Magnesium
2. Antimony	14. Manganese
3. Arsenic 0. F</th <th>15. Mercury</th>	15. Mercury
4. Barium	16. Nickel
5. Beryllium	17. Potassium
6. Cadmium	18. Selenium
7. Calcium .	19. Silver
8. Chromium	20. Sodium
9. Cobalt	21. Thallium
10. Copper	22. Tin
11. Iron	23. Vanadium
12. Lead	24. Zinc
Cyanide	Percent Solids (%)
as defined on Cover Page. results are encouraged. D and contained on Cover Pag	EPA, standard result qualifiers are use Additional flags or footnotes explaining efinition of such flags must be explicie, however.
Comments:	
•	Lab Manager

U.S. EPA Contract Laboratory Program Sample Management Office P.O. Box 818 - Alexandria, VA 22313 703/557-2490 FTS: 8-557-2490	Trip Blank  Date 12/9/87
SOW NO. 784	CASE NO. 7576/
LAB SAMPLE ID. NO. 75761-7	QC REPORT NO
Elements Identi	fied and Measured
Concentration: Low	Medium
Matrix: Water X Soil	SludgeOther
Ag/L)or mg/kg o	iry weight (Circle One)
1. Aluminum /20 P	13. Magnesium
	14. Manganese
. —————————————	15. Mercury
4. Barium	16. Nickel
5. Beryllium	17. Potassium
6. Cadmium	18. Selenium
7. Calcium .	19. Silver
8. Chromium	20. Sodium
9. Cobalt	21. Thallium
10. Copper	22. Tin
11. Iron	23. Vanadium
12. Lead	24. Zinc
Cyanide	Percent Solids (%)
as defined on Cover Page.	
<del></del>	
•	Lab Manager

				-//
Q.	c.	Report	No.	761

#### INITIAL AND CONTINUING CALIBRATION VERIFICATION3

LAB	NAME	15 Te	sting	<b>/</b>	CASE	NO.		576/		
			0		SOW 1	10.		84		
DATE 12/9/87					· UNITS	s	ug	ll		
Compound . Initial Calib. 1				.1	Cont	inuing	Calibr	ation <sup>2</sup>		
Met	als:	True Value	Found	ZR	True Value	Found	ZR	Found	ZR	Method 4
1.	Aluminum	5000	5497	109.9	10000	10430	104.3			ρ
2.	Antimony	900			2500					p
3.	Arsenic	40.9	42.1	102.9	50 -	46	92.0			F
4.	Barium	1200			2500					ρ
5.	Beryllium	1000			500	<u> </u>	<u> </u>			P
6.	Cadmium	250	<u> </u>		2500	·			(ji	ρ
7.	Calcium	75000			25006					IP
8.	Chromium	1000		·	2506					ρ
9.	Cobalt	1000			2500					ρ
10.	Copper	1000			2500	•				ρ
11.	Iron	1000			2500					ρ
12.	Lead	91.7			50					F
13.	Magnesium	5000		·	25000					ρ
14.	Manganese	1000			2500					P
15.	Mercury				Ý					COLD
16.	Nickel	1000			2500 F					ρ
17.	Potassium	15000			25000					p
18.	Selenium	864			50			,		F
19.	Silver	300			500					ρ
20.	Sodium	15000			25000					ρ
21.	Thallium	95.2			50					F
22.	Tin	100			100					F
23.	Vanadium	2500			2500					P
24.	Zinc	1000			2500					ρ
Othe:	:							·		
								:		
Cyan:	ide									METHOD
1 I	nitial Cal	ibration So	urce E	PA	<sup>2</sup> Contin	uing Cal	ibrat	ion Sour	ce A	+ STDS

<sup>3</sup> Control Limits: Mercury and Tin 80-120; All Other Compounds 90-110

<sup>4</sup> Indicate Analytical Method Used: P - ICP/Flame AA; F - Furnace

Form III

Q. C. Report No. 761

BLANKS

LAB NAME	USTESting	CASE NO
DATE	12/9/87	units uq/L
		Matrix Worler+Soil

Initial   Continuing Calibration								
Preparation	Calibration	Blank Value				Preparation Blank		
Compound	Blank Value	1	2	3	4	11	2	
Metals:				,			ا: ا	
l. Aluminum	38U	38U				381)		
2. Antimony	,							
3. Arsenic	8.20	P.20				8.20		
4. Barium								
5. Beryllium								
6. Cadmium								
7. Calcium				L				
8. Chromium				<u></u>				
9. Cobalt				<u> </u>			·	
10. Copper	·							
ll. Iron		<b></b>						
12. Lead	,			ļ				
13. Magnesium								
14. Manganese			<u> </u>					
15. Mercury								
16. Nickel				ļ	-			
17. Potassium		<u>                                     </u>						
18. Selenium								
19. Silver			<u> </u>			<u> </u>		
20. Sodium						<u> </u>	· ·	
21. Thallium						<u> </u>		
22. Tin								
23. Vanadium								
24. Zinc								
Other:							`	
Cyanide								

Q. C. Report No. 761

ICP INTERFERENCE CHECK SAMPLE

, , , , , , , , , , , , , , , , , , , ,	INTERFERENCE CHECK SALLES
LAS NAME US TESTING	CASE NO. 7576/
DATE 12/9/87	Check Sample I.D. ICAP Intercheck Check Sample Source ENA
	Units ug/L

<u> </u>							~~~~	
Control Limits   Initial					Final			
Com	dound	Mean	Std. Dev.	True <sup>2</sup>	Observed	ZR	Observed	ZR
Met	als:				1			1 1
1.	Aluminum			503000	497000	198.81	492000	97.8
2.	Antimony			[[	<u> </u>		<u> </u>	1
3.	Arsenic					1	<u> </u>	1
4.	Barium	·		472				
5.	Beryllium	·		456	<u> -</u>	1		
6.	Çadmium			964				<u> </u>
7.	Calcium	· _ · ·		499000		11	<u> </u>	1
8.	Chromium	·		985				
9.	Cobalt		•	478			<u> </u>	
10.	Copper ·		·	509				
11.	Iron			198000				
12.	Lead		<u> </u>					
13.	Magnesium	<u> </u>		497000				
14.	Manganese	<del> </del>		522				
15.	Mercury	·		*				
- 16.	Nickel			913				
17.	Potassium			11	· .			
18.	Selenium						j. *.	
19.	Silver			1986				
20.	Sodium							
21.	Thallium							
22.	Tin		•					
23	. Vanadium			11471				
24	Zinc			1948				
Oti	ner:							

l Mean value based on n .

True value of EPA ICP Interference Check Sample or contractor standard.

#### Form V

Q. C. Report No. 76

#### SPIKE SAMPLE RECOVERY

LAB NAME US Testina		CASE NO.	75
10/0		EPA Sample No	0
DATE/2/9/87		Lab Sample I	D
	i.	Ilmira	a

CASE NO. /3 /0/
EPA Sample No. water sample
Lab Sample ID No. 5761-5
Units ug/l

i Compound	Control Limit ZR	Spiked Sample Result (SSK)	Sample Result (SR)	Spiked Added (SA)	1 70!
Metals:		KESUIL (35K)	Legale (34)	10000 (317)	1
l. Aluminum	75-125	52610	5/000	2000	1805
2. Antimony				500	1
3. Argenic			•	20	1
4. Barium	•			2000	1
5. Beryllium	n .			50	
6. Cadmium	*			50	1
7. Calcium				100000	İ
8. Chromium	•			200	
9. Cobalt	**			500	1
10. Copper	•			250	• [
ll. Iron	•	,		1000	1
12. Lead	•		·	20	1
13. Magnesiu				50000	1
14. Manganes	e -			200	1
15. Mercury	•			1.0	
16. Nickel	•			400	
17. Potassiu	-			50000	<u>· İ</u>
18. Selenium	•			10	1
19. Silver	•			50	
20. Sodium	•	•		100000	
21. Thallium	•			50	
22. <u>Tin</u>	•			200	
23. Vanadium	•			500	
24. Zinc	•			200	
Other:				•	
Cyanide	•				

 $<sup>1</sup> ZR = [(SSR - SR)/SA] \times 100$ 

"R"- out of control

_	·	. •	
Comments:	•		
	The state of the s		

Q. C. Report No. 76/

	( )		SPIKE SMIPLE			
LAB	NAME 1	5 Tosting 12/9/87	·	CASE NO	15761	
DAT	Fi	12/0/87	•	EPA Sad	ple No. #	1
	<del>*</del>	19/10/	<del>-</del> .		ug/l	<u>- ۱۵۱ -</u> بد
			Matrix Soi	<u>/</u>	7 31	
	i	Control Limit	Spiked Sample		Spiked	
_	pound	ZR	Result (SSR)	Result (SR)	Added (SA)	ZR!
Het	als:				l	1
1.	Aluminum	75-125				<u> </u>
2.	Antimony	•			500	
3.	Arsenic	•	57.2	21.8	1 40	188.5
4.	Barium		<u> </u>	<u></u>	2000	1
5.	Beryllium	<u> </u>	<u> </u>	<u> </u>	50	1
6.	Cadmium	-	<u> </u>	<u> </u>	50	1
7.	Calcium				<u> </u>	
8.	Chronium	•		<u> </u>	200	
9.	Cobalt	<u> </u>			500	1
10.	Copper	-			250	• [
11.	Iron	-				<u> </u>
12.	Lead	• .			40	1
13.	Magnesium	•				1
14.	Menganese	•			500	1
15.	Mercury	•			1.0	
16.	Nickel	•			500	1
17.	Potassium	•				, i
18.	Selenium	•	·		10	
19.	Silver	• .			50	
20.	Sodium	•	•			
21.	Thallium	•			50	
22.	Tin	•			200	
	Vanadium	•	·		500	
24.	Zinc	•			500	
	0 C :-				•	
	<del></del>					1
Сув	nide	•				1
-		- SR)/SA] x 100				
	- out of c			, , , , ,		
	ments:		* Bose	edon diluted	, solution	

and the second s

Q. C. Report No. 76/

DUPLICATES

LAB NAME	US Testing	
DATE	12/9/87	

CASE NO. 7576/ EPA Sample No. Lab Sample ID No. 7576/-5

Hucrix Water

Compound	Control Limit	Sample(S)	Duplicate(D)	RPD <sup>2</sup>
	0000102 23220	July 100	30,220310(3)	<del>                                     </del>
Metals: 1. Aluminum		51000	48600	4.8
2. Antimony				
3. Arsenic	• •			
4. Barium	<u> </u>			<u> </u>
5. Beryllium				
6. Cadmium				ļ
7. Calcium				<u> </u>
8. Chromium		·	· · · · · · · · · · · · · · · · · · ·	<u> </u>
9. Cobalt	<u> </u>			<u> </u>
10. Copper				
11. Iron				<u> </u>
12. Lead		<u> </u>		
13. Magnesium		·		
14. Manganese		<u> </u>		<u> </u>
15. Mercury	·			
16. Nickel		2, 2,		
17. Potassium				
18. Selenium			<u> </u>	<u>بور</u>
19. <u>Silver</u>				<u></u>
20. Sodium				
21. Thallium			<u> </u>	<u> </u>
22. <u>Tin</u>		<u> </u>		
23. Vanadium		<u> </u>		
24. Zinc				
Other:				
				4
Cyanide				

<sup>\*</sup> Out of Control

<sup>1</sup> To be added at a later date.

 $<sup>^{2}</sup>$ .RPD = [|S - D|/((S + D)/2)] x 100

NC - Non calculable RPD due to value(s) less than CRDL

Q. C. Report No. 76/

DUPLICATES

LAB NAME US Testing		CASE NO. 7576/
DATE 12/9/87		EPA Sample No. # / Lab Sample ID No. 7576/-
M. o	50:1	Units mg/kg

Compound	Control Limit 1	Sample(S)	Duplicate(D)	RPD <sup>2</sup>
l. Aluminum		72600	75900	4.4
2. Antimony				
3. Arsenic		21.8	18.7	15.3
4. Barium				
5. Beryllium				
6. Cadmium				
7. Calcium		•		
8. Chromium		·		, ,
9. Cobalt				
10. Copper				
11. Iron		<u>.</u>	· ·	·
12. Lead				<u> </u>
13. Magnesium				
14. Manganese				
15. Mercury				
16. Nickel	<u> </u>			
17. Potassium		<u> </u>		
18. Selenium				
19. Silver				
20. Sodium		<u> </u>		
21. Thallium				
22. <u>Tin</u>				
23. Vanadium				
24. Zinc				
Other:				
			·	
Cyanide				

<sup>\*</sup> Out of Control

<sup>1</sup> To be added at a later date.

 $<sup>^{2}</sup>$  RPD = [|S - D|/((S + D)/2)] x 100

NC - Non calculable RPD due to value(s) less than CRDL

#### Form VII

Q.C. Report No. 761

# INSTRUMENT DETECTION LIMITS AND

#### LABORATORY CUNTROL SAMPLE

LAB NAME	US Testina		CASE NO.	7576	
DATE	12/9/87		LCS UNITS	Ug/L)	mg/kg
, 4		•	•	(Circle	e One)

	Required Detection	Instrumen	t Detection				
Compound	Limits (CRDL)-ug/l	l Limits (IDL)-ug/l Lab C		Lab Con	ontrol Sample		
		ICP/AA	Furnace	True	Found	%R	
Mecals:							
l. Aluminum	200	38	!	11000	1097	109.7	
2. Antimony	60	121		1000	<u> </u>		
3. Arsenic	10	1	1 8.2	. 1	135	87.5	
4. Barium	200	3.9	<u> </u>	1000		<u> </u>	
5. Beryllium	5	1./	<u> </u>	1/000	1	<u> </u>	
6. Cadmium	5	2.3		1000	<u> </u>	<u>i</u>	
7. Calcium	5000	54	<u> </u>	20000	1	<u> </u>	
8. Chromium	10	<u>3.6</u>	<u> </u>	1000		<u> </u>	
9. Cobalt	50	3.0		1000	<u> </u>	<u> </u>	
10. Copper	25	8.5		1000	<u> </u>		
11. Iron	100	5.1		1000	<u>i</u>	<u> </u>	
12. Lead	5		5.0	1 25	<u> </u>	1.	
13. Magnesium	5000	38		20000			
14. Manganese	15	2.1		1/000		1	
15. Mercury	0.2	0.1	1				
16. Nickel	40	9.7		1000			
17. Potassium	5000	107		120000			
18. Selenium	5		5.0	25			
19. Silver	10	4.0		1000			
20. Sodium	5000	24		2000			
21. Thallium	10		7.2	50			
22. Tin	40		33		1	1	
23. Vanadium	50	3.9	,	1000	1	1	
24. Zinc	20	1 2.6	<u> </u>	11/000		1	
Other:		11		11	1	j	
			<del>                                     </del>	11	1		
Cyanide	10			<u>'                                    </u>	<u> </u>	1	

REFERENCE NO. 27

CEDAR GROVE

VI. FACILITY LOCATION

A STREET ROUTE NO. OR OTHER SPECIFIC IDENTIFIER

501 LITTLE ROAD

B: COUNTY NAME

ESSEX

CEDAR GROVE NJ07009

CONTINUED FROM THE FRONT	
VII. SIC CODES (4-digit, in order of priority)	
A. FIRST	B. SECOND
7 3 8 1 1 (specify) ENG INSTRUMENTS & EQUIPMENT	(specify) 7 3, 7, 6, 9 MISSILE & SPACE PARTS
19 10 - 10	15 116 19
C. THIRD	D, FOURTH
7 3 8 2 3 INDUSTRIAL INSTRUMENTS & PARTS	(specify) 7 3, 6, 7, 9 ELECTRONIC COMPONENTS NOT CLASSIFIED
VIII. OPERATOR INFORMATION	15 16 - 19
VIII. OPERATOR INFORMATION	AME B. is the name listed in
	item:VIII-A elso the
8 SERVOMETER CORPORATI	O N X YES INO
15 16	66
C. STATUS OF OPERATOR (Enter the appropriate letter into  F = FEDERAL M = PUBLIC (other than federal or state)	
S = STATE O = OTHER (specify)	P (specify) CORPORATION A 2 0 1 7 8 5 4 6 3 0
P = PRIVATE  E. STREET OR P.O. BOX	56 CORFORATION 15 16 - 68 10 - 21 22 - 26
	<del></del>
501 LITTLE FALLS ROAD	)
F. CITY OR TOWN	G.STATE H. ZIP CODE IX, INDIAN LAND
	Is the facility located on Indian lands?
B C E D A R G R O V E	N J 0 7 0 0 9 ☐ YES ☑ NO
18 16	40 41 42 47 - 31
X. EXISTING ENVIRONMENTAL PERMITS  A. NPDES (Discharges to Surface Water)  D. PSD (Air	r Emissions from Proposed Sources)
CITIE CITE	Thisson's your Proposed Sources/
9 N N J 0 0 2 7 8 4 7 9 P	
B. UIC (Underground Injection of Fluids)	E. OTHER (specify)
9 U	(specify)
18 16 17 18 - 30 15 16 17 18	36
C. RCRA (Hazardous Wastes)	E. OTHER (specify)                    (specify)
9 R 9 10 17 19 30 15 16 17 19	
18 1 18 17 18 - 20 18 16 17 18 XI. MAP	. 30
Attach to this application a topographic map of the area ex	stending to at least one mile beyond property boundaries. The map must show
the outline of the facility, the location of each of its exist	ting and proposed intake and discharge structures, each of its hazardous waste
treatment, storage, or disposal facilities, and each well whe water bodies in the map area. See instructions for precise rec	ere it injects fluids underground. Include all springs, rivers and other surface
XII. NATURE OF BUSINESS (provide a brief description)	quirements. F9: A/50
SERVOMETER MANUFACTURES MINIATURE ME	
IN ADDITION THE RELATED PRODUCTS; SU	
BELLOWS CONTACTS AND BELLOWS ASSEMBL INDUSTRY WE PROVIDE INTRICATE ELECTR	
INDUSTRI WE IROVIDE INTRICATE ELECTR	OFORTS.
	F9: 51
	14.31
XIII. CERTIFICATION (see instructions)	
I certify under penalty of law that I have personally exam	ined and am familiar with the information submitted in this application and all
attachments and that, based on my inquiry of those per	rsons immediately responsible for obtaining the information contained in the te and complete. I am aware that there are significant penalties for submitting
false information, including the possibility of fine and impr	
Mind and the control of the contro	等于10000mm。 10000mm, 100000mm, 100000mm, 100000mm, 100000mm, 100000mm, 100000mm, 100000mm, 1000000mm, 100000mm, 100000mm, 100000mm, 100000mm, 100000mm, 1
MORRIS HOLOWACHUK, PRESIDENT	Morris Stolewachek 10/31/80
TRIBIDINI	1/10000 / procention
COMMENTS FOR OFFICIAL USE ONLY	

	Please print or type in the unshaded a (fill—in-areas are spaced for elite type		Form Approved OMB No. 158-S80004
	SEPA SEPA	U.S. ENVIRONMENTAL PROTECTION AGENCY HAZARDOUS WASTE PERMIT APPLICATION  Consolidated Permits Program  (This information is required under Section 3005 of RCRA.)	I. EPA I.D. NUMBER  F N J D 0 0 2 1 3 8 5 4 3 3 1
	FOR OFFICIAL USE ONLY		
1	APPROVED (yr., mo., & day)	COMMENTS	
ľ	<u>SOIII9</u>		
_	II. FIRST OR REVISED APPLI	CATION	
		n A or B below <i>(mark one box only)</i> to indicate whether this is the first st application and you already know your facility's EPA I.D. Number, o	
		an "X" below and provide the appropriate date)	Constitution of the contract o
	11. EXISTING FACILITY (S	ee instructions for definition of "existing" facility. Complete item below.)	2.NEW FACILITY (Complete item below.) FOR NEW FACILITIES.
	OPER	EXISTING FACILITIES, PROVIDE THE DATE (yr., $mo.$ , & day) LATION BEGAN OR THE DATE CONSTRUCTION COMMENCED the boxes to the left)	VR. MO. DAY (yr., mo., & day) OPERA- TION BEGAN OR IS EXPECTED TO BEGIN
	B. REVISED APPLICATION (P.	lace an "X" below and complete Item I above)	
	1. FACILITY HAS INTERI	M STATUS	2. FACILITY HAS A RCRA PERMIT
	III. PROCESSES – CODES ANI	D DESIGN CAPACITIES	
	entering codes. If more lines are	le from the list of process codes below that best describes each process the federal process the federal process will be used design capacity) in the space provided on the form (Item III-C).	
	<ol> <li>AMOUNT — Enter the amount</li> <li>UNIT OF MEASURE — For e</li> </ol>	- For each code entered in column A enter the capacity of the process. t. ach amount entered in column B(1), enter the code from the list of unit of measure that are listed below should be used.	t measure codes below that describes the unit of

		PRO-	APPROPRIATE UNITS OF		PRO-	APPROPRIATE UNITS OF
		CESS	MEASURE FOR PROCESS		CESS	MEASURE FOR PROCESS
1	PROCESS	CODE	DESIGN CAPACITY	PROCESS	CODE	DESIGN CAPACITY
1	Storage:			Treatment:		
	CONTAINER (barrel, drum, etc.)	S01 S02	GALLONS OR LITERS GALLONS OR LITERS	TANK	TOI	GALLONS PER DAY OR LITERS PER DAY
1	WASTE PILE	503	CUBIC YARDS OR CUBIC METERS	SURFACE IMPOUNDMENT	T02	GALLONS PER DAY OR LITERS PER DAY
	SURFACE IMPOUNDMENT	S04	GALLONS OR LITERS	INCINERATOR	Т03	TONS PER HOUR OR METRIC TONS PER HOUR:
	Disposal:					GALLONS PER HOUR OR LITERS PER HOUR
į	INJECTION WELL LANDFILL	D79 D80	GALLONS OR LITERS ACRE-FEET (the volume that	OTHER (Use for physical, chemical,	T04	GALLONS PER DAY OR
		500	would cover one acre to a depth of one foot) OR HECTARE-METER	thermal or biological treatment processes not occurring in tanks, surface impoundments or inciner-	104	LITERS PER DAY
i	LAND APPLICATION	D81	ACRES OR HECTARES	ators. Describe the processes in		
į	OCEAN DISPOSAL	D82	GALLONS PER DAY OR LITERS PER DAY	the space provided; Item III-C.)		

SURFACE IMPOUNDMENT	LITERS	PER DAY IS OR LITERS			
UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASUR CODE
GALLONS	Y C	LITERS PER DAY TONS PER HOUR METRIC TONS PER HOUR GALLONS PER HOUR		ACRE-FEET HECTARE-METER ACRES HECTARES	F
CVANDLE FOR COURT ETIMO				and the second control of the second control	Δ II I

**EXAMPLE FOR COMPLETING ITEM III** (shown in line numbers X-1 and X-2 below): A facility has two storage tanks, one tank can hold 200 gallons and the other can hold 400 gallons. The facility also has an incinerator that can burn up to 20 gallons per hour.

Š C	z			D U P 13 (4 15	$\sqrt{}$	1.1	/		1		/	/	7				$\sum$		$\sqrt{}$	$\sum$	7	7	7
a		PE	20-	B. PROCESS DESIGN CAPA	CITY					1 ~	A	PR		B. PR	OCESS	DESIG	NCA	PACI	TY				
LINE	C	OE om bov	IS DE list le)	1. AMOUNT (specify)	S	UNIT MEA- URE enter ode)		FO FIG US	CIAL Se	LINE	(fre	OD om l bove	E ist		1. AM	TNUC			OF S	UNI ME URE enter	A-	OF E	NI
X-	1.5 S	_	2	600	<i>3</i> 1	G			32	5	16		18	19		<u></u>		27	1	28	t	29	Ť
X-:	T	0	3	<i>20</i>		E				6													
1	s	0	2	8,000 ისს		G				7						`							
2										8													
3										9													
4										10	<u>_</u>												
,	16	-	1.8	10	27	3.0	20		- 32		1 16		1.0	1 19		•		27	. )	28	. ;	29	

Ш.	PROC	ESSES	(continued)
111.	11100		Cimiliated

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESSES (code "T04"). FOR EACH PROCESS ENTERED/HERL INCLUDE DESIGN CAPACITY.

#### IV. DESCRIPTION OF HAZARDOUS WASTES

- A. EPA HAZARDOUS WASTE NUMBER Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If you handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number(s) from 40 CFR, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.
- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste/s/ that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE CODE
POUNDS,	P	KILOGRAMS
TONS	т	METRIC TONS

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

#### D. PROCESSES

1. PROCESS CODES:

For listed hazardous waste: For each listed hazardous waste entered in column A select the code/s/ from the list of process codes contained in Item III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER — Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:


- 1. Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B,C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- 2. In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
- 3. Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.


**EXAMPLE FOR COMPLETING ITEM IV** (shown in line numbers X-1, X-2, X-3, and X-4 below) — A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non—listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.


	<u> </u>			_								_				 				
				PA				UNIT												D. PROCESSES
NON NO.	V	۷Α	ST	AR EN	10	B. ESTIMATED ANNUAL QUANTITY OF WASTE	S	MEA URE enter ode)				1	I. P		CES (en	COE	ES			2. PROCESS DESCRIPTION (if a code is not entered in $D(1)$ )
X-1		K	0	5	4	. 900		P	7		0	3	D	8	0	1 1		1	1	·
X-2	2 /	D	0	0	2	400		P	7	т Г	0	3	D	8	0	1 1			Т	
X-3	3	D	0	0	1	100		P	7	$\Gamma$	0	3	D	8	0	7		1	T	
χ4	1	D	0	0	2						ı			Γ		1				included with above

wi/	1		C.	۵	2 1 3 8 5 9 3 1		$^{'}/$		W						DU					32 DUP	
1V. I	ES	CF	RIP.	TIC	N OF HAZARDOUS WASTE			tin	ue	_	$\geq$							:		13 14 18 23 - 26	
LINE NO.		A.I AZ.	ΛD	n I	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. OF	UNI ME URE	T.	_			1. 6	PRO	OCE	ss c	ODE			-	). PROCESSES 2. PROCES	S DESCRIPTION ot entered in D(1))
Jž	(e)	nter	CO	de)		C	ode)	1	27	-					SS C				20	(if a code is n	ot entered in D(1))
1	F	0	0	1 1	2000		T	- 1	S		2	1	•		'	,		7 1			
2	F	0	0	6	71000		Т		s	0	2	D	8	<sup>'</sup> 3	<u> </u>	. 1					
3	F	0	0	9	3000		Т		s	0	2	D	8	3				, ,			
4	D	0	0	2	104 000		Т		s	0	2	D		3	'			T - 1			
5											ı		'	1							
6										i 			ī	T	'	- 1					
7											Ţ-		T	I				T			
8														1							
9											1		T	,							
10											,		1			·· 1		7			
11											I		1	1				1			
12											T		7	1		7		1			
13										-	1		1	T		<del>- 1</del>		7		,	
14											T		1	1			Ì	т			
15											Τ		1	T	1			T			
16										r —	Т		Т	1	+			7	<b>,</b>		
17											Т		Τ'	T		<del>,-</del>		<del></del>	r		
18						T				r	T		1	7-		Т.		1	1		
19	-						$  \cdot  $			r	T	<del>                                     </del>	Т	1	'	1	+	1	1		
20							$  \cdot  $			Τ	T -		T-	1	+	1	-	1	Т		
21						$\dagger$	$  \cdot  $			τ	T		1	1	+		$\dagger$	T	T		
22						<del> </del>	$  \cdot  $			1	1		1	T			+	T	т		
23	<del> </del>					+				1	1		T	Т	+¬	<del>- 1-</del>	+	7	_		
24	-	-					$\dagger$			1	1	-	Τ.	T-	+	<del>- 1</del>	+	Τ-	<del></del>		
25	$\vdash$		$\vdash$			$\dagger$	H		-	ī -	<del></del>	+	Т	Т	+-		+	Т	T		
26		$\vdash$		+		+	$ \cdot $	_	_	Т	1	+	T	7	1	ГТ	$\dagger$	Т			·
EPA	For		510	26		1_	30		27		29	1 27		29	27	• 2	9	27 -	29	1	CONTINUE ON REVERSE

Continued from the front.				•
IV. DESCRIPTION OF HAZARDOUS WASTES (				
E. USE THIS SPACE TO LIST ADDITIONAL PR	OCESS CODES FR	OM ITEM D(1) ON PAGE 3.		,
				· etima
				4
				•
	•			
	,			
				•
		•		
)				v
	A	4		•
	$\mathcal{A}$	A		
EPA I.D. NO. (enter from page 1)	$-6 \cdot \frac{H}{SS}$	F6. 36		
FNJD00213854336	2.2	56		
13 14 15				
V. FACILITY DRAWING  All existing facilities must include in the space provided	on name 5 a scale drawi	on of the facility (rea instruction	s for more detail	· · · · · · · · · · · · · · · · · · ·
VI. PHOTOGRAPHS	on page 3 a scale draw	ing of the facility (see instruction	s for more octany.	
All existing facilities must include photographs (a	nerial or ground—lev	ell that clearly delineate all e	xisting structures; ex	cisting storage,
treatment and disposal areas; and sites of future s				
VII. FACILITY GEOGRAPHIC LOCATION				
LATITUDE (degrees, minutes, & seco	nds)	LONGITUE	E (degrees, minutes, &	seconds)
40 51 500		0	74 /3 30	<u>[0]</u>
VIII. FACILITY OWNER	a .		- 74 75 76 777 -	79
X A. If the facility owner is also the facility operator	as listed in Section VI	Lon Form 1 "General Informati	on", place an "X" in t	he box to the left and
skip to Section IX below.		, , , , , , , , , , , , , , , , , , , ,	, , ,	,
B. If the facility owner is not the facility operator	as listed in Section VII	I on Form 1, complete the follow	wing items:	
				NE NO. (area code & no.)
	CILITY'S LEGAL OW	NER		ME NO: (urea code a no.)
E 15. 16			55 56 - 56	59 - 61 62 -
3. STREET OR P.O. BOX		4. CITY OR TOWN	55   56 - 56   5. ST.	6. ZIP CODE
F	G G	,		
12 16	45 15 16		49 41 42	47 - 51
IX. OWNER CERTIFICATION				
I certify under penalty of law that I have persona documents, and that based on my inquiry of the				
submitted information is true, accurate, and com	plete. I am aware th	at there are significant penals	ies for submitting f	alse information,
including the possibility of fine and imprisonmen		•	-	
A. NAME (print or type)	B. SIGNATURE	2 1	C. DATE S	IGNED
MORRIS HOLOWACHUK	Mini	Afelonachak	10/27/	80
HORRIS HOLOWACHER	Maria,	geton acrist		
X, OPERATOR CERTIFICATION				
I certify under penalty of law that I have personal	ally examined and ar	n familiar with the informati	on submitted in this	and all attached
documents, and that based on my inquiry of those submitted information is true, accurate, and com	se individuals immed oblete. I am aware th	nately responsible for obtain at there are significant penal	ing the information, ties for submitting f	alse information
including the possibility of fine and imprisonmen	nt.	A CONTROL OF THE PROPERTY OF T		
A. NAME (print or type)	B. SIGNATURE	, and the second of the second	C. DATE S	IGNED
	1		1	









#### State of New Jersey

#### DEPARTMENT OF ENVIRONMENTAL PROTECTION

## DIVISION OF WATER RESOURCES METRO BUREAU OF REGIONAL ENFORCEMENT

2 BABCOCK PLACE WEST ORANGE, NEW JERSEY 07052

GEORGE G. McCANN, P.E. DIRECTOR

November 18, 1988

DIRK C. HOFMAN, P.E. DEPUTY DIRECTOR

Mr. Peter Holowachuk, Fresident Servometer Corporation 501 Little Falls Road Cedar Grove, NJ 07009

Re: Compliance Evaluation Inspection Servometer Corporation NJPDES No. NJ0027847 Cedar Grove/Essex County

Dear Mr. Holowachuk:

A Compliance Evaluation Inspection of your facility was conducted by representatives of this Division on October 5, 1988.

Your facility received a rating of "ACCEPTABLE". A copy of the completed inspection report form is enclosed for your information. Please address any minor deficiencies noted therein.

This Division anticipates your continued cooperation in assisting us in the prevention and control of water pollution in New Jersey.

: 6<sup>th</sup>.

Very truly yours,

Stefan D. Sedlak Section Chief Metro Bureau of

Regional Enforcement

A7:G26

c: Mr. Paul Molinari, USEPA

Dr. Richard Baker, USEPA

Mr. Thomas Restaino, H.O.

bc: Zaheer Hussain Central File



#### NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION DIVISION OF WATER RESOURCES CN 029, Trenton, N.J. 08625

# 53

#### DISCHARGE SURVEILLANCE REPORT

PERMIT # NJ0027847 NO. OF DISCHARGES UOI CLASS Maj / Ind.
DISCHARGER Servometer Corporation
OWNER Servometer Corporation
MUNICIPALITY Ceder Grove COUNTY Essex WATERSHED CODE P  LOCATION 501 Li He Falls logd 07009
RECEIVING WATERS Peckman River STREAM CLASS FW-ZNT
LICENSED OPERATOR & PLANT CLASS Poter Holowachuk N-N
TRAINEE/ASSISTANT OTHER INFO. (201) 785 - 4636
DEFICIENCIES OR COMMENTS None
OVERALL RATING Acceptable Conditionally Acceptable Unacceptable
EVALUATOR Steve Ciambruschia: /Howard GoldmyTITLE Enviconmental Specialist
INFORMATION FURNISHED BY (Name) Mr. Peter Holowachuk
(Title) President (Organization) Servemeter (orporation

## SEY DEPARTMENT OF ENVIRONMENTAL PROTION DIVISION OF WATER RESOURCES CN 029, Trenton, N.J. 08625

Permit # NJ00 27847

#### DISCHARGE SURVEILLANCE REPORT

Date October 5 1988

· ·	Servometer GRO	UN	D W A	TER DISCHARGE EVALUATION
RAT		_		J = Unsatisfactory. NA = Not Applicable N1 - Not Inspected
			TING	COMMENTS
	TYPE DGW	-	-	Underground Storage Tank.
	RCRA FACILITY	Ι-	_	NJD002138543 J
	DISCHARGE NUMBER	1	/A	
≴	WASTEWATER SOURCE/FREQ.		1	
GENERAL	PUMPS AND PIPING			
E	ALTERNATE POWER/ALARM			
	BYPASS	7	/	
	·			
	WATER SUPPLY/MONITORING	N	Δ	
•	AQUIFERS MONITORED	10	<u>~</u>	
E	UPGRADIENT WELLS	3	<del></del>	Glacial + Aluvial deposite overlying Triassic Brussiak Fermotion
SYSTEM	DOWNGRADIENT WELLS	Š		MW-1 and Triassic Watching Base
	SAMPLING PLAN	-		NW-2, MW-3, MW-4
20	SAMPLING PROCEDURES			March June, Sept. Dec.
RII	LAB CERTIFICATION	<del>                                     </del>		Sampling will be carried out in
10		١-,	<u> </u>	October 1988.
Z	RECORDS	<del>                                     </del>		A - A - A - A - A - A - A - A - A - A -
MONITORING	REPORTING	⊢=		April, July, Oct., Jan.
_		$\vdash$		
<del></del>	DRILLING PERMIT NUMBERS	<	Ś	2612213-8. 2612214-6 2612215-4 2612216-2
LLS	WELLS NUMBERED/IDENTIFIED	5	>	mw! mw2 mw-3 mw-4
ER/ WEI	LOCKS/INTEGRITY	9/	15	Good Good
JE O	ABANDONMENT PLAN	N		
#E	ABANDONMENT PLAN ELEVATION INFORMATION WATER LEVEL MEASUREMENT TURBIDITY FREE	N		
Sign	WATER LEVEL MEASUREMENT	N	<i>T</i>	
걸두	TURBIDITY FREE	N		
MO	SUFFICIENT YIELD	NI		
	CLASSIFICATION	1	1	
	PERC./LEACHING PROBLEMS			
OIC	SOLVENTS/REPAIRS MADE	Λ	Α	
)	MAX, PRESSURE & VOLUME	Ì		
	CLOSEST USDW/SUPPLY WELLS			
	MOUND INTEGRITY/COVER	Ī		
Ħ	LINING INTEGRITY	V		
EN	EMBANKMENT INTEGRITY	N	A	·
W	LEACHATE COLLECTION SYS.	i		
	SOLIDS BUILDUP/REMOVAL			
ָק ו	HEIGHT TO FREEBOARD	$\Box$		
IMPOUNDMENT	APPEARANCE	$\Box$		
		$\perp$		
_	EVEN DISTRIBUTION (3)	1		
NO.	PONDING/RUNOFF/EROSION	$\underline{\hspace{1cm}}$		
ICATION/	SPRAY HEADS	N	Λ	
CA 'ST	DISCING			
PPLIC, Y SYS	COVER CROP			 
< <	APPEARANCE			
	BUFFER ZONE		,	
LAND SPR	SLUDGE STOCKPILED	!		
1				
		<u> </u>	,	
THER	SEEPAGE/LEACHING			
H	ODOR/AEROSOLS	N	Ą	,



REC. WATERS APPEARENCE

NI

Peckman

River

## N.J.D.E.P. D.W.R.



Page 2 of 3 (I Permit #: NJ0027847

DISCHARGE SURVEILLANCE REPORT Date: October 5 1988 at a contra a service and services INDUSTRIAL TREATMENT PROCESS EVALUATION RATING CODES: S = Satisfactory M = Marginal U = Unsatisfactory NA = Not Applicable RATING COMMENTS DISCHARGE # 001 WASTEWATER SOURCE(S) Process water for electroplating 24 hours/day CONTINUITY OF OPERATION 5 Days / Week BYPASSES/OVERFLOWS NA S.P.C.C. PLAN NA NA ALARM SYSTEMS ALTERNATE POWER SUPPLY NA Pretreatment of PROCESSES Electroplating waste water (Acid or coustic Addition) **TREATMENT** Clarifier Servometer Gen.# NJD002138543 Waste Sodium Hydroxide Solution Transporter # NJD054126164 Freehold Cartage DISPOSAL SITE E.l. Dupont # NJD002385730 Deepwater NJ FLOW METER & RECORDER Meterod RECORDS Permit DMR's 5 SAMPLING PROCEDURES Personnel Lancy International INC Cert. # 77269 ANALYSES PERFORMED BY Zelenople, Pa. INFORMATION Atlantic Environmental is subcontracted by Loncy to do Bioassay Electroploting Operation Metalk used in process Ni Cu Au OTHER FINAL EFFLUENT APPEARENCE Clear

Form DWR-053




#### NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION DIVISION OF WATER RESOURCES CN 029, Trenton, N.J. 08625

Page 3 of 3

Permit # NJ002784

DISCHARGE SURVEILLANCE REPORT

Date October 5,



DISCHARGE DATA No DMR Violations

SOURCE: DJN 001

MONITORING DEFICIENCIES:

PERIOD: June + July 1988

DIS	PARA	SAMPLE TYPE	PERMIT LIMITS	DATA	DIS	PARA	SAMPLE TYPE	PERMIT LIMITS	DATA
			•						
-									
								:	-
							·	·	

00-30 - 00 3003 -30

## NUS CORPORATION

TELECON NOTE

CONTROL NO:	DATE:	TIM	1F:
	6/30/88	·	905
DISTRIBUTION:		<u></u>	
Perk RICHAR	ids 73	50 02	-5803-55
	8	RICS	NJ648I
BETWEEN:	OF:		PHONE:
GLENRIDGE CC	othe	e_	(301) 748-8408
STAN SIGN	LFEOR		(NUS)
DISCUSSION:			
I stoke	with	some one	in the
office, 7			
Don, at	The The	greenske	repers phone #
201 - 748 -	0883.		
			green skeepers
phone		· · · · · · · · · · · · · · · · · · ·	
		·	
7/5/88 910	_ /		
greens keep	ser for	Glenrin	Lge Country Club.
Don ac	luised a	rave of	hat C.C.
has 3	wells.	Two o	vells, # 1 and #
are used	only to	or irri	gation purposes
on the	golf cou	erse.	Well #3 15
used to	Supply	water	to the  l is located  st of Ridgewood
Swimming	pool,	This wel	l is located
in Glenrid	ge , / 1	Block ea.	st of Ridgewood
ACTION ITEMS: Averue	cet Yant	ecaw and	Forest Avenues
L .			are located
In Bloom			
		ion we	lls were
			ng the last
water short	tage, when	being co.	usidered for as
an emergen	y water	supply.	over ->

The Swimming pool supply well is used to tested for only chlorides on a regular basis.

## NUS CORPORATION

TELECON NOTE


CONTROL NO:	5475		
CONTROL NO.	DATE:	/cc	TIME:
	1/30	/88	905
DISTRIBUTION:			
Poor Richa	~~!/ C		NJ648I
BETWEEN:	OF: /	L	PHONE:
Bob Dickers	on Upa	reenskeeper ( rMontelair C.C	(201)779-7505
STAN S	HULFER		(NUS)
DISCUSSION:			<del></del>
I ask	ed Mr	. Dickers	son about
1 ,			as in use
			as in use
at the			
Mr. Di	ckerson	achis	ed that
			Seini-public
			serving the
Club Jones	Rom	wex muse	mempership
and Sta	H +1	tal	1,000 people.
Wells #Za	nd 3	are	used in
			onsite pond
to irrig			fely 100 acres
of golf	course.	77	0
Onle	2 He	drinki	no supply
is tested	77	13 Lecte	D Gr
hucteriolog	gical g	mality a	ud nitrales.
ACTION ITEMS:			
l .			

SERVOMETER CORP. NOTO 002138543

O-HRS Score

### CONFIDENTIAL-NOT FOR PUBLIC RELEASE

Ground Water Route Work Sheet											
	Rating Factor		Assigned Value (Circle One)			HRS	Max. Score	PRO			
0	Observed Release			45	1	0	45	0			
	If observed release is given a score of 45, proceed to line 4.  If observed release is given a score of 0, proceed to line 2.										
2	Route Characterisi Depth to Aquifer Concern		0 1 2	<u> </u>	2	6	6	6			
	Net Precipitation Permeability of t	16	0 1 2 0	3	1 1	3 2	3 3	3 2			
	Unsaturated Zo Physical State	18	0 1 2	<u> </u>	1	3	3	3			
		Total	Route Chare	acteristics Score		14	15	14			
3	Containment		0 1 2	3	1	O	3				
4	Waste Characteris Toxicity/Persiste Hazardous Wast Quantity	nce	$\mathcal{L}$	9 12 15 18 3 4 5 6 7 8	1	0	1 <b>8</b> 8	0 0			
	İ	Total	Waste Chara	acteristics Score		0	26	0			
5	Targets Ground Water Use Distance to Near Well/Population Served	est }	0 1 2 0 4 6 12 16 18 24 30 32	8 10 20 35 40	3	6 30	9	9 30			
			Total Targe	ets Score		36	49	39			
	If line 11 is 45. If line 11 is 0, m	nultiply 1 x ultiply 2 x		x 5		0	57,330	0			
7	Divide line 6 b	57,330 and mu	ultiply by 10	0	Sgw-	0		0			



02-8904-65-PA REV. NO. O

## CONFIDENTIAL-NOT FOR PUBLIC RELEASE

	Surface Water Route Work Sheet											
	Rating Factor		Assigned Value (Circle One)	Multi- plier	HRS	Max. Score	PRO					
0	Observed Release	9	45	1	0	45	0					
	if observed release is given a value of 45, proceed to line 4.  If observed release is given a value of 0, proceed to line 2.											
2	Route Characteris Facility Slope ar Terrain		ning 1 2 3	1	0	3	0					
	1-yr. 24-hr. Raini Distance to Nea Water		0 1 2 3 ce 0 1 2 3	1 2	26	3 6	2 6					
	Physical State		0 1 2 3	1	3	3	3					
	· .		Total Poute Characteristics Score	•	((	15	11					
3	Containment		0123	1	0	3	1					
4	Waste Characteris Toxicity/Persiste Hazardous Wast Quantity	ence	① 3 6 9 12 15 18 ① 1 ② 3 4 5 6 7	8 1	0	18	18 2					
		<del></del>										
			Total Waste Characteristics Score	B	0	26	20					
5	Targets Surface Water U Distance to a Se Environment		0 1 2 3	3	3	9 6	0					
	Population Serve to Water Intake Downstream		0 4 6 8 10 12 16 18 20 24 30 32 35 40	1	0	40	0					
			Total Targets Score		ß	5 <b>5</b>	6					
		-	1 x 4 x 5 2 x 3 x 4 x 5		0	64,350	(320					
7	Divide line 6 b	y 64,350 a	and multiply by 100	S <sub>sw</sub> -	$\subset$	)	2.05					

### CONFIDENTIAL-NOT FOR PUBLIC RELEASE

Air Route Work Sheet									
Rating Factor			gned V rcle On			Multi- plier	HRS	Max. Score	PRO
Observed Release	9	0		45		1	0	45	0
Date and Location	1:								
Sampling Protocol	l:								
	the S <sub>a</sub> = 0.								
Waste Characteris Reactivity and	stics	0 1	2 3		<u> </u>	1		3	
Incompatibility Toxicity Hazardous Waste Quantity	9		2 3 2 3	4 5	6 7 8	3 1		9 8	
	Т	otal Waste	Charac	teristic	s Score			20	
Targets Population Within 4-Mile Radius Olstance to Sens Environment		1 21 24	12 15 27 30 2 3	18		1 2		30 6	-
Land Use		0 1	2 3			1		3	
		Total	Targets	Score	)			39	
4 Multiply 1 x	2 x 3						0	35,100	0
5 Divide line 4 b	y 35,100 ar	nd multiply	by 100			Sa=	0		0

## CONFIDENTIAL-NOT FOR PUBLIC RELEASE

HRS	s	52
Groundwater Route Score (Sgw)	0	0
Surface Water Route Score (S <sub>SW</sub> )	0	0
Air Route Score (Sa)	0	0
$S_{gw}^2 + S_{sw}^2 + S_a^2$		0
$\sqrt{s_{gw}^2 + s_{sw}^2 + s_a^2}$		0
$\sqrt{s_{gw}^2 + s_{sw}^2 + s_a^2} / 1.73 = s_M =$		$\circ$

## WORKSHEET FOR COMPUTING SM

PRO	s	s²
Groundwater Route Score (Sgw)	0	0
Surface Water Route Score (S <sub>3w</sub> )	2.05	0
Air Route Score (Sa)		0
$s_{gw}^2 + s_{sw}^2 + s_a^2$		4.20
$\sqrt{s_{gw}^2 + s_{sw}^2 + s_a^2}$		2.05
$\sqrt{s_{gw}^2 + s_{sw}^2 + s_a^2} / 1.73 - s_M -$		1:18

WORKSHEET FOR COMPUTING SM